

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT
MAR 21 2017
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action **AMENDED***

NAB1708850091

OPERATOR <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report		
Name of Company Matador Resources 228937	Contact Catherine Green	
Address 500 N Main St Ste One Roswell NM 88201	Telephone No. 575-623-6601	
Facility Name Paul 25 24S 28E RB 221H	Facility Type Production Battery	
Surface Owner Fee	Mineral Owner Fee	API No. 30-015-43018

LOCATION OF RELEASE

Unit Letter D	Section 25	Township 24S	Range 28E	Feet from the 359	North/South Line FNL	Feet from the 217	East/West Line FWL	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-------------------------	----------------------	-----------------------	----------------

Latitude **32.19484171** Longitude **-104.0487226**

NATURE OF RELEASE

Type of Release Oil	Volume of Release ~5BBLs *	Volume Recovered ~2BBLs
Source of Release Hauler left thief hatch open on oil tank	Date and Hour of Occurrence Dec 25 2016 8:00am	Date and Hour of Discovery Dec 25 2016 8:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Telephoned Artesia NMOCD hotline. Left message	
By Whom? Jason Thibodeaux	Date and Hour Dec 25 2016 8:45 sm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Oil Hauler did not properly close hatch. Lease operator discovered open hatch, closed it, called for vacuum truck to vacuum up excess fluid on production pad.

Describe Area Affected and Cleanup Action Taken.*

Oil spilled on ground. Soil will be sampled for contaminants. Contaminated soil will be removed and replaced after work plan is approved.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION	
Signature: <i>Catherine Green</i>	Approved by Environmental Specialist <i>[Signature]</i>
Printed Name: Catherine Green	Signed By: <i>[Signature]</i>
Title: Regulatory Analyst	Approval Date: 3/21/17 Expiration Date: N/A
E-mail Address: cgreen@matadorresources.com	Conditions of Approval: Original Initial C-141 has CoA's & initial Correspondence scanned
Date: March 9, 2017 Phone: 575-627-2453	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

With it.

2RP-4051