

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
OCD ArtesiaFORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*5. Lease Serial No.
NMNM118108

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
HH SO 8 P2 6H9. API Well No.
30-015-43934-00-X110. Field and Pool or Exploratory Area
WILDCAT11. County or Parish, State
EDDY COUNTY, NM**SUBMIT IN TRIPLICATE - Other instructions on page 2**

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

CHEVRON USA INCORPORATED

Contact: DORIAN K FUENTES

E-Mail: DJVO@CHEVRON.COM

3a. Address

6301 DEAUVILLE BLVD
MIDLAND, TX 79706

3b. Phone No. (include area code)

Ph: 432-687-7631

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 17 T26S R27E NWNW 280FNL 960FWL

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

| TYPE OF SUBMISSION | TYPE OF ACTION | | | |
|--|---|---|--|---|
| <input checked="" type="checkbox"/> Notice of Intent | <input type="checkbox"/> Acidize | <input type="checkbox"/> Deepen | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off |
| <input type="checkbox"/> Subsequent Report | <input type="checkbox"/> Alter Casing | <input type="checkbox"/> Hydraulic Fracturing | <input type="checkbox"/> Reclamation | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Final Abandonment Notice | <input type="checkbox"/> Casing Repair | <input type="checkbox"/> New Construction | <input type="checkbox"/> Recomplete | <input checked="" type="checkbox"/> Other |
| | <input type="checkbox"/> Change Plans | <input type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon | Change to Original A |
| | <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back | <input type="checkbox"/> Water Disposal | PD |

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Chevron respectfully requests the ability to cement offline on the subject well.
The summary provided is a brief description for drilling run casing, and cement offline attached.

should questions arise, please contact Rod @ 281-413-3794.

NM OIL CONSERVATION
ARTESIA DISTRICT
AUG 09 2017
RECEIVED

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #372991 verified by the BLM Well Information System
For CHEVRON USA INCORPORATED, sent to the Carlsbad
Committed to AFMSS for processing by DEBORAH MCKINNEY on 04/20/2017 (17DLM1433SE)

Name (Printed/Typed) DORIAN K FUENTES

Title REGULATORY SPECIALIST

Signature (Electronic Submission)

Date 04/17/2017

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By OMAR ALOMAR

Title PETROLEUM ENGINEER

Date 08/07/2017

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Carlsbad

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

Delaware Basin

Changes to APD for Federal Well



Well Names:

| <u>WELL NAME</u> | <u>WELL #</u> | <u>API NUMBER</u> |
|-------------------|---------------|---------------------|
| <u>HH SO 8 P2</u> | <u>5H</u> | <u>30-015-43935</u> |
| <u>HH SO 8 P2</u> | <u>6H</u> | <u>30-015-43934</u> |
| <u>HH SO 8 P2</u> | <u>13H</u> | <u>30-015-43933</u> |
| <u>HH SO 8 P2</u> | <u>14H</u> | <u>30-015-43931</u> |
| <u>HH SO 8 P2</u> | <u>21H</u> | <u>30-015-43927</u> |
| <u>HH SO 8 P2</u> | <u>22H</u> | <u>30-015-43928</u> |

Rig: Patterson 815

CVX CONTACT:

RODERICK MILLIGAN

DRILLING ENGINEER

CHEVRON NORTH AMERICA EXPLORATION AND PRODUCTION CO.

MIDCONTINENT SBU

1400 SMITH STREET

HOU140/43120

HOUSTON, TX 77002

DIRECT:(713) 372-2011

MOBILE: (281) 413-9794

EMAIL: RODERICKMILLIGAN@CHEVRON.COM

Summary of Changes to APD Submission

Chevron respectfully request the ability to cement offline on the HH SO 8 P2 (5H,6H,13H,14H,21H,22H). The summary provided below is a brief description of the main operational sequences for drilling run casing, and cement offline the four wells listed above.

- Move rig to first well in the Drill Order.

Drill order for HH SO 8 P2 (5H,6H,13H,14H,21H,22H).)

| HH SO 8 P2 from S to N | | | | | | |
|------------------------|------|-------|-----|-----|------|------|
| | 14HD | 13H D | 6HC | 5HC | 22HA | 21HA |
| Surface | X | X | X | X | X | X |
| Intermediate | X | X | X | X | X | X |
| Pilot Hole | X | | | | | |
| A Laterals & D Liners | X | X | | | X | X |
| C&D Laterals | X | X | X | X | | |

Sequencing by hole section.

- Surface Hole:

1. Drill 17-1/2" surface hole with fresh water to planned casing set depth with 10' rat hole.
2. Run casing as stated by approved APD, land out wellhead.
3. Move the rig to next well (~2-3 hours) and cement previous well offline.
 - All sacks and volumes will remain the same.
4. Dress out 13-5/8" 5M SH-2 wellhead and install/secure with temporary abandonment cap, and a pressure gauge will be installed.
5. Skid to next well according to above "Drill Order"

Repeat 1 through 3 until all three surface holes are drilled, cased and cemented offline.

- Intermediate Hole:

1. N/U, using an API approved Quick-Connect, and test 13-5/8" 5M Class IV BOP to 250 psi / 5,000 psi.
2. Test casing to required pressure. Drill out shoe track and 10' of new formation. Perform FIT. Drill 12-1/4" intermediate hole to planned casing set depth with ~10' of rat hole.
3. Run casing as stated by approved APD, land out hanger and cement offline.

Repeat 1 through 3 until all three intermediate holes are drilled, cased and cemented offline.

- Production Hole:

1. Test casing to required pressure. Drill out shoe track and 10' of new formation. Perform FIT. Drill 8-1/2" vertical section, curve, and lateral as stated by approved APD.
2. Run casing as stated by approved APD, land out hanger and cement offline.

- All sacks and volumes will remain the same.
3. Install back pressure valve and temporary abandonment cap.

Repeat steps in production hole until all wells are drilled, cased, and cemented offline.

Changes Summary

Summary: Variance to cement offline the Hayhurst pad not requested in original submittal. We will not abandon (move the rig off of the pad) the well without cementing and securing the well.

| As Defined in APD: | As Planned on Well: |
|---|---|
| Variance to cement offline not requested. | Chevron respectfully request the ability to cement offline on the HH SO 8 P2 (5H,6H,13H,14H,21H,22H).) The summary provided is a brief description of the main operational sequences for drilling, casing and cementing the wells listed above. |