Forus 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					NMNM101110 6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No.			
Type of Well ☐ Gas Well ☐ Other					8. Well Name and No. RDX FEDERAL COM 17 44H			
Name of Operator Contact: CAITLIN O'HAIR RKI EXPLORATION & PROD LLC E-Mail: caitlin.ohair@wpxenergy.com					9. API Well No. 30-015-44409-00-X1			
3a. Address 3500 ONE WILLIAMS CENTE TULSA, OK 74172	3b. Phone No. Ph: 539-57	3b. Phone No. (include area code) Ph: 539-573-3527			10. Field and Pool or Exploratory Area PURPLE SAGE-WOLFCAMP (GAS)			
4. Location of Well (Footage, Sec., T			11. County or Parish	State				
Sec 17 T26N R30E NENW 75 32.049641 N Lat, 103.904083			EDDY COUNTY, NM					
12. CHECK THE AI	PPROPRIATE BOX(ES) TO INDICA	ΓE NATURE O	F NOTICE,	REPORT, OR OT	HER I	OATA	
TYPE OF SUBMISSION	TYPE OF ACTION							
S National State	☐ Acidize ☐ De		epen Prod		ction (Start/Resume)		Vater Shut-Off	
■ Notice of Intent	☐ Alter Casing	☐ Hydi	raulic Fracturing		ation	■ Well Integrity		
☐ Subsequent Report	agguent Beneat		Construction	☐ Recomplete			Other	
☐ Final Abandonment Notice	☐ Change Plans	— □ Plug	☐ Plug and Abandon		☐ Temporarily Abandon			
_	☐ Convert to Injection	_ ·			Water Disposal			
following completion of the involved testing has been completed. Final Al determined that the site is ready for f RKI EXPLORATION & PROD at least 200? above the 9 5/8'	pandonment Notices must be final inspection. UCTION, LLC requests	iled only after all i	equirements, includ	ing reclamation	n, have been completed	and the	operator has	
Detailed remediation plan and	l WBD are attached.							
Accepted for rec					PIL CONSERVA ARTESIA DISTRICI JAN 03 2018		d	
					RECEIVED			
14. I hereby certify that the foregoing is	Electronic Submission	DRATION & PR	DD LLC, sent to t	he Carlsbad	-			
Name(Printed/Typed) CAITLIN O'HAIR			Title PERMIT TECHNICIAN II					
Signature (Electronic								
	THIS SPACE F	OR FEDERA	L OR STATE	OFFICE U	SE			
_Approved_By_CHRISTOPHER WALLS			TitlePETROLE	UM ENGINE	ER		Date 12/27/2017	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Carlsbac	1				


Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

RDX Federal Com 17-44H

WPXENERGY

Wellbore Diagram

Wolfcamp A (lower) Eddy County, NM API #: 30-015-44409 Rig Release Date: 10/26/2017



Date Prepared:

12/4/2017

email:

taylor.carlson@wpxenergy.com

Date Revised: 12/4/2017

email: nicolette.ferraradas@wpxenergy.com



RKI Exploration & Production, LLC RDX Federal Com 17-44H

Drilling Program Eddy County, NM

December 21, 2017

9-5/8" x 7" Remedial Squeeze

Objective: The objective is to remediate the TOC behind the 7" casing to at least 200-ft above the 9-5/8" casing shoe.

API#: 30-015-44409

Procedure

- 1. Notify BLM at least 4 hours prior to upcoming cement job.
- 2. MIRU Par Five Equipment
- 3. Record pressure on 7" casing and 9-5/8" x 7" annulus. Bleed off pressure on 9-5/8" x 7" annulus if any.
- 4. Tie into 2-1/16" 5K inlet valve on wellhead to pump down 9-5/8" x 7" annulus.
- 5. Test cement lines to 3,000 psi.
- 6. Establish injection rates at 2, 3, and 4 bpm with 50 bbls of freshwater. Record pressures at each rate.
 - a. Do not exceed 2,000 psi while pumping cement job. Set pump kick out at 2,000 psi.
 - b. Discuss with drilling superintendent/engineer if additional pressure is needed.
- 7. Pump 423 sx, 143 bbls of 35/65 Poz C with additives, mixed @ 12.9 ppg & 1.91 ft³/sk
- 8. Displace cement with 3 bbls of freshwater
 - a. Treat freshwater with corrosion inhibitor to protect casing
- 9. Open other 2-1/16" 5K inlet valve to 9-5/8" x 7" annulus and monitor to see if well is on vacuum.
- 10. Record pump rates and pressures. Send data to engineer to be entered into Openwells.