DIID	PARTMENT OF THI		or	D As	eld Offic tesia ^{No.} LC.	053250 4		
BUREAU OF LAND MANAGEMENT OCD SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6.1	6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit of CA/Agreement, Name and/or No.			
1. Type of Well	100		and the	8	Well Name and No.			
Oil Well Gas	and the second sec	the states and	Land a st	0	8. Well Name and No. Maddren "A" Federal #4			
2. Name of Operator EnergyQuest II, LLC 3a Address 4500 December 5500 De				The second second	9. API Well No. 30-015-23123			
4526 Research Porest D1., Ste. 200 The Woodlands, TX 77381 (281) 875-620			de area code	(10. Field and Pool or Exploratory Area Grayburg Jackson 7R-QN-GB-SA			
 Location of Well (Footage, Sec., T.,R.,M., or Survey Description) Sect. 28, T17S, R30E; 330' FNL & 1650' FEL 			11. Country or Parish, State Eddy County, NM					
	the second second second second second		TE NATURE	the later of the		FR DATA		
	ECK THE APPROPRIAT	E BUA(ES) IU INDICAI	and the second second		and the second	CR DAIA		
TYPE OF SUBMISSION			TYI	PE OF ACTIO	The second second	UV-ta-6	Shut-Off	
✓ Notice of Intent	Acidize	Deepen Hydraulic l	Fracturing	Product Reclam	ion (Start/Resume) ation	Water S		
	Alter Casing	New Const		Recom		Other		
Subsequent Report	Casing Repair	Plug and A			mporarily Abandon			
Final Abandonment Notice	Convert to Injec			Water I				
completion of the involved operat completed. Final Abandonment N is ready for final inspection.) MIRU pulling unit. Pull completion assembly. Repair failed components. Change pump.	will be performed or provid	le the Bond No. on file wi	th BLM/BIA	Required su eletion in a ne	bsequent reports mus w interval, a Form 31	t all pertinent i t be filed with 60-4 must be	in 30 days following filed once testing has been	
completion of the involved operat completed. Final Abandonment N is ready for final inspection.) MIRU pulling unit. Pull completion assembly. Repair failed components.	will be perfonned or provid tions. If the operation resu Notices must be filed only a	le the Bond No. on file wi Its in a multiple completic after all requirements, incl	ations and n th BLM/BIA on or recomp luding reclan	Required and the Required sub- clicition in a net sub-	rue vertical depths of bsequent reports mus w interval, a Form 31 een completed and th	t all pertinent i t be filed with 60-4 must be ne operator has	in 30 days following filed once testing has been	
completion of the involved operat completed. Final Abandonment N is ready for final inspection.) MIRU pulling unit. Pull completion assembly. Repair failed components. Change pump . Rig down pulling unit.	will be perfonned or provid tions. If the operation resu Notices must be filed only a	le the Bond No. on file wi Its in a multiple completic after all requirements, incl	ations and n th BLM/BIA on or recomp luding reclan	Required and the Required sub- clicition in a net sub-	rue vertical depths of bsequent reports mus w interval, a Form 31 een completed and th	t be filed with 60-4 must be the operator has	in 30 days following filed once testing has been	
completion of the involved operat completed. Final Abandonment N is ready for final inspection.) MIRU pulling unit. Pull completion assembly. Repair failed components. Change pump . Rig down pulling unit.	will be perfonned or provid tions. If the operation resu Notices must be filed only a	le the Bond No. on file wi	ations and n th BLM/BIA on or recomp luding reclan	Required and the Required sub- clicition in a net sub-	rue vertical depths of bsequent reports mus w interval, a Form 31 een completed and th	t be filed with 60-4 must be the operator has	in 30 days following filed once testing has been	
completion of the involved operat completed. Final Abandonment N is ready for final inspection.) MIRU pulling unit. Pull completion assembly. Repair failed components. Change pump. Rig down pulling unit.	will be perfonned or provid tions. If the operation resu Notices must be filed only a	le the Bond No. on file wi Its in a multiple completic after all requirements, incl	ations and n th BLM/BIA on or recomp luding reclan	Required and the Required sub- clicition in a net sub-	rue vertical depths of bsequent reports mus w interval, a Form 31 een completed and th RECE	EVED 3 2018	markers and zones. Attach in 30 days following filed once testing has been s detennined that the site	
completion of the involved operat completed. Final Abandonment N is ready for final inspection.) MIRU pulling unit. Pull completion assembly. Repair failed components. Change pump . Rig down pulling unit.	will be perfonned or provid tions. If the operation resu Notices must be filed only a	le the Bond No. on file wi Its in a multiple completic after all requirements, incl	ations and n th BLM/BIA on or recomp luding reclan	Required and the Required sub- clicition in a net sub-	rue vertical depths of bsequent reports mus w interval, a Form 31 een completed and th	EVED 3 2018	markers and zones. Attach in 30 days following filed once testing has been s detennined that the site	
completion of the involved operat completed. Final Abandonment N is ready for final inspection.) MIRU pulling unit. Pull completion assembly. Repair failed components. Change pump . Rig down pulling unit. Return to production.	will be perfonned or provid titons. If the operation resu Notices must be filed only a	le the Bond No. on file wi Its in a multiple completion after all requirements, incl 6 - 5 - 24 - pted for record - N	entions and n th BLM/BIA on or recomp luding reclan	neasured and i	rue vertical depths of bsequent reports mus w interval, a Form 31 een completed and th RECE	EVED 3 2018	markers and zones. Attach in 30 days following filed once testing has been s detennined that the site	
completion of the involved operat completed. Final Abandonment N is ready for final inspection.) MIRU pulling unit. Pull completion assembly. Repair failed components. Change pump . Rig down pulling unit. Return to production.	will be perfonned or provid titons. If the operation resu Notices must be filed only a	le the Bond No. on file wi Its in a multiple completion after all requirements, incl 6 - 5 - 24 - pted for record - N	eations and n th BLM/BIA on or recomp luding reclan 1 8 MOCD	Required and the Required sub- clicition in a net sub-	rue vertical depths of bsequent reports mus w interval, a Form 31 een completed and th RECE	EVED 2 3 2018 ARTESIA C	narkers and zones. Attach in 30 days following filed once testing has been s detennined that the site	
completion of the involved operat completed. Final Abandonment N is ready for final inspection.) MIRU pulling unit. Pull completion assembly. Repair failed components. Change pump . Rig down pulling unit. Return to production. 14. I hereby certify that the foregoing Debra Moore	will be perfonned or provid titons. If the operation resu Notices must be filed only a	e the Bond No. on file wi Its in a multiple completic after all requirements, incl	eations and n th BLM/BIA on or recomp luding reclan MOCD	neasured and i	rue vertical depths of bsequent reports mus w interval, a Form 31 een completed and th RECE	EVED 2 3 2018 ARTESIA C	markers and zones. Attach in 30 days following filed once testing has been s detennined that the site	
completion of the involved operat completed. Final Abandonment N is ready for final inspection.) MIRU pulling unit. Pull completion assembly. Repair failed components. Change pump . Rig down pulling unit. Return to production. 14. I hereby certify that the foregoing Debra Moore	will be perfonned or provid trions. If the operation resu Notices must be filed only a GACCE	le the Bond No. on file wi Its in a multiple completic after all requirements, incl <i>G</i> - <i>S</i> - <i>2 Y</i> - pted for record - <i>P</i> <i>e</i> (<i>Printed/Typed</i>) Tith	e Productice	neasured and it. Required su letion in a ne nation, have b	RECE MAY DISTRICT II- 04/10/20	EVED 2 3 2018 ARTESIA C	narkers and zones. Attach in 30 days following filed once testing has been s detennined that the site	
completion of the involved operat completed. Final Abandonment N is ready for final inspection.) MIRU pulling unit. Pull completion assembly. Repair failed components. Change pump . Rig down pulling unit. Return to production. 14. I hereby certify that the foregoing Debra Moore Signature	will be perfonned or provid trions. If the operation resu Notices must be filed only a GACCE	le the Bond No. on file wi Its in a multiple completic after all requirements, incl 6 - 5 - 2 4 - pted for record - N e (Printed/Typed) Title Dat	e Productice	neasured and it. Required su letion in a ne nation, have b	RECE MAY DISTRICT II- 04/10/20	EVED 2 3 2018 ARTESIA C	narkers and zones. Attach in 30 days following filed once testing has been s detennined that the site	
completion of the involved operat completed. Final Abandonment N is ready for final inspection.) MIRU pulling unit. Pull completion assembly. Repair failed components. Change pump . Rig down pulling unit. Return to production. 14. I hereby certify that the foregoing Debra Moore	will be perfonned or provid ttions. If the operation resu Notices must be filed only a g is true and correct. Name Model THE SP/ ttached. Approval of this no or equitable title to those r	le the Bond No. on file wi Its in a multiple completic after all requirements, incl <i>G</i> - 5 - 2 4 - <i>G</i> - 7 - 7 - <i>G</i> -	e Productice e Productice	neasured and it. Required su letion in a ne nation, have b	RECE MAY 04/10/20 TEUSEORIC MAY 16 20	EVED 3 2018 ARTESIA C /s/ JOI 018	narkers and zones. Attach in 30 days following filed once testing has been s detennined that the site	