Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103
<u>District 1</u> – (575) 393-6161 RECEIVED Energy, Minerals and Natural Resource 1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30_015_36384
District II - (575) 748-1283 811 S. First St., Artesia, NM 88219 UN 0 4 20 IIL CONSERVATION DIVISION District III - (505) 334-6178 1220 South St. Francis Dr.	5. Indicate Type of Lease
District III - (505) 334-6178 JUN 9 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460 District IV - (505) 476-3460	STATE FEE 6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Saptisterior II-ARTESIA O.C.D. Santa Fe, NM 87505 87505	36900
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	RDX 16 8. Well Number 003
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator RKI EXPLORATION & PRODUCTION, L	0 OGPID Number
3. Address of Operator 3500 ONE WILLIAMS CENTER MD 35	10. Pool name or Wildcat
TULSA, OK 74172 4. Well Location	WILD CAT G-03 S263016K; BONE SPRING
Unit Letter P : 990 feet from the SOUTH line and 990 feet from the EAST line	
Section 16 Township 26S Range 30E	
11. Elevation (Show whether DR, RKB, RT, G. 3,082' GR	r, etc.)
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
	E DRILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CE	EMENT JOB
CLOSED-LOOP SYSTEM	_
OTHER: OTHER: OTHER: OTHER:	ils, and give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion. 5-16-18 MIRU Contact NMOCD.	
5-21-18 Set CIBP 5550'. Contact NMOCD- Tag CIBP Circulate Salt Gel. Spot 25 sacks Class C 5550'-5303'. WOC.	
5-22-18 Tag Plug @ 5300'. Notify NMOCD. Tag Approved. Spot 25 sacks Class C 5049'-4802'. WOC. Tag Plug @ 4780'.	
Perforate @ 3626'. Attempt to establish rate. No rate. Discuss with Gilbert NMOCD. Approved to spot. Spot 25 sacks Class C 3676'-3433'. WOC. Tag Plug @ 3450'. Notify NMOCD. Tag Approved. Perforate @ 2590'. Attempt to establish rate. No rate. Notify	
NMOCD. Drop down to 2640'. Spot 25 sacks Class C 2640'-2397'. WOC.	
5-23-18 Tag Plug @ 2350'. Notify NMOCD of tag. Perforate @ 530'. Establish circulation out 8-5/8. Squeeze 70 sacks Class C.	
NOC. Tag Plug @ 350'. Notify NMOCD of Tag. Perforate @ 150' Circulate 80 .eave 5-1/2 Casing full.	sacks Class C 150'-Surface in 8-5/8" Annulus.
Spud Date: 07/28/2008 Rig Release Date:	10/18/2008
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE LITTLE Permit Tech	
Type or print name Caitlin O'Hair E-mail address: caitlin.ohair@wpxenergy.com PHONE: 539-573-3527	
APPROVED BY:	DATE 6-4-18