Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMLC057634

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee o	r Tribe Nam	ıc
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agree	ment, Name	c and/or No.
1. Type of Well					8. Well Name and No. MCINTYRE A WE	ST 16	
					9. API Well No.		
COG OPERATING LLC E-Mail: kcastillo@concho.com					30-015-31855		
3a. Address 600 W ILLINOIS AVE MIDLAND, TX 79701 3b. Phone No. (include area code) Ph: 432-685-4332					10. Field and Pool or I LOCO HILLS;GI	LORIETA	YESO
4. Location of Well (Footage, Sec., T.	11. County or Parish,	State	2009				
Sec 20 T17S R30E Mer NMP	ı	EDDY COUNTY	', NM	0.80-7			
12. CHECK THE AP	PROPRIATE BOX(ES)	TO INDICAT	E NATURE O	F NOTICE,	REPORT, OR OTH	IER DAT	A
TYPE OF SUBMISSION			TYPE OF	ACTION			
Notice of Intent ■ Notice of Intent Notice of	☐ Acidize	□ Deep	en	☐ Product	ion (Start/Resume)	☐ Water	r Shut-Off
☐ Subsequent Report	☐ Alter Casing	-	aulic Fracturing	☐ Reclama			Integrity
	Casing Repair	_	Construction	Recomp		Other	•
☐ Final Abandonment Notice	Change Plans		and Abandon		arily Abandon		
13. Describe Proposed or Completed Ope	Convert to Injection	Plug		☐ Water D	•		
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. COG Operating LLC, respectfully requests to recomplete to the San Andres as follows: MCINTYRE A WEST #16 We are going to set a CIBP at 4,518? (50? above the YESO perfs) w/ 40? of CMT on top of the plug to have our PBTD @ 4,478?. We plan to have our top perfs from 3,260? ? 3,635? and bottom perfs from							30 days filed once ator has
3,675?-4,060?. Ideally, we like bottom hole assembly room ar desired rathole space, this give time.	nd prevent tubing from get es COG the option to re-e	ting stuck with nter the Glorie	n sand. In addit etta/Yeso forma	tion to havin		R 2 6 20	
	Accepted to	-26-1	e		DISTRICT	II-AH IES	IA U.U.D.
Equipment Pull Procedure ? MIRU WSU, NU BOP ? Unset pump and POOH with rod and tbg SEE ATTACHED FOR CONDITIONS OF APPROVAL						L	
14. I hereby certify that the foregoing is true and correct. Electronic Submission #409114 verified by the BLM Well Information System For COG OPERATING L.C., sent to the/Carlsbad Committed to AFMSS for processing by PRISCILLA/PEREZ on 03/26/2018 () Name (Printed/Typed) KANICIA CASTILLO Title PREPARER							
Namc (Printed/Typed) KANICIA C	CASTILLO		Title PREPAR	KER /	//	$\wedge / -$	+
Signature (Electronic S	ubmission)		Date 03/23/20	018 /\ [PPRAVED	- X 7/	1
	THIS SPACE FO	R FEDERAL				,/ /	
		Ī		-/		 	
Approved By]	Title	_/ AF	PR // 2 20/18 /	Mate	
Conditions of approval, if any, are attached certify that the applicant holds legal or equi which would entitle the applicant to conduc	itable title to those rights in the		Office	BUREAU	VF LAND MANAGEM		
States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							
Instructions on page 2) ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **							

Additional data for EC transaction #409114 that would not fit on the form

32. Additional remarks, continued

? PU scraper and scrape down to 4,570? ? RU Wireline

? Nake gauge ring/ junk basket run
? Set CIBP @ 4,518?
? Wireline truck dump 40? Class C cement of top of CIBP
? Tag cement plug to verify depth of 4,478?
? Pull up 4? to circulate hole clean with fresh water, and displace w/ 2% KCL and 1% packer

? Test Casing to 4,300 psi and report back to engineering if the pressure holds.
? Dump bail acid in the perf interval
? RIH w/ perforating guns and perforate San Andres Zone from 3,675?-4,060?, w/ 3 spf, 120? phasing,

54 holes

? NU 5K frac valve

? Secure wellbore ? RDMO WSU

Tentative Recompletion Procedure
? RU Elite Well Services Frac Crew
? Acidize w/ 1,500 gals of 15% HCI.
? XL Frac zone w/ 375,000 # of sand.
? Record ISIP and FG, Get 5, 10, 15 min SIP
? Rig up Wireline
? RIH w/ WL and set Composite Plug @ 3,655?
? Perforate San Andres Zone from 3,260?-3,635?, w/ 3 spf, 120? phasing, 54 holes.
? Acidize w/ 1,500 gals of 15% HCI.

? Acidize w/ 1,500 gals of 15% HCl. ? XL Frac zone w/ 375,000 # of sand. ? Record ISIP and FG, Get 5, 10, 15 min SIP ? RDMO Elite

Please see attachment for full procedure.

MCINTYRE A WEST #16

We are going to set a CIBP at 4,518' (50' above the YESO perfs) w/ 40' of CMT on top of the plug to have our PBTD @ 4,478'. We plan to have our top perfs from 3,260' – 3,635' and bottom perfs from 3,675'-4,060'. Ideally, we like to have 200'-300' of rathole below our bottom perfs to give our bottom hole assembly room and prevent tubing from getting stuck with sand. In addition to having desired rathole space, this gives COG the option to re-enter the Glorietta/Yeso formation at later time.

Equipment Pull Procedure

- MIRU WSU, NU BOP
- Unset pump and POOH with rod and tbg
- PU scraper and scrape down to 4,570'
- RU Wireline
- Make gauge ring/junk basket run

Sacie @4,518

• Wireline truck dump 40' Class C cement of top of CIBP

ilar coment plug to wealth depth of 4,47/8

- Pull up 4' to circulate hole clean with fresh water, and displace w/ 2% KCL and 1% packer corrosion inhibitor.
- Test Casing to 4,300 psi and report back to engineering if the pressure holds.
- Dump bail acid in the perf interval
- RIH w/ perforating guns and perforate San Andres Zone from 3,675° 4,660, w/ 3 spf, 120° phasing, 54 holes
- NU 5K frac valve
- Secure wellbore
- RDMO WSU

Tentative Recompletion Procedure

- RU Elite Well Services Frac Crew
- Acidize w/ 1,500 gals of 15% HCl.
- XL Frac zone w/ 375,000 # of sand.
- Record ISIP and FG, Get 5, 10, 15 min SIP
- Rig up Wireline

: RAPL w/ VOM word some Companying Phys. (c) 3,15513

- Perforate San Andres Zone from 3/20/5 (w/ 3 spf, 120° phasing, 54 holes.
- Acidize w/ 1,500 gals of 15% HCl.
- XL Frac zone w/ 375,000 # of sand.
- Record ISIP and FG, Get 5, 10, 15 min SIP
- RDMO Elite

Return to Production Procedure

- MIRU WSU
- RIH with bit and jet tool to drill out composite plugs
- Clean out fill to new THIN (0) 4 ANN
- RIH with production tubing as follows:
 - o (98) jts 2-7/8" J55 6.5# tbg
 - o (1) 2' marker joint


- o (2) jts 2-7/8" J55 6.5# tbg
- o TAC @3,252'
- o (26) jts 2-7/8" J55 6.5# tbg
- o SN @ 4,097'
- o (1) 20' MSMA
- o EOT @ 4,117'
- ND BOP, set TAC, flange up WH
- RIH w/ rod design as follows:
 - o (1) 26' x 1-1/4" SMPR w/ 1-1/2" liner
 - o (1) 6' x 7/8" pony rod
 - o (2) 8' x 7/8" pony rods
 - o (25) 7/8" N-97 rods
 - o (130) 7/8" N-97 rods
 - o (8) 1-5/8" K bars
 - o (1) 25-150 RHBC-20' Pump
- Please reuse as many node as possible and pull the lost from traverrony
- · MISSELY OF THAT TRUBERS TO THE
- · HEASE PURE WARE IN HOME HOPE ON GRANTS (NOOT STOKE LENGTH)
 - o Unit currently in middle hole
- Hang on, load tubing and note pump action and alignment
- Clean location
- Update rod and tubing detail in Well View
- All charges will hit AFE #
- PWOP and contact Robby Miller before turning on
- RDMO, TOTP

amont

COG Operating LLC

Lease & Well # McIntyre A West # 16

Spud: 8/27/01




Proposed

COG Operating LLC

Lease & Well # McIntyre A West # 16 WELL NAME: McIntyre A West SHL: O-17-17S-30E BHL: O-17-17S-30E Spud: 8/27/01 FORMATION: Yeso LEGAL: O-17-17S-30E Elevation - 3611' KB -13 3/8" 54# H-40 STC csg @ 427', 450 sx. Ready mix to surface. 8 5/8" 24# J-55 StC @ 1217', 625 sx, circ 64 sx San Andres 3260 - 3635, 3 spf, 54 holes. Acidized w/1,500 gal 15% HC! Frac'd with 375,000 lbs sand COMPOSITE PLUG @ 3,655' 3675 - 4060, 3 spf, 54 holes. Acidized w/ 1,500 gal 15% HCI Frac'd with 375,000 lbs sand DV tool -4202' PBTD @ 4478' CIBP w/ 40' cmt plug on top @ 4518' Marker jt @ 4700' Yeso 4568.5 - 4710, 1 spf, 42 holes. Acidized w/2000 gal 15% NEFE Treat w/32,000 gal 20% HCL, 54,000 gal LG, 5,000 gal 15% HCL CIBP - 5400' 5439 - 5817.5, 30 holes Acidize w/2000 gal 15% HCL CIBP - 5875' 5889.5 - 6036, 47 holes Acidize w/2000 gal 15% HCL 1st stage: 480- 50/50/2 c, circ. 56 sx PBTD - 6193 2nd stage: 825 sx , circ 97 sx.

5 1/2" 17 # J-55 LT&C csg @ 6204'.

#16		PROSPECT NAME:	Loco Hills
330 FSL	2160 FEL	STATE & COUNTY:	New Mexico, I
330 FSL	2160 FEL	OBJECTIVE:	Two stage Recompletion to GB-SA
		DEPTH:	5,400
			



9 10 11 12 13 14 15 16 17 18

3426 3447 3468 3469 3560 3560 3561 3572 3568 3614

3 3 3 3 3 3 3 3 3 3 3

9 10 11 12 13 14 15 16 17

District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 8821 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 875	0	rgy, Minera OIL CON 1220 Sa	NSERVAT South St. anta Fe, NI	Resources Depa ION DIVISION Francis Dr. M 87505	DISTRICT II-A	A Blû Gd O AIRBTRA □	Revis ppropria CState Fee AME	Form C-102 ed June 10, 2003 te District Office Lease - 4 Copies Lease - 3 Copies NDED REPORT
			AND ACR	EAGE DEDIC				
API Number		¹ Pool Code	1		' Pool Na		C.A.	
30-015-31855	İ	28509			ayburg Jackson	; 5K-Q-G-	5A	
Property Code			⁵ Property N	iame		1	* Well Number	
302521			McIntyre A	West				16
OGRID No.		Operator Name					* Elevation	
229137		COG OPERATING LLC					3616	
¹⁰ Surface Location								
UL or lot no. Section Township	Range	Lot Idn F	Feet from the	North/South line	Feet from the	East/Wes	t line	County
O 20 17S	30E		330	South	2160	East	t	Eddy
11 Bottom Hole Location If Different From Surface								
UL or lot no. Section Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/\	Vest line	County
].]]
12 Dedicated Acres 13 Joint or Infill 14	Consolidation Co	ode 15 Order	No.	-	-			
40								· · ·

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

				¹⁷ OPERATOR CERTIFICATION
•				I hereby certify that the information contained herein is true
				and complete to the best of my knowledge and belief.
·				V , C
				Signature
				Kanicia Carrillo
			•	Lead Regulatory Analyst
				Title and E-mail Address
				07/22/15
				Date
	•			
			1	19
			·	18SURVEYOR CERTIFICATION
				I hereby certify that the well location shown on this plat was
				plotted from field notes of actual surveys made by me or under
				my supervision, and that the same is true and correct to the
				best of my belief.
				Referred Original Survey
				Date of Survey
				Signature and Seal of Professional Surveyor:
			2160'	
	·		2100	
	,	. ○ ◀	•	,
		233		Certificate Number

RP 5-4-18

RECEIVED

Energy, Minerals & Natural Resources Department PR 26 2018
OIL CONSERVATION DIVISION Form C-102

at time per ' O.C. Revised June 10, 2003

IN Superior of Appropriate District Office

State Lease - 4 C District I 1625 N. French Dr., Hobbs, NM 88240 1301 W. Grand Avenue, Artesia, NM 88210 District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV ☐ AMENDED REPORT 1220 S. St. Francis Dr., Santa Fe, NM 87505 WELL LOCATION AND ACREAGE DEDICATION PLAT API Number Pool Code ³ Pool Name 96718 30-015-31855 Loco Hills; Glorieta-Yeso ⁵ Property Name Property Code Well Number 302521 McIntyre A West 16 OGRID No. ⁶ Operator Name Elevation 229137 COG OPERATING LLC 3616 ¹⁰ Surface Location UL or lot no. Range North/South line Section Township Lot Idn Feet from the Feet from the East/West line County 20 **17S** 30E 330 South 2160 East Eddy 11 Bottom Hole Location If Different From Surface UL or lot no. Section Township Range Lot Idn Feet from the North/South line Feet from the East/West line County

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A
NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

12 Dedicated Acres

Joint or Infill

Consolidation Code

Order No.

NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION					
				¹⁷ OPERATOR CERTIFICATION	
·				I hereby certify that the information contained herein is true	
				and complete to the best of my knowledge and belief.	
				Y.C.	
				Signature	
				Kanicia Carrillo	
	!			Lead Regulatory Analyst	
	. !			Title and E-mail Address	
	. !	†	,	07/22/15	
·	ļ .			Date	
				18SURVEYOR CERTIFICATION	
•	!		•	I hereby certify that the well location shown on this plat was	
i			,	plotted from field notes of actual surveys made by me or under	
	. !	1	į	my supervision, and that the same is true and correct to the	
		1		best of my belief.	
	·	1		Referred Original Survey	
			<u> </u>	, .	
1		- 		Date of Survey	
l]	Í	å	Signature and Seal of Professional Surveyor:	
1		i 1	34.60	•••••••••••••••••••••••••••••••••••••••	
].	Í	2160'		
		. ∘ ←			
l ,		<u> </u>	<u>.</u>	Certificate Number	
A .	i .	<u>~</u>			

Mcintyre A West 16 30-015-31855 COG Operating LLC April 12, 2018 Conditions of Approval

Work to be completed by July 12, 2018.

1. Operator shall place a CIBP at 4,518' and place 40' Class C Cement on top of the CIBP. WOC and TAG.

Note: At a later date, operator will need to add 110' of cement to the CIBP to properly seal the Glorietta Formation.

- 2. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails.
- 3. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 4. Surface disturbance beyond the originally approved pad must have prior approval.
- 5. Closed loop system required.
- 6. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 7. Operator to have H2S monitoring equipment on location.
- 8. A minimum of a 2000 (2M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.

- 9. Subsequent sundry required detailing work done and completion report for the formation. Operator to include new well plat and well bore schematic of current well condition when work is complete.
- 10. See attached for general requirements.

JAM 041218

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220

575-234-5972

Permanent Abandonment of Production Zone Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within **ninety (90)** days from this approval.

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. Notification: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822, For wells in Lea County, call 575-393-3612
- 3. Blowout Preventers: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13.636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. Mud Requirement: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. Cement Requirement: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Subsequent Plug back Reporting: Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date work was completed.

