

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON
Governor

0 2006 APR 17 PM 12 49

P/A O/C To Relace

4/1-8/06

Joanna Prukop
Cabinet Secretary
Acting Director
Oil Conservation Division

10 April 2006

Elk Oil Company
P. O. Box 310
Pocyvell New Mex

Roswell, New Mexico 88202-0310

RECEIVED

APR 2 0 2006 OCU-ARTESIA

Field Rep. II

Form C-103 Report of Plugging for you're Hi-Way State # 1 J-36-10-27 API 30-005-63021 Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- 1. All pits have been closed as per Rule 50.
- 2. Rat hole and cellar have been filled and leveled.
- □ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- 5. The dead men and tie downs have been cut and removed.
- 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Joseph J. Kelly, President

Title

Date: April 13, 2006

Oil Conservation Division * 1220 South St. Francis Drive * Santa Fe, New Mexico 87505 Phone: (505) 476-3440 * Fax (505) 476-3462 * http://www.emnrd.state.nm.us

Sport of a growing a payor but the control of a long to the control of the contro

Submit 3 Copies to Appropriate

(This space for State Use)

CONDITIONS OF APPROVAL, IF ANY

APPROVED BY

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

MAY 0 2 2006

DATE

District Office **OIL CONSERVATION DIVISION** DISTRICT I 2040 South Pacheco 1625 N. French Dr., Hobbs, NM 88240 WELL APL NO 30-005-63021 Santa Fe, New Mexico 87505 DISTRICT II 5. Indicate Type of Lease STATE \overline{X} FEE 1301 W. Grand Ave., Artesia, NM 88210 DISTRICT III 6 State Oil & Gas Lease No. V-4978 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) RECEIVED οiι. GAS WELL WELL \Box HI-WAY STATE APR 0 7 2006 Name of Operator 8 Well No ELK OIL COMPANY UUU-MATERIM 9. Pool Name or Wildcat 3. Address of Operator POST OFFICE BOX 310, ROSWELL, NEW MEXICO 88202-0310 WOLFCAMP 4. Well Location 2417 2245 EAST Unit Letter Feet From The Line and Feet From The 10 SOUTH 27 EAST NMPM County Section 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3698' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING REMEDIAL WORK PLUG AND ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER OTHER 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103 Plug and Abandon Well as Follows: 04/14/05 SET CIBP @ 5700' - DUMP 35' CEMENT ON TOP 04/18/05 SPOT 25 SXS @ 4500'-4300' 04/18/05 SPOT 25 SXS @ 3500'-3125' 04/18/05 PULL 1586' OF 5 1/2" CASING 04/18/05 SPOT 50 SXS @ 1636'-1448' TAG 04/19/05 SPOT 35 SXS @ 350'-250' 04/19/05 SPOT 10 SXS @ 30' TO SURFACE INSTALL DRY HOLE MARKER, CIRCULATE 10# MUD. LOCATION HAS BEEN CLEANED AND LEVELLED. READY FOR INSPECTION. I hereby certify that the information above is true and complete to the best of my knowledge and belief. **PRESIDENT** 04/06/06 SIGNATURE -ERH J. KELLY TYPE OR PRINT TELEPHONE NO. 505-623-3190

TITLE