Fc m 3160-5 (June 2015)

UNITED STATES

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS
on of use this form for proposals to drill or to re-enter and the second s

abandoned we	II. Use form 3160-3 (APE)) for such p	roposals.	Arte	Sindian,	Allottee or	Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. NMNM88525X		
1. Type of Well					8. Well Name and No. BURCH KEELY UNIT 967H		
2. Name of Operator Contact: SANDY BALLARD					9. API Well No.		
COG OPERATING LLC			30-015-39579-00-S1				
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701 3b. Phone N Ph: 432-6			(include area code) 6-4373		10. Field and Pool or Exploratory Area BURCH KEELY-GLORIETA-UPR YES		
4. Location of Well (Footage, Sec., T			11. County or Parish, State				
Sec 19 T17S R30E NWSW 17			EDDY COUNTY, NM				
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE, I	REPORT,	OR OTH	ER DATA
TYPE OF SUBMISSION	TYPE OF ACTION						
□ Notice of Intent	☐ Acidize	☐ Deep	☐ Deepen ☐		☐ Production (Start/Resume)		■ Water Shut-Off
	☐ Alter Casing			☐ Reclamat			☐ Well Integrity
Subsequent Report	☐ Casing Repair	_	Construction	- •			Other Venting and/or Flari
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection		Plug and Abandon		n	ng	
determined that the site is ready for five strength of the Burch Keely Sat. A Battery Permit approval: Electronic Sun Actual gas flared for this batte April Total for Battery = 0 MCF May Total for Battery = 0 MCF June Total for Battery = 0 mcf Number of wells to flare: (51) BURCH-KEELY UNIT 85 30-0	ubmission #408397 ry for 4/2/2018 TO 7/1/201	18 is as follov	vs: Acce	NH/SH pred for	AB Tecció	ARTES	DNSERVATION LA DISTRICT 1 2 2018
				<u> NMOCI</u>	<u> </u>	REC	CEIVED
14. I hereby certify that the foregoing is Com Name (Printed/Typed) SANDY E	Electronic Submission #4 For COG Ol nmitted to AFMSS for proce	PERATING L	C, sent to the Ca SCILLA PEREZ or	ırlsbad	19PP0511S		
Signature (Electronic Submission)			Date 11/28/2018				
	THIS SPACE FO	R FEDERA	PARTER	FARRE			
_Approved By			Title Title	FUR RE	ינואטטב		Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office DEC	0 6 2018	/s/ Jon	athon	Shepard
Fitle 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any postates any false, fictitious or fraudulent statements or representations as to any matter w			thin[its][trisdiction	and Manage	EMENT	artment or a	gency of the United
Instructions on page 2)		1	CAKE2RA	U FIELD UFFI	(JE		

Additional data for EC transaction #445468 that would not fit on the form

32. Additional remarks, continued

```
BURCH-KEELY UNIT 87 30-015-21662 BURCH-KEELY UNIT 88 30-015-21665 BURCH-KEELY UNIT 89 30-015-03079
BURCH-KEELY UNIT 90 30-015-03073
BURCH-KEELY UNIT 106 30-015-26890 —
BURCH-KEELY UNIT 107 30-015-03076 —
BURCH-KEELY UNIT 108 30-015-25668 —
BURCH-KEELY UNIT 110 30-015-03067 /
BURCH-KEELY UNIT 111 30-015-21294 /
BURCH-KEELY UNIT 112 30-015-03075 /
BURCH-KEELY UNIT 139 30-015-03102 /
BURCH-KEELY UNIT 141 30-015-03110 /
BURCH-KEELY UNIT 219 30-015-27726 -
BURCH-KEELY UNIT 220 30-015-27769—
BURCH-KEELY UNIT 221 30-015-27764—
BURCH-KEELY UNIT 222 30-015-27788—
BURCH-KEELY UNIT 230 30-015-27991 BURCH-KEELY UNIT 235 30-015-28584 BURCH-KEELY UNIT 245 30-015-28156 BURCH-KEELY UNIT 246 30-015-28330
BURCH-KEELY UNIT 247 30-015-28335 #
BURCH-KEELY UNIT 271 30-015-29301 #
BURCH-KEELY UNIT 276 30-015-29512 —
BURCH-KEELY UNIT 280 30-015-29921 —
BURCH-KEELY UNIT 281 30-015-29511
BURCH-KEELY UNIT 282 30-015-29722 —
BURCH-KEELY UNIT 314 30-015-31526 —
BURCH-KEELY UNIT 315 30-015-30642 —
BURCH-KEELY UNIT 324 30-015-32427

BURCH-KEELY UNIT 325 30-015-32428

BURCH-KEELY UNIT 326 30-015-32429
BURCH-KEELY UNIT 340 30-015-32757
BURCH-KEELY UNIT 344 30-015-32712 -
BURCH-KEELY UNIT 345 30-015-32713
BURCH-KEELY UNIT 363 30-015-32992
BURCH-KEELY UNIT 365 30-015-32867 BURCH-KEELY UNIT 376 30-015-33569
BURCH-KEELY UNIT 406H 30-015-35564~
BURCH-KEELY UNIT 413 30-015-36209 –
BURCH-KEELY UNIT 415 30-015-37131 –
BURCH-KEELY UNIT 623 30-015-38561 –
BURCH-KEELY UNIT 624 30-015-39126 —
BURCH-KEELY UNIT 629 30-015-40705 —
BURCH-KEELY UNIT 630 30-015-38647
BURCH-KEELY UNIT 631 30-015-38648 /
BURCH-KEELY UNIT 636 30-015-38558 /
BURCH-KEELY UNIT 637 30-015-40183-
BURCH-KEELY UNIT 699 30-015-39551 /
BURCH-KEELY UNIT 966H 30-015-44067 /
BURCH-KEELY UNIT 967H 30-015-39579~
Reason for flare: UNPLANNED MIDSTREAM CURTAILMENT DUE TO HLP OR PLANT MAINTENANCE
```