

Office

Revised June 10, 2003

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO.

30.015. 01094

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Empire Abo Unit "F"

8. Well Number

32

9. OGRID Number

000778

10. Pool name or Wildcat

Empire Abo

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

BP America Production Company

3. Address of Operator

P.O. Box 1089, Eunice, NM 88231

4. Well Location

Unit Letter H : 1980 feet from the N line and 660 feet from the E lineSection 33 Township 17S Range 28E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3665' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐CASING TEST AND CEMENT JOB ☐OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

TD: 6280' PBD: 6263' PERFS: 5820-5836'

MIRUPU. NUBOP. Unset pkr & POH w/tbg.

RIH w/CIBP. Set @ 5810'. Spot 25 sxs cmt on top of plug.

RU and circ hole w/9.5# KCL mud.

PUH. Spot 25 sxs cmt f/3402-3502' across Glorieta

PUH. Spot 25 sxs cmt f/341-441' across Yates

POH w/tbg. RU and perf csg 50' below @ 1050'.

RIH w/pkr & squeeze 50 sxs cmt 50' out and 50' in. WOC.

POH w/pkr & tbg. RIH w/tbg open ended & tag cmt plug.

Pull up hole and spot 10 sxs cmt f/60' to surf. WOC.

Tag cmt. Cut off wellhead, dead man marker, and clean location.

Perf csg. @ 441- Place 100' of cmt. inside & outside of csg. 341-441-

Place 100' of cmt. inside & outside - TAS

Perf. csg. @ 60' Place 60' of cmt. inside & outside of csg. 0'-60' - WOC - 24 HAS - TAS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murriks TITLE Sr. Administrative Assistant DATE 07.17.03Type or print name Kellie D. Murriks E-mail address: murrikd@bp.com Telephone No. 505.394.1649

(This space for State use)

APPROVED BY [Signature] TITLE Field Rep ID DATE 7/21/03

Conditions of approval, if any:

OPERATOR: B-P America Production				API#	30-015-01694	
WELL: Empire Abo Ut. "F" # 32				LOCATION:	H-33-17-28	
SURFACE CSG-	HOLE SIZE	"	CSG. SIZE	8 5/8"	SET @	1000' SX. CMT. TOC. Circ
INT.CSG-	HOLE SIZE	??	CSG. SIZE	"	SET @	' SX. CMT. TOC.
LONG STRING-	HOLE SIZE	7 7/8"	CSG. SIZE	4.5"	SET @	6080' SX. CMT. TOC. 1000'
OTHER-						

