• Form 3180-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMLC029392B

SUNDRY NOTICES	AND REPORTS ON WELLS			
o not use this form for	proposals to drill or to re-enter an	_	n 1	3016

Do not use this form for proposals to drill or to re-enter all abandoned well. Use form 3160-3 (APD) for such proposals RPR 0.1 P

6. If Indian, Allottee or Tribe Name

	· · · · · · · · · · · · · · · · · · ·	 			 		
	TRIPLICATE - Other Inst	tructions on page 2	RICT II-ARTESIA C	7. If Unit or CA/Agree	ement, Name and/or No.		
1. Type of Well ☐ Gas Well ☐ Other				8. Well Name and No. PRINCIPLE FEDERAL 1			
Name of Operator Contact: NICK GLANN CHEVRON USA INCORPORATED E-Mail: nglann@chevron.com			9. API Well No. 30-015-32616-00-S1				
3a. Address 6301 DEAUVILLE BLVD MIDLAND, TX 79706	3b. Phone No. (include Ph: 661-599-5062	one No. (include area code) 61-599-5062		10. Field and Pool or Exploratory Area SHUGART			
4. Location of Well (Footage, Sec., T.	., R., M., or Survey Description)		11. County or Parish,	11. County or Parish, State		
Sec 27 T18S R31E NENW 990FNL 1650FWL				EDDY COUNTY, NM			
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICATE NAT	URE OF NOTICE	E, REPORT, OR OTI	HER DATA		
TYPE OF SUBMISSION		TYPE OF ACTION					
☐ Notice of Intent	☐ Acidize	☐ Deepen	_	ction (Start/Resume)	☐ Water Shut-Off		
C.1.	☐ Alter Casing	☐ Hydraulic Fr	acturing	mation	☐ Well Integrity		
Subsequent Report ■	☐ Casing Repair	■ New Constru	ction	nplete	Other		
☐ Final Abandonment Notice	☐ Change Plans	Plug and Ab	ındon 🔲 Temp	orarily Abandon			
	☐ Convert to Injection	Plug Back	☐ Water	Disposal			
determined that the site is ready for final inspection. 2/20-21/19 MiRU, LD 222 joints 2-7/8" tubing with TAC. Run gauge ring to 6100'. 2/22/19 Set CIBP @ 6070'. Tag CIBP. Pressure test casing to 1000# - good. Spot 14 bbls salt gel from 5817' to 5250'. Plug #1 25 sxs (1.32 yield, 14.8ppg) Class C cmt f/ 6070' t/ 5817'. 2/25/19 Pump 70 bbls 10 PPG BW mixed w/17 SG. Plug #2 80 sxs (1.32 yield, 14.8ppg) Class C cmt f/ 5250' t/ 4441'. Plug #3 75 sxs (1.32 yield, 14.8ppg) Class C cmt f/ 2600 t/ 1842'. Perforate @ 1700'. Establish injection rate 1 bpm @ 700#. Pumped 60 bbls 10 PPG BW - no returns. Plug #4 squeeze 25 sxs (1.33 yield, 14.8ppg) Class C cmt with 2% gas block f/ 1700' t/ 1600'. 2/26/19 Tag TOC @ 1485'. BLM. approved tag. Spot 18 bbls SG from 1485' to 714'. Perforate @ 714'. Establish injection rate 2 bpm at 200#down 5.5" - circulate out annulus. Plug #5 185 sxs (1.33 yield, 14.8ppg) Class C cmt f/ 714' t/ surface. Good cement returns. RDMO CC-1/26/19 Tag TOC @ 1485'. BLM. approved tag. Spot 18 bbls SG from 1485' to 714'. Perforate @ RECLAMATION DV CLAMATION C							
14. 1 hereby certify that the foregoing is true and correct. Electronic Submission #457005 verified by the BLM Well Information System For CHEVRON USA INCORPORATED, sent to the Carlsbad Committed to AFMSS for processing by PRISCILLA PEREZ on 03/06/2019 (19DLM0177SE)							
Name (Printed/Typed) NICK GLANN		Title	Title WELL ABANDONMENT ENGINEER				
Signature (Electronic S		Date	03/06/2019				
THIS SPACE FOR FEDERAL OR STATE OFFICAUSE PIEU FUR RECURD							
Approved By Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conduct the applicant to conduct the applicant to conduct the applicant to condu	uitable title to those rights in the			MAR -8	2019 Dite		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agencing the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							



Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filling the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filling the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crystal Weaver
Environmental Protection Specialist
575-234-5943

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612