Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**



FORM APPROVED OMB NO. 1004-0137

Expires: January 31, 2018

5. Lease Serial No. NMNM0555443

| SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals 1 2019 | | | | | | NMNM0555443 6. If Indian, Allottee or Tribe Name | | | | | |
|--|--|---|-----------------|-------------------|--------------------------------|--|---|------------------------|----------|---|--|
| SUBMIT IN TRIPLICATE - Other instructions on page 2 | | | | | | 7. If Unit or CA/Agreement, Name and/or No. 8910138100 | | | | | |
| 1. Type of Well | | | | | | 8. Well Name and No. | | | | | |
| ☐ Oil Well 🙎 Gas Well 🗖 Other | | | | | | | RAW 8 | | | | |
| Name of Operator Contact: CAITLIN O'HAIR RKI EXPLORATION & PROD LLC E-Mail: caitlin.ohair@wpxenergy.com | | | | | | | 9. API Well No. 30-015-23017-00-S1 | | | | |
| 3a. Address 3500 ONE WILLIAMS CENTER MD 35 TULSA, OK 74172 3b. Phone No. (include area code) Ph: 539-573-3527 | | | | | | | 10. Field and Pool or Exploratory Area UNDESIGNATED | | | | |
| 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) | | | | | | | 11. County or Parish, State | | | | |
| Sec 27 T26S R30E SWNE 1650FNL 1650FEL | | | | | | | EDDY COUNTY, NM | | | | |
| | 12. CHECK THE AF | PPROPRIATE BOX(ES) | TO INDICA | TE NATURE O | F NOTICE, | REPORT, (| OR OTH | ER DATA | | | |
| | TYPE OF SUBMISSION | | | | | | | | | | |
| | ☐ Notice of Intent | ☐ Acidize | Dee | pen | ☐ Producti | on (Start/Res | sume) | ■ Water | Shut-Off | f | |
| | • | ☐ Alter Casing | ☐ Hyd | raulic Fracturing | ☐ Reclama | ition | | ☐ Well In | ntegrity | | |
| | Subsequent Report ∴ | □ Casing Repair | ☐ Nev | Construction | ☐ Recomp | lete | | ☐ Other | | | |
| | ☐ Final Abandonment Notice | ☐ Change Plans | 🛛 Plug | and Abandon | ☐ Tempora | arily Abando | n | | | | |
| | | Convert to Injection | Plug | Back | □ Water D | isposal | | | | | |
| | Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond Under which the work will be performed or provide the Bond No. on life with BLM/BIA. Required subsequent reports must be filled within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filled once testing has been completed. Final Abandonment Notices must be filled only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. 04/25/19 MIRU plugging equipment. Dug out cellar. Circulated hole to kill well. Shut in well @ 700 PSI. 04/26/19 Circ'd hole w/ MLF, bled down well to 0 PSI. ND well head tree, NU BOP. 04/29/19 RIH w/ sink bar to 11,000'. Established fluid level @ 1650'. POH. Set 7" CIBP @ 6500'. Had well flow through the @ 1 BPM per minute. RU vacuum truck. 04/30/19 7" csg @ 0 PSI. Set 7" CIBP @ 10,912'. Circulated hole w/ 80 sx salt getl & 85 sx MLF. Spotted 30 sx class H cmt @ 7196-7405'. Spotted 40 sx class H cmt @ 8726-8965'. Spotted 35 sx class H cmt @ 7196-7405'. Spotted 40 sx class F cmt @ 3660-3302'. WOC. 05/02/19 Tagged plug @ 3820'. Perf'd csg @ 3610'. Pressured up on perfs to 600 PSI. Spotted 60 sx class C cmt @ 3660-3302'. WOC. 05/03/19 No tag. Re-spotted 60 sx class C cmt @ 3660-3302'. WOC. Tagged plug @ 3330'. Perf'd csg @ 3330'. Perf'd csg @ 3610'. Pressured up on perfs to 600 PSI. Spotted 60 sx class C cmt @ 3660-3302'. WOC. Tagged plug @ 3330'. Perf'd csg @ 3330'. Perf'd csg @ 3610'. Pressured up on perfs to 600 PSI. Spotted 60 sx class C cmt @ 3660-3302'. WOC. Tagged plug @ 3330'. Perf'd csg @ 3330'. Perf'd csg @ 3330'. Perf'd csg @ 3330' | | | | | | | | | | |
| class C cmt @ 3660-3302' WOC. 05/03/19 No tag. Re-spotted 60 sx class C cmt @ 3660-3302'. WOC. Tagged plug @ 3330'. Perf'd csg @ | | | | | | | | | OCD | | |
| | | | | | | - Cable | <i>b</i> | | | | |
| 14 | Components (Printed/Typed) CAITLIN C | # Electronic Submission For RKI EXPLO mitted to AFMSS for proce | KAHUN & PR | JU LLC, Sent to 1 | ne Carispad 1 05/09/2019 (1 | system I C | E) | R RECC 2019 | RD | | |
| | Signature (Electronic S | | | Date 05/09/2 | 019 | DMexic | ney | _ HE | | | |
| | | THIS SPACE FO | OR FEDERA | L OR STATE | OFFICE US | CARLSE | LAND WI BAD FIELD | anageiviei) Office | 41. | | |
| _Aı | pproved By | | · | Title | | | | Date | | | |
| certi whic | ditions of approval, if any, are attached ify that the applicant holds legal or equ ch would entitle the applicant to condu | itable title to those rights in the ct operations thereon. | e subject lease | Office | | | | | | | |
| F2412 | 18 U.S.C. Section 1001 and Title 42 1 | U.S.C. Spotion 1212 males it a | | man lenavinale | will6.11 to | les to any dema | etmont o | anner of the | 11 | | |

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #464745 that would not fit on the form

32. Additional remarks, continued

1145'. Established injection rate of 2 BBLS per minute @ 0 PSI. Squeezed 70 sx class C cmt @ 650' & displaced to 995'. WOC.

05/06/19 Pressure tested plug, held 700 PSI. Tagged plug @ 945'. Perf'd csg @ 385'. Squeezed 75 sx class C cmt @ 385 & displaced to 285'. WOC. Tagged plug @ 260'. Perf'd csg @ 150'. ND BOP. Established injection rate only on the 9.5/8". Pressured up to 600 PSI on 13 3/8" csg. Squeezed 45 sx class C cmt @ 150'. & circulated to surface on 7" & 9 5/8" csg. Rigged down & moved off. 05/07/19 Moved in backhoe and welder, dug out cellar, cut off well head, and Terry Wilson w/ BLM verified cement to surface. Welded on "Above Ground Dry Hole Marker". Backfilled cellar, cut off deadmen, cleaned location, and moved off. deadmen, cleaned location, and moved off.



BUKEAU UF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/mm

TAKE PRIDE®

In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filling the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filling the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3 The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

nave issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crystal Weaver Environmental Protection Specialist 575-234-5943

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Environmental Protection Specialist 575-234-5996

Trishia Bad Bear Hobbs Field Station Natural Resource Specialist 575-393-3612