<b>Y</b> ,	
Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 872	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 1200 G. H. G. F. L. G. F. F. L. G. F. L. G. F. F. F. L. G. F.	30-015-10337 5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	· 1
1000 Rio Brazos Rd., Aztec, NM 874 Santa Fe, NM 87505	STATE 🗷 FEE 🗌
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No. E 6018
SUNDRY NOTICES AND REPORTS ON WELLS 14 15, (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (PORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name: STATE
1. Type of Well: Oil Well 🖾 Gas Well 🗌 Other	8. Well Number
1: 55	9. OGRID Number
RAY WESTALL	018862
3. Address of Operator  BOX 4. LOSS Hills, NM 88255	10. Pool name or Wildcat
BOX 4, Loco Hills, NM 88255	SHUÇART
4. Well Location	
Unit Letter A : 330 feet from the NORTH line and	330 feet from the EAST line
Section 2 Township 195 Range 31E	NMPM County EDDY
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3630 GL	
Pit or Below-grade Tank Application or Closure	
Pit type STEEL Depth to Groundwater Distance from nearest fresh water well Dis	
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction	on Material
12. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	Report, or Other Data  SEQUENT REPORT OF:  ALTERING CASING
TEMPORARILY ABANDON	
PULL OR ALTER CASING	ABANDONMENT
OTHER: OTHER:	roved as to plugging of the well bore. Liability
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.	
10-17-06 Set 5 1/2" CIBP@2,875'. Cap w/35' cmt. w/Bailer. Circulate hole with mud. Spot 35 sx. cmt. @2,600'. Tag plug @2,260. Perf. 4 holes @975'. Set pkr. @630'. Sqz. 40 sx. cmt.	
02,600'. Tag plug 02,260. Perf. 4 holes 0975'. Set pkr. 00	330'. Sqz. 40 sx. cmt.
<pre>@2,600'. Tag plug @2,260. Perf. 4 holes @975'. Set pkr. @6  10-18-06 Tag plug @821'. Perf. 4 holes @500'. Set Pkr. @60'. Sqz. 4 4 hles @60'. Pump 25 sx. cmt. Down 5 1/2" to surf. out 8 5</pre>	0 sx. cmt. Tag plug @340'. Perf
10-18-06 Tag plug @821'. Perf. 4 holes @500'. Set Pkr. @60'. Sqz. 4	0 sx. cmt. Tag plug @340'. Perf
10-18-06 Tag plug @821'. Perf. 4 holes @500'. Set Pkr. @60'. Sqz. 4 4 hles @60'. Pump 25 sx. cmt. Down 5 1/2" to surf. out 8 5	30 sx. cmt. Tag plug @340'. Perf 5/8". Leave 5 1/2" full of cmt.
10-18-06 Tag plug @821'. Perf. 4 holes @500'. Set Pkr. @60'. Sqz. 4 4 hles @60'. Pump 25 sx. cmt. Down 5 1/2" to surf. out 8 5  10-19-06 Install Dry Hole Marker.  I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit SIGNATURE	30 sx. cmt. Tag plug @340'. Perf 5/8". Leave 5 1/2" full of cmt.
10-18-06 Tag plug @821'. Perf. 4 holes @500'. Set Pkr. @60'. Sqz. 4 4 hles @60'. Pump 25 sx. cmt. Down 5 1/2" to surf. out 8 5  10-19-06 Install Dry Hole Marker.  I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit  SIGNATURE	and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan  DATE
10-18-06 Tag plug @821'. Perf. 4 holes @500'. Set Pkr. @60'. Scz. 4 4 hles @60'. Pump 25 sx. cmt. Down 5 1/2" to surf. out 8 5  10-19-06 Install Dry Hole Marker.  I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit SIGNATURE	and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan  DATE 10-30-06