

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-10818
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. State 647
7. Lease Name or Unit Agreement Name: NORTHWEST ARTESIA UNIT
8. Well Number 8
9. OGRID Number 020451
10. Pool name or Wildcat Artesia, ON-GB-SA

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-100) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	2. Name of Operator SDX RESOURCES, INC.
3. Address of Operator P.O. BOX 5061, MIDLAND, TX 79704	4. Well Location Unit Letter <u>K</u> : <u>2310</u> feet from the <u>SOUTH</u> line and <u>2105</u> feet from the <u>WEST</u> line Section <u>32</u> Township <u>17S</u> Range <u>28E</u> NMPM County <u>EDDY, NM</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3687 RT	
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/> Pit type <u>W/O</u> Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: <u>12</u> mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

11-2-06 Set 4 1/2" CIBP @1,800'. Circulate hole with mud. Spot 25 sx. cmt. @1,800'. Perf 4 holes @1,240'. Set pkr. @900'. Sqz. 35 sx. cmt.

11-3-06 Tag plug @1,080'. Perf 4 holes @512'. Set pkr. @30'. Sqz. 70 sx. cmt. Tag & plug @200'. Perf 4 holes @60'. Pump 15 sx. cmt. down 4 1/2" to surf. out of 8 5/8". Leave 4 1/2" full of cmt.

11-6-06 Install Dryhole Marker.

Plugging of the well bore.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐ , a general permit ☐ or an (attached) alternative OGC approved plan ☐

SIGNATURE Dusty Roach TITLE AREA MANAGER DATE 11-7-06
Type or print name DUSTY ROACH E-mail address: _____ Telephone No. _____

For State Use Only

APPROVED BY Gerry Guye TITLE Deputy Field Inspector DATE DEC 1 2006
Conditions of Approval, if any: District II - Artesia