

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.

NM-70945 LC-067858

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

NM 70945X

8. Well Name and No.

EMPIRE ABO UNIT 133

'M'

9. API Well No.

30.015.22833

10. Field and Pool, or Exploratory Area

EMPIRE ABO

11. County or Parish, State

EDDY NM

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

BP America Production Company

3a. Address

P.O. Box 1089 Eunice NM 88231

3b. Phone No. (include area code)

505.394.1650

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

UL D, N4W, 450' ENL & 1175' FWL
SECTION 11, T18S, R27E

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize ☐ Deepen ☒ Production (Start/Resume) ☐ Water Shut-Off
☐ Alter Casing ☐ Fracture Treat ☐ Reclamation ☐ Well Integrity
☐ Casing Repair ☐ New Construction ☐ Recomplete ☐ Other
☐ Change Plans ☐ Plug and Abandon ☐ Temporarily Abandon
☐ Convert to Injection ☐ Plug Back ☐ Water Disposal

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

TD: 6225' PBID: 6180' PERFS: 5966'-5976', 5998'-6010', 6044'-6064'

Drilled out two CIBPs @ 5987' and 6030' to reopen two lower Abo zones and return well to production, per attached Operations Summary report.

RTP 12/14/06

24 hr. well test: 12/20/06 - 9 bbls. oil, 56 bbls. water, 41 mcf gas.

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Vicki Owens

Title

Administrative Assistant

Date 12/21/06

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Office

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

APPROVED

Date
DEC 28 2006

FREDERICK WRIGHT
PETROLEUM ENGINEER

Operations Summary Report

Legal Well Name: EMPIRE ABO UNIT M #133

Common Well Name: EMPIRE ABO UNIT M #133

Event Name: WORKOVER

Contractor Name: KEY

Rig Name:

Start: 11/27/2006

Spud Date: 5/23/1979

Rig Release:

End: 12/6/2006

Rig Number: 174

Date	From - To	Hours	Task	Code	NPT	Phase	Description of Operations
11/27/2006	14:30 - 17:30	3.00		P		LOWER1	MOBILISE RIG
	17:30 - 18:30	1.00		P		LOWER1	RU
	18:30 - 20:00	1.50		P		LOWER1	TRAVEL TO HOBBS
11/28/2006	05:30 - 06:30	1.00		P		LOWER1	TRAVEL TO OFFICE
	06:30 - 07:00	0.50		P		LOWER1	SAFETY MEETING
	07:00 - 07:15	0.25		P		LOWER1	TRAVEL TO WELLSITE
	07:15 - 08:00	0.75		P		LOWER1	JSA'S
	08:00 - 09:00	1.00		P		LOWER1	KILL WELL
11/29/2006	09:00 - 10:30	1.50		P		LOWER1	NDWH, NUBOP
	10:30 - 15:00	4.50		N	WAIT	LOWER1	WINDY CONDITIONS. SHUT DOWN
	15:00 - 16:30	1.50		P		LOWER1	TRAVEL TO HOBBS
	05:30 - 06:30	1.00		P		LOWER1	TRAVEL TO OFFICE
	06:30 - 07:00	0.50		P		LOWER1	SAFETY MEETING
	07:00 - 07:15	0.25		P		LOWER1	TRAVEL TO LOCATION
	07:15 - 08:00	0.75		P		LOWER1	JSA'S
	08:00 - 10:30	2.50		P		LOWER1	LD TBG
	10:30 - 12:30	2.00		P		LOWER1	PU TBG, CUTRITE SHOE, AND DRILL COLLARS
	12:30 - 13:00	0.50		P		LOWER1	CREW BREAK
	13:00 - 16:30	3.50		P		LOWER1	PU TBG
	16:30 - 18:00	1.50		P		LOWER1	TRAVEL TO HOBBS
	05:30 - 15:30	10.00		N	WAIT	LOWER1	ICE STORM
	05:30 - 06:30	1.00		P		LOWER1	TRAVEL TO OFFICE
	06:30 - 07:00	0.50		P		LOWER1	SAFETY MEETING
12/1/2006	07:00 - 07:15	0.25		P		LOWER1	TRAVEL TO LOCATION
	07:15 - 08:00	0.75		P		LOWER1	JSA'S
	08:00 - 10:30	2.50		N	HMAN	LOWER1	WAIT TO THAW AIR LINES ON RIG
	10:30 - 11:00	0.50		P		LOWER1	PU 10 JTS TO CIBP
	11:00 - 12:00	1.00		P		LOWER1	RU POWER SWIVEL, STAND PIPE, AND DRILL LINE
	12:00 - 12:30	0.50		P		LOWER1	CREW LUNCH
	12:30 - 16:00	3.50		P		LOWER1	DRILL ON CIBP WITH CUTRITE SHOE- NO LUCK
	16:00 - 17:00	1.00		P		LOWER1	TOH TO ABOVE PERFS, LEAVING KILL STRING IN HOLE
	17:00 - 18:30	1.50		P		LOWER1	TRAVEL TO HOBBS
	05:30 - 06:30	1.00		P		LOWER1	TRAVEL TO OFFICE
	06:30 - 07:00	0.50		P		LOWER1	SAFETY MEETING
	07:00 - 07:15	0.25		P		LOWER1	TRAVEL TO LOCATION
	07:15 - 08:00	0.75		P		LOWER1	JSA'S
	08:00 - 09:30	1.50		P		LOWER1	TOH W/ TBG, COLLARS AND SHOE
	09:30 - 11:30	2.00		P		LOWER1	TIH W/ 4 3/4 BIT, COLLARS AND TBG
12/4/2006	11:30 - 15:00	3.50		P		LOWER1	DRILL OUT 2 CIBP'S
	15:00 - 15:30	0.50		P		LOWER1	FLUSH 50 BBLS
	15:30 - 16:30	1.00		P		LOWER1	RD SWIVEL, STANDPIPE, AND DRILL LINE
	16:30 - 17:00	0.50		P		LOWER1	TOH ABOVE PERFS
	17:00 - 18:30	1.50		P		LOWER1	TRAVEL TO HOBBS
	05:30 - 06:30	1.00		P		LOWER1	TRAVEL TO OFFICE
	06:30 - 07:00	0.50		P		LOWER1	SAFETY MEETING
	07:00 - 07:15	0.25		P		LOWER1	TRAVEL TO LOCATION
	07:15 - 08:00	0.75		P		LOWER1	JSA'S
	08:00 - 09:30	1.50		P		LOWER1	TOH W/ TBG
	09:30 - 10:30	1.00		P		LOWER1	LD DC'S AND BIT. PU BHA
	10:30 - 14:00	3.50		P		LOWER1	TIH W/ TBG TO CIBP. PU TBG AND PUSH TO 6178' W/ KB
	14:00 - 14:30	0.50		P		LOWER1	SET TAC
	14:30 - 16:00	1.50		P		LOWER1	NDBOP. NUWH. CHANGE WELLHEAD VALVES
	16:00 - 17:30	1.50		P		LOWER1	TRAVEL TO HOBBS

Operations Summary Report

Rig Number: 174

Printed: 12/7/2006 9:27:29 AM