Submit 3 Copies To Appropriate District	State of New N	Mexico	Form C-103	
Office	Energy, Minerals and Natural Resources		May 27, 2004	
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, witherais and waterar resources		WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210	GL CONSERVATION DIVISION		30-005-63067	
District III	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE X	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		STATE FEE X 6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM			N/A	
87505	S AND DEDODTS ON WELL	· C	7 Lagge Name on Unit	A annument Name
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name Northern Lights	
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other			8. Well Number 1	
2. Name of Operator		Modern 7 2007 men	9. OGRID Number	
Armstrong Energy Corporation	505-625-2222	CEB - BAS	001092	
3. Address of Operator		More 1 200 mm	10. Pool name or Wild	
P.O. Box 1973, Roswell, NM 88202-19	973		Bullseye F	ısselman
4. Well Location				
Unit Letter O: 449 feet from the South line and 2183 feet from the East line				
Section 7	Township 8S	Range 29E		County Chaves
1	1. Elevation (Show whether D	R, RKB, RT, GR, etc.)		
Pit or Below-grade Tank Application or Clo	4068 GR			
Pit type Steel Tanks Depth to Groundwater 600 Distance from nearest fresh water well 2 miles Distance from nearest surface water 2.5 miles				
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK X ALTERING CASING				
TEMPORARILY ABANDON				
PULL OR ALTER CASING				
OTHER:	П	OTHER:		П
13. Describe proposed or completed	d operations. (Clearly state a		give pertinent dates, inc	luding estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
1 02 07 P O H with and a few manner and	at TAC and DO H with tab			
1-03-07 P.O.H. with rods & pump, unseat TAC and P.O.H. with tubing, 5000 # drag. 1-04-07 Found salt, scale and iron sulfide on top of TAC. R.I.H. with casing inspection log, rough spots at 5000' and 2900'.				
1-05-07 T.I.H. with casing scraper and test tubing to 5000 psi, tag at 7015'.				
1-08-07 T.I.H. with packer and RBP, test casing at 1500-2000 psi, o.k.				
1-09-07 Swab down casing, no fluid entry.				
1-10-07 P.O.H. with tools, R.I.H. with tubing, rods and pump. S.N. at 6977', started pumping at 5:00 PM. 1-11-07 to 2-5-07 Testing, 2-5-07 69 BO, 8 BW.				
Final report, returned to production.				
i mai report, retained to production.				
I hereby certify that the information above				
grade tank has been/will be constructed or close	ed according to NMOCD guideline	s 🔲, a general permit 🔲 o	r an (attached) alternative O	CD-approved plan
SIGNATURE /	TITLE	Vice President-Opera	ntions DAT	E 2-6-07
-/ 3 - /)				
Type or print name Bruce A. Stubbs	E-mail address:	bastubbs@zianet.com	Telephone No. 50	5-625-2222
For State Use Only				1 1
APPROVED BY: Accepted for Conditions of Approval (if any):	record - NMOCD TITLE		DAT	TE 2/1/07
Conditions of Approval (if any).				