OCD-ARTESIA

Form 3160-5 (April 2004)

Month -MAR 19 OCD - ARTE

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

5. Lease Serial No.

Month - Yo	ו חטווטס ו	NOTICES AND RE	PORTS ON WEL	LS	NM-38464		
MAR 192	9 2007 Do not use this form for proposals to drill or to re-enter and				6. If Indian, Allottee or Tribe Name		
CD - ARTES	A, NM abandoned well. Use Form 3160-3 (APD) for such proposals.						
Par Mark	SUBMIT IN TRIPLICATE- Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No.		
of the construction of the	1. Type of Well X Oil Well						
	XIOH WEH Gas WEH CLOTHER				8. Well Name and No.		
	2. Name of Operator Pogo Producing Company				Pure Gold A Federal # 13 9. API Well No.		
	3a. Address 3b. Phone No. (include area code)			30-015- 35306			
-	P. 0. Box 10340, Midl	432-685-8100		10. Field and Pool, or Exploratory Area			
	4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Sand Dunes Delaware West			
	1860' FNL & 1980' FEL, Section 21, T23S, R31E				11. County or Parish, State		
	1860' FNL & 1980' FEL, Section 21, T23S, R31E			Eddy County, NM			
•	12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, RE				EPORT, OR OTHER DATA		
	TYPE OF SUBMISSION TYPE OF ACTION						
		Acidize	Deepen	Production (Star	Start/Resume) Water Shut-Off		
	× Notice of Intent	XX Alter Casing	Fracture Treat	Reclamation	Well Integrity		
	Subsequent Report	Casing Repair Change Plans	New Construction	Recomplete	Other		
	Final Abandonment Notice	Convert to Injection	Plug and Abandon Plug Back	Temporarily Aba Water Disposal	indon		
	Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)						
Hole Size	_		Setting Depth	Cement Qua			
26" 17-1/2"	20" Sched 10 13-3/8" H-40	53# 48#	40' 800'	650 sks circu	-mix grouted		
11"	8-5/8" J-55	32#	4100'	1300 sks circ			
7-7/8"	5-1/2" J-55	17#	Surf-1000'		sks "C" 14.1 ppg, circ		
7-7/8"	5-1/2" J-55	15.5#	1000'-6000'		o sks "C" 12.8 ppg, circ		
7-7/8"	5-1/2" J-55	17#	6000'-8200'		sks "C" 12.8 ppg, circ		
SEE	ATTACHED FO	מ		Stage tools (@ 3900' & 6000'		
CON	DITIONS OF	K					
CONDITIONS OF APPROVATION of Salt @ 860', Basal Anhydrite @ 4024' & Delaware Lime @ 425							
=	14. Thereby certify that the foreg			-			
	Name (Printed/Typed) Cathy Wright	. U		Sr. Eng Tec	:h		
_			Title	3			
	Signature	Mucht	Date	03/09/0	7		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE APPROVEL							

Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or representations as to any matter within its jurisdiction.

Pure Gold "A" Federal #13 Pogo Producing Company March 13, 2007 Conditions of Approval

- 1. 20" Sched 10 53# casing to be cemented to surface with ready mix.
- 2. 13-3/8" H-40 48# casing to be set a minimum of 25 feet into the Rustler Anhydrite at approximately 800 feet and above the salt.
- 3. 8-5/8" J-55 32# casing to be set at least 100 feet below and not more than 600 feet below the base of the salt at approximately 4100 feet.

WWI 031307