

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Oil Cons.
N.M. DIV-Dist. 2
1301 W. Grand Avenue
Artesia, NM 88210

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

Oil ☐ Gas ☐
☒ Well ☐ Well ☐ Other

2. Name of Operator

STRATA PRODUCTION COMPANY

3. Address and Telephone No.

P. O. Box 1030
Roswell, New Mexico 88202-1030

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FNL & 660' FEL
Section 21-7S-34E

5. Lease Designation and Serial No.

NM-84732

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Sunrise Federal #1

9. API Well No.

30-041-20577

10. Field and Pool, or Exploratory Area

Chaveroo San Andres

11. County or Parish, State

Roosevelt County, New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input checked="" type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> OTHER	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

08/13/03: MI to location.

08/14/03: Notify BLM. RU. POOH w/rods. High winds, close in well.

08/15/03: POOH w/ rods. NUBOP. Unset Anchor. Storm, close in well.

08/18/03: POOH w/tbg. TIH w/5 1/2" CIBP & set at 4325'. TIH & circ 10# mud. Spot 10 sxs cmt on top. POOH. Close in well.

08/19/03: NDWH. Freepoint csg. Cut csg @ 2150'. Lay down 51 jnts 5 1/2" csg. TIH & spot 75 sxs cmt @ 2200' - 2074', Tagged. POOH. Close in well.

08/20/03: TIH & tag cmt @ 2074'. Reset plug w/25 sxs @ 2074' - 2000'. POOH. Spot 35 sxs @ 1000' - 900'. POOH. Spot 25 sxs @ 62' to surface. Dig out & cut off WH & anchors. RD. Install dry hole marker. Move out.

SPC will rip and reseed per BLM guidelines when mother nature gives us some moisture.
Final Abandonment Notice will be submitted when the above is completed.
Equipment has already been pulled off location.

14. I hereby certify that the foregoing is true and correct

Signed Kurt M. Britt

Title Production Records

Date 08/28/03

(This space for Federal or State office use)

Approved by ACE

Title PE

Date 9/3/03

Conditions of approval, if any: