

30.015-05128



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON
Governor
Joanna Prukop
Cabinet Secretary

Mark E. Fesmire, P.E.
Director
Oil Conservation Division

16-Apr-07

MERIT ENERGY CO
13727 Noel Road, Suite 500
Dallas TX 75240-

LOV NO. 0210207

LETTER OF VIOLATION and SHUT-IN DIRECTIVE Failed Mechanical Integrity Test

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

H E WEST B No.016			30-015-05056-00-00 M-3-17S-31E
Active Injection - (All Types)			
Test Date: 4/10/2007	Permitted Injection PSI:	Actual PSI:	
Test Reason: Annual IMIT	Test Result: F	Repair Due: 7/14/2007	
Test Type: Bradenhead Test	FAIL TYPE: Operational Violation	FAIL CAUSE:	
Comments on MIT: No injection line - unable to test..			
H E WEST A No.005			30-015-05064-00-00 J-4-17S-31E
Active Injection - (All Types)			
Test Date: 4/10/2007	Permitted Injection PSI:	Actual PSI:	
Test Reason: Annual IMIT	Test Result: F	Repair Due: 7/14/2007	
Test Type: Bradenhead Test	FAIL TYPE: Permit Violation	FAIL CAUSE:	
Comments on MIT: Injection pressure over limit			
J L KEEL B No.009			30-015-05076-00-00 H-5-17S-31E
Active Injection - (All Types)			
Test Date: 4/4/2007	Permitted Injection PSI:	Actual PSI: 1940	
Test Reason: Annual IMIT	Test Result: F	Repair Due: 7/8/2007	
Test Type: Bradenhead Test	FAIL TYPE: Permit Violation	FAIL CAUSE:	
Comments on MIT: Injection pressure over limit			

J L KEEL B No.011**30-015-05077-00-00**

N-5-17S-31E

Expired TA Injection - (All Types)
Test Date: 4/10/2007 Permitted Injection PSI: Actual PSI:
Test Reason: Annual IMIT Test Result: F Repair Due: 7/14/2007
Test Type: Bradenhead Test FAIL TYPE: Operational Violation FAIL CAUSE:
Comments on MIT: Unable to test. TA expired on 02-10-2007

J L KEEL B No.023**30-015-05086-00-00**

N-6-17S-31E

Active Injection - (All Types)
Test Date: 4/4/2007 Permitted Injection PSI: Actual PSI: 1750
Test Reason: Annual IMIT Test Result: F Repair Due: 7/8/2007
Test Type: Bradenhead Test FAIL TYPE: Permit Violation FAIL CAUSE:
Comments on MIT: Injection pressure over limit

J L KEEL A No.004**30-015-05092-00-00**

K-7-17S-31E

Active Injection - (All Types)
Test Date: 4/4/2007 Permitted Injection PSI: Actual PSI:
Test Reason: Annual IMIT Test Result: F Repair Due: 7/8/2007
Test Type: Bradenhead Test FAIL TYPE: Permit Violation FAIL CAUSE:
Comments on MIT: Injection pressure over limit

J L KEEL B No.003**30-015-05104-00-00**

N-8-17S-31E

Active Injection - (All Types)
Test Date: 4/5/2007 Permitted Injection PSI: Actual PSI: 1760
Test Reason: 5-year Test Test Result: F Repair Due: 7/9/2007
Test Type: Std. Annulus Pres. Test FAIL TYPE: Permit Violation FAIL CAUSE:
Comments on MIT: Injection pressure over limit

H E WEST B No.024**30-015-05128-00-00**

A-10-17S-31E

Active Injection - (All Types)
Test Date: 4/10/2007 Permitted Injection PSI: Actual PSI:
Test Reason: Annual IMIT Test Result: F Repair Due: 7/14/2007
Test Type: Bradenhead Test FAIL TYPE: Casing FAIL CAUSE:
Comments on MIT: Continuous flow from casing valve indicating possible casing leak.

TURNER B No.030**30-015-05186-00-00**

P-17-17S-31E

Active Injection - (All Types)
Test Date: 4/3/2007 Permitted Injection PSI: Actual PSI: 1500
Test Reason: Annual IMIT Test Result: F Repair Due: 7/7/2007
Test Type: Bradenhead Test FAIL TYPE: Permit Violation FAIL CAUSE:
Comments on MIT: Injection pressure over limit

C A RUSSELL No.006**30-015-05219-00-00**

C-18-17S-31E

Active Injection - (All Types)
Test Date: 4/9/2007 Permitted Injection PSI: Actual PSI:
Test Reason: Annual IMIT Test Result: F Repair Due: 7/13/2007
Test Type: Bradenhead Test FAIL TYPE: Permit Violation FAIL CAUSE:
Comments on MIT: Injection pressure over limit

TURNER A No.014**30-015-05239-00-00**

E-19-17S-31E

Active Injection - (All Types)
Test Date: 4/3/2007 Permitted Injection PSI: Actual PSI: 1800
Test Reason: Annual IMIT Test Result: F Repair Due: 7/7/2007
Test Type: Bradenhead Test FAIL TYPE: Casing FAIL CAUSE:
Comments on MIT: Continuous water flow from casing valve indicating possible hole in casing.

TURNER B No.067**30-015-05300-00-00**

L-20-17S-31E

Active Injection - (All Types)

Test Date:	4/5/2007	Permitted Injection PSI:		Actual PSI:	
Test Reason:	Annual IMIT	Test Result:	F	Repair Due:	7/9/2007
Test Type:	Bradenhead Test	FAIL TYPE:	Casing	FAIL CAUSE:	
Comments on MIT:	No injection line connected, unable to test. Continuous flow from casing valve indicating a casing leak.				

TURNER B No.054**30-015-05443-00-00**

F-29-17S-31E

Active Injection - (All Types)

Test Date:	4/5/2007	Permitted Injection PSI:		Actual PSI:	1650
Test Reason:	Annual IMIT	Test Result:	F	Repair Due:	7/9/2007
Test Type:	Bradenhead Test	FAIL TYPE:	Casing	FAIL CAUSE:	
Comments on MIT:	Continuous flow from casing valve indicating possible casing leak.				

MAX FRIESS MA No.001**30-015-05459-00-00**

B-30-17S-31E

Active Injection - (All Types)

Test Date:	4/5/2007	Permitted Injection PSI:		Actual PSI:	
Test Reason:	Annual IMIT	Test Result:	F	Repair Due:	7/9/2007
Test Type:	Bradenhead Test	FAIL TYPE:	Permit Violation	FAIL CAUSE:	
Comments on MIT:	Injection pressure over limit. Injection line under repair.				

C A RUSSELL No.011**30-015-21258-00-00**

C-18-17S-31E

Active Injection - (All Types)

Test Date:	4/3/2007	Permitted Injection PSI:		Actual PSI:	
Test Reason:	Annual IMIT	Test Result:	F	Repair Due:	7/7/2007
Test Type:	Bradenhead Test	FAIL TYPE:	Permit Violation	FAIL CAUSE:	
Comments on MIT:	Injection pressure over limit				

J L KEEL A No.016**30-015-25423-00-00**

F-7-17S-31E

Active Injection - (All Types)

Test Date:	4/4/2007	Permitted Injection PSI:		Actual PSI:	
Test Reason:	Annual IMIT	Test Result:	F	Repair Due:	7/8/2007
Test Type:	Bradenhead Test	FAIL TYPE:	Permit Violation	FAIL CAUSE:	
Comments on MIT:	Injection pressure over limit				

J L KEEL B No.040**30-015-25940-00-00**

E-6-17S-31E

Active Injection - (All Types)

Test Date:	4/9/2007	Permitted Injection PSI:		Actual PSI:	1850
Test Reason:	Annual IMIT	Test Result:	F	Repair Due:	7/13/2007
Test Type:	Bradenhead Test	FAIL TYPE:	Permit Violation	FAIL CAUSE:	
Comments on MIT:	Injection pressure over limit				

H E WEST B No.036**30-015-25995-00-00**

H-9-17S-31E

Active Injection - (All Types)

Test Date:	4/10/2007	Permitted Injection PSI:		Actual PSI:	
Test Reason:	Annual IMIT	Test Result:	F	Repair Due:	7/14/2007
Test Type:	Bradenhead Test	FAIL TYPE:	Permit Violation	FAIL CAUSE:	
Comments on MIT:	Injection pressure over limit				

J L KEEL A No.030**30-015-28306-00-00**

O-7-17S-31E

Active Injection - (All Types)

Test Date:	4/4/2007	Permitted Injection PSI:		Actual PSI:	
Test Reason:	Annual IMIT	Test Result:	F	Repair Due:	7/8/2007
Test Type:	Bradenhead Test	FAIL TYPE:	Permit Violation	FAIL CAUSE:	
Comments on MIT:	Injection pressure over limit				

Active Injection - (All Types)

J-19-17S-31E

Test Date:	4/5/2007	Permitted Injection PSI:	Actual PSI:
Test Reason:	Annual IMIT	Test Result:	F
Test Type:	Bradenhead Test	FAIL TYPE:	Operational Violation
Comments on MIT:	Injection line under repair. Unable to test.		

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,



Artesia OCD District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.