Submit 3 Copies To Appropriate District	State of New Mexico			Form C-103
Office District I	Energy, Minerals and Natural Resources			Revised June 10, 2003
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	015 04563
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type	0-015-04562
District III	1220 South St. Francis Dr.		STATE	FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & G	
1220 S. St. Francis Dr., Santa Fe, NM				E-9262
87505 SUNDRY NOTIC	CES AND REPORTS ON WELLS		7. Lease Name (or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			North Benson Queen Unit	
PROPOSALS.) 1. Type of Well:	\(\begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\		8. Well Number	
· · · ·	Other Injection/Well		39	
2. Name of Operator	© 2003 ST		9. OGRID Number	
United Oil & Minerals Limited Partnership ECEIVED			5300	
3. Address of Operator			10. Pool name or Wildcat	
4. Well Location	ank Dr., Austin, TX 78746		Que	en - Grayburg
4. Well Location				
Unit Letter F: 1650 feet from the North line and 1980 feet from the West line				
Section 3 <u>4</u>			NMPM <u>Eddy</u>	County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3460' GR				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF IN			SEQUENT RE	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR		ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	HANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AN	ND 🗆	
OTHER:		OTHER:		П
			d give pertinent da	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
Run Mechanical Integrity test – test at min. 500 psi pressure for 30 minutes; record with a chart and give notice to OCD for witness.				
industrial integrity test—test at him. 500 psi pressure for 50 initiates, record with a chart and give notice to OCD for withess.				
0		3.7 . · · · ·		ARM WAC
Operator will use current packer to Notify OCD 24 hours				
isolate perfs. as per Ms. Patton on 9- 15-03 via phone call prior to test. 748-1283				
15-03 via phone call.		Paron vo		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE MIC ()	Die TITLE D	egulatory Coordin	atow	DATE <u>9/10/2003</u>
SIGNATURE / May Cent	mile k			
Type or print name Mary Curli	ss Patton E-mail addre	ess: mpattan@uo	Tele	phone No. (512) 328-8184
(This space for State use)	\mathcal{U}	July 8	SO PADI	PROVED SED : 6 200
APPPROVED BY Conditions of approval, if any:	TITLE) Ari	THAYEU SEP : 6 200