


Submit 3 Copies To Appropriate District
Office:
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505



API NO.

30-01-33654

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
Barclay Federal

8. Well Number

21

9. OGRID Number

8041

10. Pool name or Wildcat
S. Livingston Ridge Delaware

SUNDRY NOTICES AND REPORTS ON WELLS:

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

Forest Oil Corporation

3. Address of Operator

707 17th Street, Suite 3600, Denver, Colorado

4. Well Location

Unit Letter: F feet from the 2000 line and North feet and 2180 from the West line

Section 12 Township 23S Range 31E NMPM County Eddy

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3481 GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls: Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

OTHER: Tubing Repair ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

5-29-07 RU PU unhung well head. POH 126-1.2 F.G. rods & 40.1" rods to body break, run paraffin knives to 2500'. Run swab cubs to 2500'.

5-30-07 ND well head flange POH tbg to body rod break. POH rods * pmp. POH tbg & tally 229 jts 2-7/8" tbg out of hole. Send pmp to R&R, RBIH 3 jts w/BP, 4' sub & S.N.- 8 jts 2-7/8".

5-31-07 RU Bo monk tbg tester. Test tbg BIH fine no hole, could have been tbg collar leak. RD tbg tester. Change tbg tools, to hook rods. RBIH pmp, K-bars, rods, replace 26-K shear tool, replace 1-1" rod & tac 2-7/8" seat nipple, M&S load tbg w/27 bbls wtr, press to 500# psi hold good.

6-1-07 Rig down PU clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Cindy Bush TITLE Sr. Regulatory Tech DATE 6-15-07

Type or print name Cindy Bush E-mail address: cabush@forestoil.com Telephone No. 303-812-1554

For State Use Only

APPROVED BY: _____ TITLE _____ DATE _____

Conditions of Approval (if any):