

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED  
OMB NO. 1004-0135  
Expires: November 30, 2000

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

JUL 30 2007

SUBMIT IN TRIPLICATE - Other instructions on reverse side

5. Lease Serial No.
NM-36975
6. If Indian, Allottee or Tribe Name
7. If Unit or CA/Agreement, Name and/or No.
8. Well Name and No.
Mossberg Federal #1Y
9. API Well No.
30-015-35533
10. Field and Pool, or Exploratory Area
Undsg. Malaga Morrow
11. County or Parish, State
Eddy NM

1. Type of Well	
<input type="checkbox"/> Oil Well	<input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other
2. Name of Operator	
OXY USA WTP LP 192463	
3a. Address	3b. Phone No. (include area code)
P.O. Box 50250, Midland, TX 79710-0250	432-685-5717
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	
725 FSL 809 FWL SWSW(M) Sec 28 T24S R28E	

## 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input checked="" type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other <u>Pressure</u>
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	<u>test 7" csq</u>
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

RU 6/28/07, Pressure test 7" and 9-5/8" annulus to 550# for 30 minutes. Test witnessed and approved by BLM, chart attached.

Pressure test the annulus between the 7" and 9-5/8" casing stings. The pressure test will be 500 psig, held for 30 minutes and recorded on a chart. BLM will witness the test. A successful test will fulfill the requirements under the incident of non-compliance and no perforation and circulation of cement at +/- 2400' will be required as agreed to today by OXY and the Carlsbad, NM-BLM. The casing and cementing history will be reviewed upon final abandonment of the well.

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) David Stewart	Title Sr. Regulatory Analyst
	Date 7/3/07

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

JUL 26 2007

Approved by /s/ Don Peterson	Title FIELD MANAGER	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office CARLSBAD FIELD OFFICE

