Submit 3 Copies To Appropriate District Office	State of New Me Energy, Minerals and Natur		Form C-103 May 27, 2004
" <u>District I</u> 1625 N. French Dr. 480bbs, NM 88240	Energy, witherars and water	iai Resources	WELL API NO.
District II 1301 W. Grand Ave., Autesia, NM 882 10	OIL CONSERVATION	DIVISION	30-015-21637
District III	1220 South St. Fran	cis Dr.	5. Indicate Type of Lease STATE ☐ FEE ☒
1000 Rio Brazos Rd., Azice, NY 187410 District IV	Santa Fe, NM 87	505	6. State Oil & Gas Lease No.
1220 S St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Smith EB	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other		8. Well Number	
	Gas wen Onici		1
2. Name of Operator			9. OGRID Number
Yates Petroleum Corporation 3. Address of Operator		10	025575 10. Pool name or Wildcat
105 S. 4 th Street, Artesia, N	NM 88210 AUG	13 2007	Eagle Creek S. A.
4. Well Location	¥		
Unit Letter F:	1650 feet from the North	line and	1650 feet from the West line
Section 13	Township 17S Rar		NMPM Eddy County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3466'GR			
Pit or Below-grade Tank Application 🔲 o			
Pit type Depth to Groundwate	r Distance from nearest fresh wa	ater well Dis	tance from nearest surface water
1			
Pit Liner Thickness: mil			nstruction Material
12. Check A	Below-Grade Tank: Volume Appropriate Box to Indicate N	bbls; Co	Report or Other Data
12. Check A	Below-Grade Tank: Volume Appropriate Box to Indicate N TENTION TO:	bbls; Co ature of Notice,	Report or Other Data SEQUENT REPORT OF:
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK	Below-Grade Tank: Volume Appropriate Box to Indicate N TENTION TO: PLUG AND ABANDON	bbls; Co ature of Notice, SUB: REMEDIAL WOR	Report or Other Data SEQUENT REPORT OF: K
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON	Below-Grade Tank: Volume Appropriate Box to Indicate N TENTION TO: PLUG AND ABANDON CHANGE PLANS	bbls; Co ature of Notice, SUB: REMEDIAL WORL COMMENCE DRI	Report or Other Data SEQUENT REPORT OF: K
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	Below-Grade Tank: Volume Appropriate Box to Indicate N TENTION TO: PLUG AND ABANDON	bbls; Co ature of Notice, SUB: REMEDIAL WORL COMMENCE DRI CASING/CEMEN	Report or Other Data SEQUENT REPORT OF: K
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp	Below-Grade Tank: Volume Appropriate Box to Indicate N ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	ature of Notice, SUB: REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: pertinent details, and	Report or Other Data SEQUENT REPORT OF: K ALTERING CASING DELING OPNS. PLUG AND ABANDON DELING DISTRICT DELING D
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp	Below-Grade Tank: Volume Appropriate Box to Indicate N ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	ature of Notice, SUB: REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: pertinent details, and	Report or Other Data SEQUENT REPORT OF: K ALTERING CASING LLING OPNS. PLUG AND ABANDON TOOR TOO TOO TOO TOO TOO TOO TOO TOO TO
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion.	Below-Grade Tank: Volume Appropriate Box to Indicate N TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deted operations. (Clearly state all pork). SEE RULE 1103. For Multiple	ature of Notice, SUB: REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Description of the completions: At	Report or Other Data SEQUENT REPORT OF: K ALTERING CASING DELING OPNS. PLUG AND ABANDON DELING DISTRICT DELING D
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. Yates Petroleum Corporation plans to	Appropriate Box to Indicate N TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deted operations. (Clearly state all pork). SEE RULE 1103. For Multiple to plug and abandon this well as follows.	ature of Notice, SUB: REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Dertinent details, and the Completions: Attorines	Report or Other Data SEQUENT REPORT OF: K ALTERING CASING DELING OPNS. PLUG AND ABANDON DELING OPNS
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion.	Below-Grade Tank: Volume Appropriate Box to Indicate N TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deted operations. (Clearly state all pork). SEE RULE 1103. For Multiple to plug and abandon this well as foll TAC, S/N, perf sub, mud joint with	ature of Notice, SUB: REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Dertinent details, and the Completions: Attorines	Report or Other Data SEQUENT REPORT OF: K ALTERING CASING DELING OPNS. PLUG AND ABANDON DELING OPNS
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. Yates Petroleum Corporation plans t 1. TOOH with tubing and lay down 2. Set a 4-1/2" CIBP at 1356' with 3 3. Spot a 100' cement plug (25 sx) a	Below-Grade Tank: Volume Appropriate Box to Indicate N ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deted operations. (Clearly state all pork). SEE RULE 1103. For Multiple or plug and abandon this well as followed the pork of the property of the propert	ature of Notice, SUB: REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Description details, and all built plug and all built plug.	Report or Other Data SEQUENT REPORT OF: K ALTERING CASING DELING OPNS. PLUG AND ABANDON DELING OPNS
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. Yates Petroleum Corporation plans t 1. TOOH with tubing and lay down 2. Set a 4-1/2" CIBP at 1356' with 3 3. Spot a 100' cement plug (25 sx) a 4. Spot a 100' cement plug (25 sx) a	Appropriate Box to Indicate N ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL leted operations. (Clearly state all pork). SEE RULE 1103. For Multiple TAC, S/N, perf sub, mud joint with 35' cement on top. across the shoe from 1162'-1262'. Takeross the shoe from 275'-375'. Tagent and all ports are so that the shoe from 275'-375'. Tagent are so that the shoe from 275'-375'.	ature of Notice, SUB: REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Description details, and all built plug and all built plug.	Report or Other Data SEQUENT REPORT OF: K ALTERING CASING DELING OPNS. PLUG AND ABANDON DELING OPNS
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. Yates Petroleum Corporation plans t 1. TOOH with tubing and lay down 2. Set a 4-1/2" CIBP at 1356' with 3 3. Spot a 100' cement plug (25 sx) a	Below-Grade Tank: Volume Appropriate Box to Indicate N ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL □ leted operations. (Clearly state all pork). SEE RULE 1103. For Multiple to plug and abandon this well as follows: TAC, S/N, perf sub, mud joint with as ceross the shoe from 1162'-1262'. The across the shoe from 275'-375'. Tag from 100' to surface. Tag plug.	SUB: REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Description details, and le Completions: At le Completions de la plug and all brag plug. Explus plug.	Report or Other Data SEQUENT REPORT OF: K ALTERING CASING DELING OPNS. PLUG AND ABANDON DELING OPNS
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. Yates Petroleum Corporation plans t 1. TOOH with tubing and lay down 2. Set a 4-1/2" CIBP at 1356' with 3 3. Spot a 100' cement plug (25 sx) a 4. Spot a 100' cement plug (25 sx) a 5. Spot a 100' cement plug (25 sx) a	Below-Grade Tank: Volume Appropriate Box to Indicate N ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL □ leted operations. (Clearly state all pork). SEE RULE 1103. For Multiple to plug and abandon this well as follows: TAC, S/N, perf sub, mud joint with as ceross the shoe from 1162'-1262'. The across the shoe from 275'-375'. Tag from 100' to surface. Tag plug.	SUB: REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Description details, and le Completions: At le Completions de la plug and all brag plug. Explus plug.	Report or Other Data SEQUENT REPORT OF: K ALTERING CASING DELING OPNS. PLUG AND ABANDON DELING OPNS
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Yates Petroleum Corporation plans t 1. TOOH with tubing and lay down 2. Set a 4-1/2" CIBP at 1356' with 3 3. Spot a 100' cement plug (25 sx) a 4. Spot a 100' cement plug (25 sx) a 5. Spot a 100' cement plug (25 sx) a 6. Cut off wellhead and install mark	Appropriate Box to Indicate N TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL leted operations. (Clearly state all pork). SEE RULE 1103. For Multiple to plug and abandon this well as follows: TAC, S/N, perf sub, mud joint with 35' cement on top. across the shoe from 1162'-1262'. Tagences the shoe from 275'-375'. Tagence are and clean up location as per regular.	ature of Notice, SUB: REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Description details, and the Completions: At the completion of	Report or Other Data SEQUENT REPORT OF: K ALTERING CASING DELING OPNS. PLUG AND ABANDON DELING OPNS
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. Yates Petroleum Corporation plans t 1. TOOH with tubing and lay down 2. Set a 4-1/2" CIBP at 1356' with 3 3. Spot a 100' cement plug (25 sx) a 4. Spot a 100' cement plug (25 sx) a 5. Spot a 100' cement plug (25 sx) a	Appropriate Box to Indicate N TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL leted operations. (Clearly state all pork). SEE RULE 1103. For Multiple to plug and abandon this well as follows: TAC, S/N, perf sub, mud joint with 35' cement on top. across the shoe from 1162'-1262'. Tagences the shoe from 275'-375'. Tagence are and clean up location as per regular.	ature of Notice, SUB: REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Description details, and the Completions: At the completion of	Report or Other Data SEQUENT REPORT OF: K ALTERING CASING DELING OPNS. PLUG AND ABANDON DELING OPNS

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .

SIGNATURE


TITLE Regulatory Compliance Supervisor DATE August 10, 2007

Type or print name For State Use Only APPROVED BY:

Conditions of Approval (if any):

FIELD: Eagle Creek WELL NAME: Smith EB #1 **LOCATION**: 1650' FNL & 1650' FWL of Section 13-17S-25E Eddy Co., NM **GL**: 3,466' ZERO: **KB**: 3,479' **CASING PROGRAM SPUD DATE**: 10/1/75 **COMPLETION DATE**: 11/5/75 **COMMENTS**: API No.: 30-015-21637 10-3/4" 32# J55 325' 1212' 7" 20# J55 10-3/4" @ 325' w/ 250 sx 5-1/2" 14# J55 0-1,008' 14-3/4" fell back, filled to surface Hole 4-1/2" 9.5# J55 1,008-1,540' 1,540' with 1 yard of ready mix. **Before TOPS** 9-1/2" Hole SA 776' 7" @ 1,212' w/500 sx. 1"ed to surface w/ 275 sx 6-1/4" Hole SA Yeso perfs: 1,406-1,464' (28) Not to Scale 5-1/2" to 1,008' then finished with 7/17/07 4-1/2" from 1,008-1,540' w/150 sx Moss (Circ)

TD: 1,540'



TD: 1,540'