Submit 3 Copies To Appropriate District Office	State of New Me	xico		Form C-103
District I	Energy, Minerals and Natu	ral Resources		Revised June 10, 2003
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO. 30-015-10154		
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease		
District III 1220 South St. Francis Dr.		STATE	FEE	
District IV	Santa Fe, NM 87	7505	6. State Oil & Gas	
1220 S. St. Francis Dr., Santa Fe, NM]	E-9262
87505 SUNDRY NOTIC	ES AND REPORTS ON WELLS	1	7. Lease Name or	Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				son Queen Unit
DIFFERENT RESERVOIR. USE "APPLICA" PROPOSALS.)	ATION FOR PERMIT" (FORM C-101) FO	M.STICH V		
1. Type of Well:),	8. Well Number	
Oil Well Gas Well	Other Injection Well	Elm A		27
2. Name of Operator	9:19	46 M. C. C. C.	9. OGRID Numbe	er
	Minerals Limited Partnership	2,00,00		5300
3. Address of Operator	1/2	Kr. K	10. Pool name or	
4. Well Location	ank Dr., Austin, TX 78746	· Offin	Queen	- Grayburg
4. Well Location		1016819910 line and		
Unit Letter P :	660 feet from the South	line and	feet from th	e East line
Section <u>29</u>				ounty
The state of the s	11. Elevation (Show whether DR)	
	3414			5152-E- +-1
	ppropriate Box to Indicate N			
NOTICE OF INT			SEQUENT REF	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	к <u></u>	ALTERING CASING
		COMMENCE DD		DI 110 AND
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	_	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS MULTIPLE COMPLETION	CASING TEST AI		ABANDONMENT
	MULTIPLE	CASING TEST AI	ND 🗆	ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AI CEMENT JOB OTHER: Te	nporarily!	Aband.
OTHER: 13. Describe proposed or complet of starting any proposed work.	MULTIPLE COMPLETION	CASING TEST AI CEMENT JOB OTHER: Texpertinent details, an	nporarily divergence date	ABANDONMENT Aband. s, including estimated date
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete	MULTIPLE COMPLETION cted operations. (Clearly state all	CASING TEST AI CEMENT JOB OTHER: Texpertinent details, an	nporarily divergence date	ABANDONMENT Aband. s, including estimated date
OTHER: 13. Describe proposed or complet of starting any proposed work.	MULTIPLE COMPLETION eted operations. (Clearly state all k). SEE RULE 1103. For Multip	CASING TEST AI CEMENT JOB OTHER: Tex pertinent details, an le Completions: Ai	nporarily d give pertinent date tach wellbore diagra	ABANDONMENT A band. s, including estimated date m of proposed completion ding test. Well records
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Mechanical Integrity test was run show that the packer is set at 254	MULTIPLE COMPLETION eted operations. (Clearly state all k). SEE RULE 1103. For Multip	CASING TEST AI CEMENT JOB OTHER: Tex pertinent details, an le Completions: Ai	nporarily d give pertinent date tach wellbore diagra	ABANDONMENT A band. s, including estimated date m of proposed completion ding test. Well records
OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. Mechanical Integrity test was run show that the packer is set at 254	MULTIPLE COMPLETION cted operations. (Clearly state all k). SEE RULE 1103. For Multip 9-11-03 with proper notice to OC4' on plastic lined 2-3/8" tubing in	CASING TEST AI CEMENT JOB OTHER: Tev pertinent details, an le Completions: At 2D for witness. See a 4-1/2" casing – TI	nporarily d give pertinent date tach wellbore diagra	ABANDONMENT A band. s, including estimated date m of proposed completion ding test. Well records
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Mechanical Integrity test was run show that the packer is set at 254	MULTIPLE COMPLETION cted operations. (Clearly state all k). SEE RULE 1103. For Multip 9-11-03 with proper notice to OC4' on plastic lined 2-3/8" tubing in	CASING TEST AI CEMENT JOB OTHER: Tey pertinent details, an le Completions: At CD for witness. See 14-1/2" casing — TI ad Status approved	nporarily d give pertinent date tach wellbore diagra	ABANDONMENT A band. s, including estimated date m of proposed completion ding test. Well records
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Mechanical Integrity test was run show that the packer is set at 254	MULTIPLE COMPLETION cted operations. (Clearly state all k). SEE RULE 1103. For Multip 9-11-03 with proper notice to OC4' on plastic lined 2-3/8" tubing in	CASING TEST AI CEMENT JOB OTHER: Tey pertinent details, an le Completions: At CD for witness. See 14-1/2" casing — TI ad Status approved	nporarily d give pertinent date tach wellbore diagra	ABANDONMENT A band. s, including estimated date m of proposed completion ding test. Well records
OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. Mechanical Integrity test was run show that the packer is set at 254 2664'.	MULTIPLE COMPLETION cted operations. (Clearly state all k). SEE RULE 1103. For Multip 9-11-03 with proper notice to OC4' on plastic lined 2-3/8" tubing in	CASING TEST AI CEMENT JOB OTHER: Tev pertinent details, an le Completions: At D for witness. See 14-1/2" casing – TI ad Status approved	d give pertinent date tach wellbore diagral attached chart record is 3215'. Perforation	ABANDONMENT A band. s, including estimated date m of proposed completion ding test. Well records ons are from 2635' to
OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. Mechanical Integrity test was run show that the packer is set at 254 2664'.	MULTIPLE COMPLETION cted operations. (Clearly state all k). SEE RULE 1103. For Multip 9-11-03 with proper notice to OC4' on plastic lined 2-3/8" tubing in	CASING TEST AI CEMENT JOB OTHER: Tev pertinent details, an le Completions: At D for witness. See 14-1/2" casing – TI ad Status approved	d give pertinent date tach wellbore diagral attached chart record is 3215'. Perforation	ABANDONMENT A band. s, including estimated date m of proposed completion ding test. Well records ons are from 2635' to
OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. Mechanical Integrity test was run show that the packer is set at 254 2664'.	MULTIPLE COMPLETION cted operations. (Clearly state all k). SEE RULE 1103. For Multip 9-11-03 with proper notice to OC4' on plastic lined 2-3/8" tubing in	CASING TEST AI CEMENT JOB OTHER: Tev pertinent details, an le Completions: At D for witness. See 14-1/2" casing – TI ad Status approved	d give pertinent date tach wellbore diagral attached chart record is 3215'. Perforation	ABANDONMENT A band. s, including estimated date m of proposed completion ding test. Well records ons are from 2635' to
OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. Mechanical Integrity test was run show that the packer is set at 254 2664'.	MULTIPLE COMPLETION cted operations. (Clearly state all k). SEE RULE 1103. For Multip 9-11-03 with proper notice to OC4' on plastic lined 2-3/8" tubing in	CASING TEST AI CEMENT JOB OTHER: Tev pertinent details, an le Completions: At D for witness. See 14-1/2" casing – TI ad Status approved	d give pertinent date tach wellbore diagral attached chart record is 3215'. Perforation	ABANDONMENT A band. s, including estimated date m of proposed completion ding test. Well records ons are from 2635' to
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Mechanical Integrity test was run show that the packer is set at 254-2664'. Congany man	MULTIPLE COMPLETION cted operations. (Clearly state all k). SEE RULE 1103. For Multip 9-11-03 with proper notice to OC4' on plastic lined 2-3/8" tubing in Temporary Abandon until 9-11-	CASING TEST AI CEMENT JOB OTHER: Tev pertinent details, an le Completions: At CD for witness. See 14-1/2" casing — TI ad Status approved D6 FILO 9	nperarily d give pertinent date tach wellbore diagra attached chart record is 3215'. Perforation	ABANDONMENT A band. s, including estimated date m of proposed completion ding test. Well records ons are from 2635' to
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Mechanical Integrity test was runshow that the packer is set at 254 2664'. Congary man	MULTIPLE COMPLETION cted operations. (Clearly state all k). SEE RULE 1103. For Multip 9-11-03 with proper notice to OC4' on plastic lined 2-3/8" tubing in Temporary Abandon until 9-11- a Change was	CASING TEST AI CEMENT JOB OTHER: Tev pertinent details, an le Completions: At CD for witness. See 14-1/2" casing — TI ad Status approved D6 FILO 9	nperarily d give pertinent date tach wellbore diagra attached chart record is 3215'. Perforation	ABANDONMENT A band. s, including estimated date m of proposed completion ding test. Well records ons are from 2635' to
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Mechanical Integrity test was run show that the packer is set at 254-2664'. Congany man	MULTIPLE COMPLETION cted operations. (Clearly state all k). SEE RULE 1103. For Multip 9-11-03 with proper notice to OC4' on plastic lined 2-3/8" tubing in Temporary Abandon until 9-11- a Change was	CASING TEST AI CEMENT JOB OTHER: Tev pertinent details, an le Completions: At CD for witness. See 14-1/2" casing — TI ad Status approved D6 FILO 9	npocaridade de give pertinent date tach wellbore diagra attached chart record is 3215'. Perforation de la company	ABANDONMENT A band. s, including estimated date m of proposed completion ding test. Well records ons are from 2635' to
OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. Mechanical Integrity test was run show that the packer is set at 254 2664'. Congary man	MULTIPLE COMPLETION cted operations. (Clearly state all k). SEE RULE 1103. For Multip 9-11-03 with proper notice to OC4' on plastic lined 2-3/8" tubing in Temporary Abandon until 9-11- bove is true and complete to the b	CASING TEST AI CEMENT JOB OTHER: Tex pertinent details, an le Completions: At D for witness. See 14-1/2" casing – TI ad Status approved D6 FIG. 9.	nporarila d give pertinent date tach wellbore diagra attached chart record is 3215'. Perforation	Aband. s, including estimated date m of proposed completion ding test. Well records ons are from 2635' to
OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. Mechanical Integrity test was run show that the packer is set at 254 2664. Company manual Integrity test was run show that the packer is set at 254 2664.	MULTIPLE COMPLETION cted operations. (Clearly state all k). SEE RULE 1103. For Multip 9-11-03 with proper notice to OC4' on plastic lined 2-3/8" tubing in Temporary Abandon until 9-11- bove is true and complete to the b	CASING TEST AI CEMENT JOB OTHER: Ter pertinent details, an le Completions: At D for witness. See 14-1/2" casing – TI ad Status approved D6 est of my knowledge egulatory Coordin	nporarila d give pertinent date tach wellbore diagra attached chart record is 3215'. Perforation	ABANDONMENT Aband. s, including estimated date m of proposed completion ding test. Well records ons are from 2635' to DATE 9/18/2003
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Mechanical Integrity test was runshow that the packer is set at 254-2664'. Company manual Integrity test was runshow that the packer is set at 254-2664'. I hereby certify that the information at SIGNATURE Many Certify Certify Type or print name Mary Curlis (This space for State use)	MULTIPLE COMPLETION Deted operations. (Clearly state all k). SEE RULE 1103. For Multip 9-11-03 with proper notice to OC 4' on plastic lined 2-3/8" tubing in Temporary Abandon und 9-11- a Change was bove is true and complete to the b TITLE R IS Patton E-mail address E-mail address	CASING TEST AI CEMENT JOB OTHER: Ter pertinent details, an le Completions: At D for witness. See 14-1/2" casing – TI ad Status approved D6 est of my knowledge egulatory Coordin	d give pertinent date tach wellbore diagral attached chart record is 3215'. Perforation is 3215'. Perforation attached chart record is 3215'. The second is	ABANDONMENT Aband. s, including estimated date m of proposed completion ding test. Well records ons are from 2635' to DATE 9/18/2003 none No. (512) 328-8184
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Mechanical Integrity test was runshow that the packer is set at 254-2664'. Company runn I hereby certify that the information at SIGNATURE May Certify Type or print name Mary Curlis	MULTIPLE COMPLETION cted operations. (Clearly state all k). SEE RULE 1103. For Multip 9-11-03 with proper notice to OC4' on plastic lined 2-3/8" tubing in Temporary Abandon until 9-11- bove is true and complete to the b	CASING TEST AI CEMENT JOB OTHER: Ter pertinent details, an le Completions: At D for witness. See 14-1/2" casing – TI ad Status approved D6 est of my knowledge egulatory Coordin	d give pertinent date tach wellbore diagral attached chart record is 3215'. Perforation is 3215'. Perforation attached chart record is 3215'. The second is	ABANDONMENT Aband. s, including estimated date m of proposed completion ding test. Well records ons are from 2635' to DATE 9/18/2003

