Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED OMB NO. 1004-0137 Expires March 31, 2007

5. Lease Serial No.

	N	N	12	2	0	8	0
--	---	---	----	---	---	---	---

SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do notiuse this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No SUBMIT IN TRIPLICATE - Other instructions on reverse side Type of Well AUG 07 2007 8. Well Name and No. x Oil Well Gas Well Other Barclay Federal OCD-ARTESIA 2. Name of Operator Forest Oil Corporation 9 API Well No. 3a. Address 3b Phone No. (include area code) 30-015-33654-00-S1 707 17th Street, Suite 3600 Denver, CO 80202 303-812-1554 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sand Dunes SENW 2000' FNL & 2180 FWL 11. County or Parish, State Sec. 12 T23S R31E NM CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Production (Start/Resume) Water Shut-Off Notice of Intent Acidize Deenen Alter Casing Fracture Treat Reclamation Well Integrity Subsequent Report Casing Repair New Construction Recomplete Other Plug and Abandon Temporarily Abandon Change Plans Tha Repair Final Abandonment Notice Plug Back Convert to Injection Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.) RU PU unhung well head. POH 126-1.2 F.G. rods & 40.1 rods to body break, run paraffin 5-29-07 knifes to 2500'. Run swab cubs to 2500'. ND well head flange POH tbg to body rod break. POH rods & pmp. POH tbg & tally 229 its 5-30-07 2 7/8" tbg out of hole. Send pump to R&R, RBIH 3 jts w/BP 4' sub & S.N. 8jts 2 7/8" tbg. RU Bo Monk that tester. Test that BIH fine no hole, could have been that collar leak. RD 5-31-07 tbg tester. Change tbg tools, to hook rods. RBIH pmp, K-bars, rods, replace 26-K shear tool, replace 1-1" rod & tac 2-7/8" seat nipple, M&S load the w/27 bbls wtr, press to 500# psi hold good. 6-1-07 Rig down PU clean location 2007 IRFALL OF LAND MANAGEMENT CARLSBAD FIELD OFFICE I hereby certify that the foregoing is true and correct Title Name (Printed/Typed) Cundy Bush Sr. Regulatory Tech Signature Date 6-15-07 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Date Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease

which would entitle the applicant to conduct operations thereon