# Form 3160-5 (September 2001)

# **UNITED STATES** TLARTESIA

FORM APPROVED
OMB No. 1004-0135
Expires January 31, 2004

	L	EPARIME	NIOF	THE INTERIOR	معارية فرية	1 22 -	
BUREAU OF LAND MANAGEMENT	В	UREAU OF	LAND	MANAGEMENT			

5. Lease Serial No.

SUNI	DRY	NOTI	CES	ANI	) RE	POF	RTS	ON V	VELLS	
not use	this	form	for p	ropo	sals	to c	drill	or to	re-enter	an
ndoned	well.	Use I	Form	316	0-3 (A	PD)	for.	such	proposa	ls.

·	I MONOLO AND INLIVE	7 O.Y W.L.			NMLC-00	<u> </u>			
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.							6. If Indian, Allottee or Tribe Name		
	IPLICATE - Other instru	ctions on rev	erse sid	9	7. If Unit o	r CA/A	Agreement, Name and/or No.		
<ol> <li>Type of Well</li> <li>Gas Well</li> </ol>	Other		1 5 200	,	8. Weil Na	me an	d No		
2. Name of Operator	• Other	AUG	15 200		Geronimo				
-	744	OCD	-ARTES	SIA	9 API We		Jaciai n.j		
3a. Address		3b. Phone No. (			30-015-3	5060			
PO Box 5270 Hobbs, NM 88	240	505-393-5905			10. Field ar	nd Poo	l, or Exploratory Area		
4. Location of Well (Footage, Sec.,		1505 555 5505	• • •		Bone Spr	ing			
1895' FNL & 1650' FWL Unit	tF Sec 24-T18S-R31E				11. County or Parish, State  Eddy County, NM				
12. CHECK API	PROPRIATE BOX(ES) TO	INDICATE N	ATURE O	F NOTICE, RE					
TYPE OF SUBMISSION		***************************************		F ACTION					
TITE OF BODIMBOION							/		
✓ Notice of Intent	Acidize	Deepen		Production (Start/	Resume)	=	Water Shut-Off		
Notice of Intent	☐ Alter Casing	Fracture Treat		Reclamation			Well Integrity		
Subsequent Report	Casing Repair Change Plans	New Construc	=	Recomplete		$\Delta$	Other extend APD		
Final Abandonment Notice	Plug and Abar	ndon 🔲	Temporarily Abandon						
1 mai Abandonment ivotice	Convert to Injection	Plug Back		Water Disposal					
Mewbourne Oil Company has a for one year. If you have any qu				ioned well on 07/ ROVED FOR 2 NG <u>7/24</u>					
14 1 hereby certify that the foregoing	a is true and correct				-				
Name (PrintedlTyped)	5 .5 do and contoot	1							
Kristi Green	<u> </u>	Tit	<sup>le</sup> Hobbs Re	gulatory					
Signature PMStt	- guer	Da	te 07/09/07						
	V THIS SPACE FO	R FEDERAL O	RSTATE	OFFICE USE					
Approved by (Signature)	/S/ DON PETE			DON PETE	RSON	FOR Title	FIELD MANAGER		
Conditions of approval, if any, are a certify that the applicant holds lega which would entitle the applicant to c	attached. Approval of this notice l or equitable title to those rights onduct operations thereon.	does not warrant in the subject lea	PARES	BAD FIEL	D OF	FIC	Date AUG 1 3 2007		

Title 18 U S C. Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

#### **CONDITIONS OF APPROVAL - DRILLING**

Operator's Name: Mewbourne Oil Company Well Name & No. 3-Geronimo 24 Federal

Location: 1895' FNL, 1650' FWL, Sec. 24, T-18-S, R-31-E, Eddy County, NM

Lease: NMLC - 065680

### I. DRILLING OPERATIONS REQUIREMENTS:

**A.** The Bureau of Land Management (BLM) is to be notified a minimum of 4 hours in advance for a representative to witness:

- 1. Spudding well
- 2. Setting and/or Cementing of all casing strings
- 3. BOPE tests
  - Eddy County call the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, (505) 361-2822
- B. A Hydrogen Sulfide (H2S) Drilling Plan should be activated 500 feet prior to drilling into the <a href="Queen">Queen</a> formation. Measurements in nearby sections indicate 200-2000 ppm in gas streams and 20-2600 ppm in STVs.
- C. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval.
- **D.** If floor controls are required, (3M or Greater) controls will be on the rig floor, unobstructed, readily accessible to the driller and will be operational at all times during drilling and/or completion activities. Rig floor is defined as the area immediately around the rotary table; the area immediately above the substructure on which the draw works are located, this does not include the dog house or stairway area.

### **II. CASING:**

- A. The 13-3/8 inch surface casing shall be set a minimum of 25 feet into the Rustler Anhydrite at approximately 850 feet and cemented to the surface.
  - 1. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with a surface log readout will be used or a cement bond log shall be run to verify the top of the cement.
  - 2. Wait on cement (WOC) time for a primary cement job will be a minimum of 12 hours for a non-water basin, 18 hours for a water basin, 24 hours in the potash area, or 500 pounds compression strength, whichever is greater. (This is to include the lead cement)
  - 3. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compression strength, whichever is greater.
  - 4. If cement falls back, remedial action will be done prior to drilling out that string.

Possible lost circulation in the Grayburg and San Andres formations.

Possible water flows in the Salado Group and the Premier member of the Grayburg formation.

- B. The minimum required fill of cement behind the <u>8-5/8</u> inch intermediate casing is **cement shall** come to surface. If cement does not circulate see A.1 thru 4.
- C. The minimum required fill of cement behind the <u>5-1/2</u> inch production casing is for cement to extend a minimum of 200' inside the intermediate casing. Prior to moving the rig, please provide verification of cement top.
- **D.** If hardband drill pipe is rotated inside casing; returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool joints of the drill pipe will be installed prior to continuing drilling operations.

## **III. PRESSURE CONTROL:**

- **A.** All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- **B.** The appropriate BLM office shall be notified a minimum of 4 hours in advance for a representative to witness the tests.
  - 1. The tests shall be done by an independent service company.
  - 2. The results of the test shall be reported to the appropriate BLM office.
  - 3. All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test chart and a copy of independent service company test will be submitted to the appropriate BLM office.
  - 4. The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug.

#### V. DRILL STEM TEST:

If a drill stem test is performed, the conditions of Onshore Order 2.III.D must be met.

Engineer on call phone: 505-706-2779

WWI 080907