Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No 1004-0137
Expires: March 31, 200

	Expires Mar
5	Lease Senal No

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					5 Lease Senal No NM074937 6 If Indian, Allottee or Tribe Name	
1 Type of Well □ □ Gas Well □ □ ✓ Other					8 Well Name and No. Parke F Fed #1 9. API Well No.	
2. Name of Operator Southwest Royalties, Inc.						
3a Address 6 Desta Drive, Ste 2100, Midla	3b Phone No. (include 432/688-3267	e area code)	30-0 \$ 5-20597 10 Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec.,	OCT 11	2007	Graybrug-Jackson-SR-Q-G-SA 11 County or Parish, State			
Unit O, 660' FSL & 1980' FE	OCD-ARTESIA		Eddy County, NM			
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE, R	EPORT, OF	ROTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent Subsequent Report	Acidize Alter Casing Casing Repair	Deepen Fracture Treat New Construction	Production (State of Reclamation Recomplete	art/Resume)		
Final Abandonment Notice	Change Plans Plug and Abandon Temporarily Abandon					
If the proposal is to deepen dire Attach the Bond under which the following completion of the in-	ectionally or recomplete horizontally the work will be performed or proviously volved operations If the operation real Abandonment Notices shall be f	y, give subsurface location the the Bond No. on file we results in a multiple comp	ns and measured and truinith BLM/BIA. Require letion or recompletion in	e vertical depth d subsequent r a new interva	1, a Form 3160-4 shall be filed once	

Well P&A'd 8/22/07

- * All pits and rat holes will be remediated, filled or leveled.
- * Steel marker over plugged welbore with permanent identification.
- * Location leveled and all junk, equipment and anchors removed.
- * All environmental concerns addressed by OCD guidelines.

After all is completed, a FINAL ABANDONMENT REQUEST will be filed.

APPROVED
OCT 4 2007

JAMES A. AMOS SUPERVISOR-EPS

Accepted for record NMOCD

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)				
Dawn M. Howard	Title Operations Assistant			
Signature Janua Homa	Date	08/29/2007		
THIS SPACE FOR FEDERAL O	R STATE OF	FICE USE		
Approved by	Title	Date		
Conditions of approval, if any, are attached Approval of this notice does not warrant of certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	1			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make the hand department of agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

GENERAL REQUIREMENTS
AND SPECIAL STIPULATIONS
ATTACHED

Southwest Royalties, Incorporated 6 Desta Drive, Suite 2100 Midland, TX 79705

RE: Parke E Federal 1: NM074937 SWSE, Section 10, T17S, R30E Eddy County, New Mexico

Conditions of Approval:

11

- 1. Remove all production equipment, to include, tanks, pump jack, flowlines and power lines and poles.
- 2. Remove debris, both on and off location, any and all contaminants, and all caliche down to clean soils.
- 3. Contour the entire location to blend with the surrounding landscape, keep slopes gentle to prevent erosion. Rip all disturbed areas and seed with seed mixture #2.
- 4. Contact Jim Amos at 505-234-5909 prior to start, prior to equipment a removal and prior to seeding.

There is a Notice of Intent to Abandon the #3 well. Reclamation of the #1 well can take place at the same time as the #3. That will allow for the more efficient use of equipment, and the removal of the access roads. The reclamation requirements for the #3 will be pretty much the same, removal of the power lines on all three wells, flowlines, debris removal, strip caliche, contour to blend with the surrounding and seeding. All work should be completed by 2/1/08. Contact Jim Amos if any questions.

Accepted for record NMOCD