Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OM B No 1004-0137 Expires: March 31, 2007

Do not use th	NATIONAL AND DEDORT	··· ·			
Do not use th	SUNDRY NOTICES AND REPORTS ON WELLS			NMLC029339A	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name OCT 0 9 200	
			osals.		
SUBMIT IN TRIPLICATE- Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and DARTES	
1. Type of Well Gas Well Other				8. Well Name and No.	
2. Name of Operator BURNETT OIL CO., INC.			_	JACKSON A #10 9. API Well No.	
				30-015-04310 S2	
3a. Address 801 CHERRY STREET, SUITE 1500 3b. Phone No. (include area code) UNIT #9 FORT WORTH, TX. 76102-6881 (817)/332-5108			rea code)	10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) IT A, 330' FNL, 660' FEL, SEC 24,T17S,R30E					
			⊢	GRAYBURG JACKSON 11. County or Parish, State	
				Eddy County, N.M.	
·					
	PPROPRIATE BOX(ES) TO INDIC			PORT, OR O	OTHER DATA
TYPE OF SUBMISSION			OF ACTION		
П.,	Acidize Deep	pen	Production (Start	Resume)	Water Shut-Off
Notice of Intent		cture Treat	Reclamation	ٳ	Well Integrity
Subsequent Report	, —	v Construction	Recomplete	[Other
	l ~	g and Abandon	Temporarily Abar	ndon	
Final Abandonment Notice	Convert to Injection Plug	g Back	Water Disposal		
determined that the site is read	ly for final inspection.)		nts, including reclamat		
9/27/2007 Move old 57D 9/28/2007 MIRU Basic (at 2815', NU swivel, drill 0/01/2007 RIH w/96 jts(Dean Electric install pum Vell returned to Jackso		grade pumpi IH w/3-7/8" b irculate btm u EUE T&C tb ation. 30 PM 10/02/	ng unit pad and it & sub,6- 3-1/2 up, POOH stand g. Run new suc	move in la 2" DC's on ding back to ker rods & ping oil v	arger 114 unit. 2-7/8" tbg. Tag up tbg. Lay down collars. pump. 10/02/2007
9/27/2007 Move old 57D 9/28/2007 MIRU Basic is at 2815', NU swivel, drill 0/01/2007 RIH w/96 jts(Dean Electric install pum Well returned to Jackson his form is being faxed for the faxed faxed for the faxed	by for final inspection.) pumping unit off location. Uping, NU BOP & reverse unit. Go CIP to 3145'(hit 2 bridges.) Ci 3059.8') 2-3/8" 4.7# J55 New punit motor. Check unit operation A Grayburg Battery @ 1:3 for information. The original and	grade pumpi IH w/3-7/8" b irculate btm u EUE T&C tb ation. 30 PM 10/02/	ng unit pad and it & sub,6- 3-1/2 up, POOH stand g. Run new suc	move in la 2" DC's on ding back to ker rods & ping oil v	arger 114 unit. 2-7/8" tbg. Tag up tbg. Lay down collars. pump. 10/02/2007
9/27/2007 Move old 57D 9/28/2007 MIRU Basic of the second	by for final inspection.) pumping unit off location. Uping, NU BOP & reverse unit. Go CIP to 3145'(hit 2 bridges.) Ci 3059.8') 2-3/8" 4.7# J55 New punit motor. Check unit operation A Grayburg Battery @ 1:3 for information. The original and	egrade pumpi iIH w/3-7/8" b irculate btm u EUE T&C tb ation. 30 PM 10/02/	ng unit pad and it & sub,6- 3-1/2 up, POOH stand g. Run new suc	move in la 2" DC's on ding back a ker rods & ping oil v	arger 114 unit. 2-7/8" tbg. Tag up tbg. Lay down collars. pump. 10/02/2007 /ell.
9/27/2007 Move old 57D 9/28/2007 MIRU Basic of the second	by for final inspection.) pumping unit off location. Uping, NU BOP & reverse unit. Go CIP to 3145'(hit 2 bridges.) Ci 3059.8') 2-3/8" 4.7# J55 New punit motor. Check unit operation A Grayburg Battery @ 1:3 for information. The original analysis true and correct A. JACOBY	egrade pumpi iIH w/3-7/8" b irculate btm t EUE T&C tb ation. 30 PM 10/02/ and copies are	ng unit pad and it & sub,6- 3-1/2 up, POOH stand g. Run new suc 2007 as a pum being mailed.	move in la 2" DC's on ding back a ker rods & ping oil v	arger 114 unit. 2-7/8" tbg. Tag up tbg. Lay down collars. pump. 10/02/2007 /ell.
9/27/2007 Move old 57D 9/28/2007 MIRU Basic of at 2815', NU swivel, drill 0/01/2007 RIH w/96 jts() Dean Electric install pum Well returned to Jackson his form is being faxed for the form is being faxed for the form is defined for the form is defi	by for final inspection.) pumping unit off location. Uping, NU BOP & reverse unit. Go CIP to 3145'(hit 2 bridges.) Ci 3059.8') 2-3/8" 4.7# J55 New punit motor. Check unit operation A Grayburg Battery @ 1:3 for information. The original analysis true and correct A. JACOBY	grade pumpi iIH w/3-7/8" b irculate btm u EUE T&C tb ation. 30 PM 10/02/ and copies are	ng unit pad and it & sub,6- 3-1/2 up, POOH stand g. Run new suc 2007 as a pum being mailed.	move in land the second	arger 114 unit. 2-7/8" tbg. Tag up tbg. Lay down collars. pump. 10/02/2007 /ell.
9/27/2007 Move old 57D 9/28/2007 MIRU Basic of at 2815', NU swivel, drill old/1/2007 RIH w/96 jts(Dean Electric install pum Well returned to Jackson this form is being faxed for the Name (Printed/Typed) MARK Signature Maule	by for final inspection.) pumping unit off location. Uping, NU BOP & reverse unit. Go CIP to 3145'(hit 2 bridges.) Ci 3059.8') 2-3/8" 4.7# J55 New punit motor. Check unit operation A Grayburg Battery @ 1:3 for information. The original and regoing is true and correct A. JACOBY	grade pumpi iIH w/3-7/8" b irculate btm u EUE T&C tb ation. 30 PM 10/02/ and copies are Title Date	ng unit pad and it & sub,6- 3-1/2 up, POOH stand g. Run new successions a pum being mailed. ENGINEERING ATE OFFICE I	move in land the second	arger 114 unit. 2-7/8" tbg. Tag up tbg. Lay down collars. pump. 10/02/2007 /ell.
9/27/2007 Move old 57D 9/28/2007 MIRU Basic of at 2815', NU swivel, drill old/1/2007 RIH w/96 jts(Dean Electric install pum Well returned to Jackson bis form is being faxed for the form is being faxed for the form ame (Printed/Typed) MARK Signature Mall Approved by Conditions of approval, if any, and	by for final inspection.) pumping unit off location. Uping, NU BOP & reverse unit. Go CIP to 3145'(hit 2 bridges.) Ci 3059.8') 2-3/8" 4.7# J55 New punit motor. Check unit operation A Grayburg Battery @ 1:3 for information. The original and regoing is true and correct A. JACOBY	grade pumpi iIH w/3-7/8" b irculate btm i EUE T&C tb ation. 30 PM 10/02/ and copies are	ng unit pad and it & sub,6- 3-1/2 up, POOH stand g. Run new successions a pum being mailed. ENGINEERING ATE OFFICE I	move in land the second	arger 114 unit. 2-7/8" tbg. Tag up tbg. Lay down collars. pump. 10/02/2007 /ell. ER

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.