DEPARTMENT OF THE BUREAU OF LAND MAN NOTICES AND RE his form for proposals	S INTERIOR AGEMENT PORTS ON WEL to drill or to re-ea	N OC LS nter an	OV 07 2007 FORM APPROVED D-ART EMERINA 1004-0137 Exploses March 31, 2007 5. Lease Serial No. NM-38464 6. If Indian, Allottee or Tribe Name	
	ructions on rever	se side.	7. If Unit or CA/Agreement, Name and/or No.	
Well Gas Well Other Pogo Producing Company			8. Well Name and No. Pure Gold A Federal #7 9. API Well No.	
ind, TX 79702	3b. Phone No <i>(include</i> 432-685-8100	area code)	30-015-35294         10. Field and Pool, or Exploratory Area	
			Sand Dunes Delaware West 11. County or Parish, State Eddy County, NM	
PPROPRIATE BOX(ES) TO			EPORT, OR OTHER DATA	
Acidize Alter Casing Casing Repair Change Plans Convert to Injection	TYP Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Star Reclamation Recomplete	Well Integrity	
	DEPARTMENT OF THE BUREAU OF LAND MAN NOTICES AND RE is form for proposals ell. Use Form 3160-3 ( IPLICATE- Other inst Gas Well Other Producing Company and, TX 79702 T, R. M. or Survey Description) Section 21, T23S, PPROPRIATE BOX(ES) TO Acidize Alter Casing Casing Repair Change Plans	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT NOTICES AND REPORTS ON WEL his form for proposals to drill or to re-e- ell. Use Form 3160-3 (APD) for such pro- IPLICATE- Other instructions on revers Gas Well Other Producing Company 3b. Phone No (include 432-685-8100 T, R. M. or Survey Description) Section 21, T23S, R31E PPROPRIATE BOX(ES) TO INDICATE NATUR Acidize Deepen Alter Casing Fracture Treat Casing Repair New Construction Change Plans Plug and Abandon	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT NOTICES AND REPORTS ON WELLS his form for proposals to drill or to re-enter an ell. Use Form 3160-3 (APD) for such proposals. IPLICATE- Other instructions on reverse side. Gas Well Other Producing Company and, TX 79702 3b. Phone No (include area code) 432-685-8100 T, R. M, or Survey Description) Section 21, T23S, R31E PPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, RI TYPE OF ACTION Acidize Deepen Production (Stat Alter Casing Fracture Treat Reclamation Casing Repair New Construction Recomplete Change Plans Plug and Abandon Temporarily Ab	

following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Intermediate Csg – Drld 11" hole to 4026'. TD reached @ 12:00 hrs 08/12/07. Ran 93 jts 8-5/8" 32# J-55 LT&C csg. Cmt'd w/ 1000 sks 35:65 POZ C @ 12.4 ppg followed by 300 sks Cl C + 1% CaCl2 @ 14.8 ppg. Circ 265 sks to surface. WOC 24 hrs. Make cut-off. Install WH. NU BOP's & test to 2000#. Test csg to 1000# for 30 mins ok.

TD & Production Csg – Drld 7-7/8" hole to 8140'. TD reached @ 10:30 hrs 08/19/07. Logged well w/ Halliburton. Ran 188 jts 5-1/2" 15.5# & 17# J-55 LT&C csg. Cmt'd 1<sup>st</sup> stage w/ 500 sks Cl C @ 14.1 ppg. Cmt flash set during pumping. DO cmt in 5-1/2" csg. Cmt 1<sup>st</sup> stage w/ 814 sks 50/50 POZ + add @ 1.41 ppg. Test csg to 3000# ok. Ran CBL 09/22/07. TOC @ 4775'.

Title	Sr. Eng Tech	
Date	10/23/07	
ERAL OR STATE O	FFICE USE	
ASS_Title	Date	
not warrant or subject lease Office		
e for any person knowingly and any matter within its jurisdiction	d willfully to make to any department or agency of the United n.	
	Date ERAL OR STATE O ASS not warrant or subject lease Office	