Form 3160-5 (April 2004)

1. Type of Well

2. Name of Operator

3a. Address

xx Öıl Well

TYPE OF SUBMISSION

Final Abandonment Notice

Notice of Intent

X Subsequent Report

P.O. Box 10340, Midland, TX 79702

4 Location of Well (Footage, Sec., T., R., M., or Survey Description)

1650' FNL & 1820' FWL, Section 20, T23S, R315

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

		FORM APPRO OM B No 1004- Expires March
The same of	5 Lease Sena	l No

SHINDRY	NOTICES	$\Delta ND$	REPORTS	ON	WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

Other

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE

Gas Well

Pogo Producing Company

Acidize

Alter Casing

Casing Repair

Change Plans

	FORM APPROVED OM B No 1004-0137 Expires March 31, 2007			
	5 Lease Senal No NM-38463			
r an Sals.	6. If Indian, Allottee or Tribe Name			
side.	7. If Unit or CA/Agreement, Name and/or No			
	8 Well Name and No.			
	Pure Gold B Federal #12			
	9. API Well No.			
code)	30-015-35304			
	10. Field and Pool, or Exploratory Area			
0000	Sand Dunes Delaware West			
2008	11. County or Parish, State			
TESIA	Eddy County, NM			
OF NOTICE, RI	EPORT, OR OTHER DATA			
F ACTION				
Production (Sta	rt/Resume) Water Shut-Off			
Reclamation	Well Integrity			
Recomplete	X Other Sqz holes			

Convert to Injection Plug Back 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

3b. Phone No (include area code)

MAR 25 2008

OCD-ARTESIA

TYPE OF ACTION

Production

Water Disposal

Temporarily Abandon

432-685-8100

02/13/07 Perf 4 squeeze holes @ 2035'. Cmt w/ 140 sks C1 C 65:35 Poz + 120 sks C1 C + 1% CaC12. Circ 47 sks to pit. Press up on sqz hole to 700#. Marlin Deaton w/ BLM witnessed sqz.

Deepen

Fracture Treat

New Construction

Plug and Abandon

02/18/07 Perf 2 sqz holes @ 6286 & 2 sqz holes @ 5180. Cmt w/ 360 sks C. Circ 63 sks cmt. Test sqz holes to 550#.

CONFIDENTIAL

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)							
Cathy Wright	Title	Sr. Eng Tec	h				
Signature Ophisallight	Date	03/05/07	ACI	CEPTE	) FOF	RECO	ORD
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by		Title		Date AR	1 3	2007	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office		WESLE	ky	COM NGRAM	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any States any false, fictitious or fraudulent, statements or representations as to any matter	person l	cnowingly and willfully to	nake tδ	7			

(Instructions on page 2)