

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

APR 23 2008  
OCD-ARTESIA

FORM APPROVED  
Budget Bureau No 1004-0135  
Expires March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir  
Use "APPLICATION FOR PERMIT—" for such proposals

*SUBMIT IN TRIPLICATE*

1 Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2 Name of Operator

Mack Energy Corporation

3 Address and Telephone No

P.O. Box 960 Artesia, NM 88211-0960 (575)748-1288

4 Location of Well (Footage, Sec., T, R, M or Survey Description)

2310 FSL & 330 FEL, Sec. 9-T16S-R29E

5 Lease Designation and Serial No

NMLC-068677

6 If Indian, Allottee or Tribe Name

7 If Unit or CA, Agreement Designation

8 Well Name and No

Oilers Federal #2

9 API Well No

30-015-35994

10 Field and Pool, or Exploratory Area

County Line Tank; Abo

11 County or Parish, State

Eddy, NM

12 CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☐ Recompletion  
☒ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other \_\_\_\_\_
- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Notify BLM 2 hours prior to starting plugging and TA operations @ 575-361-2822.


- 1) Set 500' balanced plug from 7840-7340', WOC and tag no lower than 7340'.
- 2) Set 500' balanced plug from 6900-6400', WOC and tag no lower than 6400'.
- 3) Set 140' balanced plug from 4165-4025', WOC and tag no lower than 4025'.
- 4) Set 100' balanced plug from 1682-1582', WOC and tag no lower than 1582'.
- 5) TA well using procedure and COA for abandonment.

Note: Per approved instruction from Jim Amos 4/14/08.

ACCEPTED FOR RECORD

APR 25 2008

Gerry Guye, Deputy Field Inspector  
NMOCD-District II ARTESIA



14 I hereby certify that the foregoing is true and correct

Signed Gary W. Sherrill Title Production Clerk Date 4/14/08

(This space for Federal or State office use)

Approved by \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_  
Conditions of approval, if any