Form 3160-5 (August 2007)

## UNITED STATES **OCI**DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED OMB No 1004-0137 Expires July 31 2010

5 Lease Serial No

6 If Indian, Allottee or Tribe Name

NM070603



SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2				7 If Unit of CA/Agreement, Name and/or No	
1 Type of Well MAY -9 2008			18	25602	
✓ Oil Well Gas W	/ell Other	TIAL -9 ZUI	8 Well Name	s and No Shearn Shilo Federal #1	
Name of Operator C&D MANAGEMENT COMPANY/dba Freedom Ventures OGRID 231382				30-015-31061	
3a Address 4801 Lang NE, Suite 110, Alburquerqu	Je, New Mexico 87109	3b Phone No (include area code) 10 Field and Pool or Exploratory Area  814-688-3297 - 505-417-1511 Emprire Yates 7 Rivers			
4. Location of Wiell (Footgon, Sec. T. P. M. or Super Description		014-000-3237 - 300-417-1311			
4 Location of Well (Footage Sec T R M or Survey Description) 991 FNL 8 1464 FEL [Unit B]			11 County C	Section 14-T17S-R27E	
12 CHEC	K THE APPROPRIATE BO	DX(ES) TO INDICATE NATUR	RE OF NOTICE REPORT	OR OTHER DATA	
TYPE OF SUBMISSION		T	YPE OF ACTION		
▼ Notice of Intent	Acidize	Deepen	Production (Start/Re	esume) Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
	Change Plans	Plug and Abandon	Temporarily Abando	on	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		
determined that the site is ready fo We are proposing to Plug & Alt of 25 sacks Class C cement. T This well is under bond #NMB0	pandon the above well by otal depth of well is 650 for 002455	placing a plug at botton of the set. And then set Abandome  EE ATTACHED  ONDITIONS OF	ent Marker FOR	Accepted for record NMOCD	
14 Thereby certify that the for going is the Thomas Kizer	rue and correct. Name (Prime	Title Preside	ent		
\	1				
Signature		Date 04/08/	2008	APPROVED	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved by				MAY 9 2009	
		Title		MAY 8 2008	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.				WESLEY W. INGRAM	
Title 18 U.S.C. Section 1001 and Title 43	USC Section 1212, make it	a crime for any person knowingly	and willfully to make to any	department or agency of the United States any false.	

fictitious or fraudulent statements Or representations as to any matter within its jurisdiction

## Shearn Shilo Federal #1 C&D Management Company May 8, 2008 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to start.

- 1. Well is to be plugged from TD to surface with Class C neat cement using tubing. Tag TD with tubing and record depth.
- 2. When casing is cut off verify that cement is in all annuli of casing. If not, it will be necessary to one inch cement from a minimum of 60' below surface to surface.
- 3. See standard COA for plug and abandonment that is attached.

WWI 050808

Accepted for record NMOCD

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.

Accepted for record NMOCD