

Submit 3 Copies To Appropriate District

Office

District I

1625 N. French Dr., Hobbs NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

May 27, 2004

WELL API NO.

30-005-61173

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

LG 0565

7. Lease Name or Unit Agreement Name

Grynberg 14 State Com

8. Well Number 1

9. OGRID Number

10. Pool name or Wildcat

Abo

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☒

2. Name of Operator

Jack J. Grynberg, dba Grynberg Petroleum Company

3. Address of Operator

5299 DTC Boulevard, Suite 500
Greenwood Village, CO 80111-3321

4. Well Location

Unit Letter N : 660 feet from the South line and 1,980 feet from the West line
Section 14 Township 5S Range 24E NMPM County Chaves

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3972 GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Ground Tank: Volume _____ bbls: _____ Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

OTHER: ☐

PLUG AND ABANDON ☒

CHANGE PLANS ☐

MULTIPLE COMPL ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING/CEMENT JOB ☐

OTHER: ☐

ALTERING CASING ☐

P AND A ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work).
SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10 3/4 casing @ 886'. 4 1/2 casing @ 4054' w/ 1550 sx. Perfs 3652 to 3919'.

San Andres Top @ 700'. Water Sands 700-750. ~~San Andres~~
Glorietta Top @ 1470 Water Sands 1470-1555 ~~Glorietta~~
Abo Top @ 3605.

Proposed P&A procedure:

1. MI-RU rig
2. Pull and lay down 2 3/8 EUE tubing - 3602'.
3. Set CIBP above perfs at $\pm$ 3600'. Pump 2 sx cement on top -35'
4. Free point 4 1/2 casing and shoot off.
5. Pull 4 1/2 casing. Set cement plug across Glorietta from 1600 to 1400'. (7.875" hole)
6. Set 10 sx surface plug in 10 3/4 casing.
7. Cut off well head, casing and all surface piping below ground level.
8. Remove all equipment and level location.

* Pump 100' CMT, CSC. Stab
Plug. 50' below Cmt. + 50' Above.
Cmt. Inside + Outside. WOC TAG.

* Pump 100' 10 3/4" CSC. Shoe Plug
50' below + 50' Above. WOC TAG.
* m.m. 60' ant Surface Plug.

P/A Markon 4" X 4' Well information

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Ken McKinney

TITLE Production Manager

DATE 05-08-2008

Type or print name Ken McKinney

E-mail address: K.McKinney@Grynberg.com

Telephone No. 303-850-7490

For State Use Only

APPROVED BY Ph.D. Harker

TITLE Compliance Officer

DATE 5/30/08

Conditions of Approval (if any):

DIFFERENT CONDITION

QUICKSILVER

BRIDGEPORT, TEXAS 76426
MOBILE 817/994-9593

PHONE A/C 817/683-2194 or 683-4093
GRUNBERG PLTR

P.O. BOX 366
FAX 817/466-3277

COMPANY GRUNBERG 14 STATE

DATE 6-15-08

PHONE

WELL NO. 1

LEASE

FIELD

ABO

100' cmt.
10 3/4 cse.
shoe ply.
TAC.

10 3/4 casing @ 886' w/ 600 st
circ cement to surface

1000

2000

* 100' cmt cse shoe ply. TAC.

FOC - UNKNOWN

3000

2 3/8 tubing @ 3602'

Pegs 3652 - 3919

4 1/2" @ 4054 w/ 1550 st Poz
TD 4100'

4000

5000

* 100' cmt. cse. shoe ply.
50' below cut + 50' Above cut.
inside + outside. woc TAC.

* 100' cmt 10 3/4" cse. shoe
ply. 50' below + 50' Above. woc TAC

* Min 60' Surface. Ply.

* P/A Marker 4" X 4'

With Well Sign information.

Placed on well above P/A.

AFTER P&A

QUICKSILVER

BRIDGEPORT, TEXAS 76426
MOBILE 817/994-9593

PHONE A/C 817/683-2194 or 683-4093

P.O. BOX 366
FAX 817/466-3277

GRYNBERG PETRO

COMPANY GRYNBERG 14 STATE

DATE 5-15-03

PHONE _____

WELL NO. 1

LEASE _____

FIELD ABO

