

AUG - 1 2008
OCD-ARTESIA

S

Submit 2 Copies To Appropriate District
Office
District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Ave, Artesia, NM 88210
District III
1000 Rio Brazos Rd, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 25, 2007

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.	30-005-61470
5. Indicate Type of Lease STATE ☐ FEE ☒	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name Badger Com	
8. Well Number	3
9. OGRID Number	255333
10. Pool name or Wildcat	Undesignated Pecos Slope Abo

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: ☐ Oil Well ☐ Gas Well ☒ Other - P&A

2. Name of Operator
Lime Rock Resources A, L.P.

3. Address of Operator
Heritage Plaza, 1111 Bagby, Suite 4600, Houston, Texas 77002

4. Well Location
Unit Letter P : 660 feet from the South line and 830 feet from the East line
Section 4 Township 5S Range 25E NMPM Chaves County New Mexico

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3,786' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

☒ Location is ready for OCD inspection after P&A

- X All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
X A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.

- X The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
X All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
X All other environmental concerns have been addressed as per OCD rules.
X Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.

When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.

SIGNATURE C. L. Miller TITLE Vice President - Operations DATE 7/28/08

TYPE OR PRINT NAME: C. Tim Miller E-MAIL: tmiller@limerockresources.com PHONE: (713) 292-9514

For State Use Only

APPROVED BY: Phil Hawkins TITLE Comptroller DATE 8/1/08

Conditions of Approval (if any):

OK to Release