Submit 3 Copies To Appropriate District	State of New Me	xico	Form C-103	
Office District I	Energy, Minerals and Natural Resources		Revised May 08, 2003	
1625 N. French Dr., Hobbs, NM 88240	37		WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30015 5. Indicate Type	
District [[] 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. 3			FEE
District IV	Santa Fe, NM 87	50 ₫ 50	6. State Oil & Ga	
1220 S. St. Francis Dr., Santa Fe, NM 87505		T 2002	2029	
SUNDRY NOTIC	ES AND REPORTS ON WELLS LS TO DRILL OR TO DEED NOR HA	CEIVED		r Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA			c I	
PROPOSALS.)		KSOULOIA CO	Schnei 8. Well Number	der
1. Type of Well:	1010		6. Well Nulliber	
Oil Well Gas Well 🔀 (Other 10168	(994EV)		
2. Name of Operator	110		9. OGRID Numb	per_
3. Address of Operator 26 EAST Compress A Well Leasting	200.		10. Pool name of	r Wildcat
26 EAST Compres	ss Rd Artesia N	IM 88210	Red La	ke
4. Well Location			=======================================	
1 1 1 mm T . 3	2310 feet from the Sout	L line and 1	980 600	make Food line
	2310 feet from the 300F	ine and /	100 leet iro	om the <u>East</u> line
Section 24	Township / 7 5 Ra	nge 27 E	NMPM Edd	y County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
				The state of the s
_	opropriate Box to Indicate N			
NOTICE OF INTENTION TO: SUBS			SEQUENT RE	:PORT OF: ALTERING CASING []
PERI ORMI REMEDIAL WORK	FLOG AND ABANDON	REMEDIAL WOR	`	ALTERING CASING
TEMPORARILY ABANDON 🛚 💆	CHANGE PLANS	COMMENCE DRI	LLING OPNS.	PLUG AND
PULL OR ALTER CASING	MULTIPLE	CASING TEST AN	ın 🗆	ABANDONMENT
TOLE ON METER ONOMO	COMPLETION	CEMENT JOB		
OTHER:		OTHER:		П
13. Describe proposed or comple	ted operations. (Clearly state all p	pertinent details, and	d give pertinent dat	tes, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompletion.				
1.10 0.00 4.	0/00/0	, /		
We propose to Set an ADI PACKER at 1100' which is 102' Above				
the top perforation, Put A Value and Bull Plug on Lubing At				
Surface, Lond Back Side & Pressure to 500# TA Well				
	•		. ,, ,,	~ <i>?</i> 1
		· · · · · · · · · · · · · · · · · · ·		
I hereby certify that the information ab	ove is true and complete to the be	est of my knowledge	and belief.	
SIGNATURE Oack Matt	Lus TITLE 1	DANAging 11	Nember	DATE 10-20-03
	- / / /			(505)
Type or print name Jack	natthews		Telepi	hone No. 748-2854
(This space for State use)		A -(11 D	n ID	
APPPROVED BY	TITLE	sul By	PE	DATE
Conditions of approval, if any:	IIILE			_DATE