Form 3160-5 (November 1994)

Approval Subject To Verification Of The Integrity Of The 8-5/8" Surface Casing Shoe Prior To Doing The Remedial Work & Submitting Copy Of The Cement

Bond Log(s) Run To The BLM-Roswell Field Office

N.M. Oil Cons. DIV-Dist. 2

UNITED STATES W. Grand Avenue DEPARTMENT OF THE INTEGRAL 88210



and willfully to make to any department or agency of the United States any false, fictitious or

FORM APPROVED OMB No 1004-0135 Expires July 31, 1996

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE — Other instructions on reverse side																			
						5. Lease Serial No. NM-32323 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No.													
										1. Type of Well						8. Well Name and No.			
										Oil Well Gas Well Other AUG 18 2008						SNAKEWEED B FEDERAL 1			
										2. Name Of Operator						9. API Well No.			
MCKAY OIL CORPORATION					30-005-64002														
3a. Address			ne No. <i>(include are</i>	2)	10. Field and Pool, or Exploratory Area														
P.O. BOX 2014 ROSWE		23-4735	WEST PECOS ABO SLOPE																
4. Location of Well (Footage, Sec	-				11. County or Parish, State														
1980' FSL, & 2310' FWL, UNIT K, SEC 18, T6S, R23E						CHAVES COUNTY, NM													
12. CHECK API	PROPRIATE BOX(ES)	IO INDI	CATE NATUR	E OF	NOTICE,	REPORT, OR	ЭНТС	ER DATA											
TYPE OF SUBMISSION	TYPE OF ACTION																		
Notice of Intent ■	☐ Acidize	□ De	eepen		Production	on (Start/Resume)		Water Shut-	·Off										
	☐ Alter Casing	☐ Fr	acture Treat		Reclamatio	on		Well Integri	ity										
Subsequent Report	Casing Repair	☐ Ne	ew Construction		Recomplet	e	\boxtimes	Other											
Final Abandonment Notice	Change Plans	☐ Pi	ug and Abandon		Temporari	ly Abandon		Cease Drilling Operations,											
	Convert to Injection	☐ Pl	ug Back		Water Disposal			Surf Casing Abatement											
60BBL gel sweep ar 10sks CemNet and stages 8 and 9 and ceased on 8/12/08. Move packer above Pressure up casing.	epen directionally or recomplet der which the work will be pe etion of the involved operation ten completed. Final Abandon	e horizonta erformed on his. If the or ment Notice ction.) er. Drille in 19jts of ment 30' o top to so it: Test 3 sure up	ally, give subsurface r provide the Bond peration results in a less shall be filed only led to 1005', hit f 8 5/8", J-55, 2 below surface surface. Drilling 330'. Pressure casing. Move	rock fin 9: g com up c RBP	ons and mean file with B ple completical requirement on ledge asing to 8 stages. 3 mmenced asing to a above 25	sured and true vertice LM/BIA. Required on or recompletion ents, including reclamand hung up. 160'. Ran 575s Byds of 5/8" graand another acapprox 800#. Move pacific LM/BIA. Required another acapprox 800#. Move pacific LM/BIA.	cal dept I subsection a ne mation, To staks classes avel w quifer Move ker at	ths of all pertiquent reports so interval, a la, have been co cabilize holeass "C" ce vas placed e struck. 2 RBP above 500'.	e, ran ment, between) Drilling /e 330'.										
depth.						A	CCE	PTED FO	R RECORD										
14. I hereby certify that the foregoi	ing is true and correct	· 						110 40 4	2000										
Name (Printed/Typed) CAROL SHANKS				Title PRODUCTION ANALYST				NUG 182	.008										
Signature (WW) XWA				Date 8/14/2008 Gerry Guye, Deputy Field Inspector NMOCD-District II ARTESI															
	THIS SPACE I	OR FE	DERAL OR ST	ATE	OFFICE	USE													
Approved By /S/ Angel Mayes					Assistar Länds A	it Field:Mana nd Minerals	agen	ate G 1 t	2008										
Approval Subject To Verificati			s not warrant	Office)			/											