

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

SEP 19 2008
OCD-ARTESIA
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

ISEB 082-7655889
NSEB 082-7655701

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Tandem Energy Corporation	Contact	Brandi Barthels
Address	P.O. Box 1559, Midland, TX 79702	Telephone No.	361-935-9377
Facility Name	Ballard Grayburg San Andres unit 001 P	Facility Type	oil

Surface Owner	FEDERAL	Mineral Owner		Lease No.	11-1
---------------	---------	---------------	--	-----------	------

30 015 03310

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	6	18S	29E	2310	North	330	East	Eddy

Latitude 32.776798 Longitude 104.106102

NATURE OF RELEASE

Type of Release	Saltwater	Volume of Release	30 bbls	Volume Recovered	0
Source of Release	Injection Line	Date and Hour of Occurrence	09/01/08 @ 11:30 a.m.	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Yes, NMOCD		
By Whom?	Brandi Barthels	Date and Hour	09/02/08 @ 11:30 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

N/A



Describe Cause of Problem and Remedial Action Taken.*

Injection line broke causing 30 bbls of saltwater to be released. None recovered. The remedial action plan will be developed and executed for the site after soil sampling is conducted.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 400' x 2'. Injection line broke approximately 40' South of the well. The remediation plan will be developed and executed based on the soil analysis results.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Brandi Barthels	Approved by District Supervisor: 	Remediation Actions to be completed and Final C-141 submitted with confirmation analyses/documentation on or before the Expiration Date
Title: Regulatory and Environmental Affairs Manager	Approval Date: 10-2-08	Expiration Date: 12-8-08
E-mail Address: bbarthels@platenergy.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: 09/10/2008 Phone: 361.935.9377	Within 30 days, on or before 11-8-08, completion of a remediation work plan based on delineation should be finalized and submitted for approval to the Division summarizing all actions taken and/or to be taken to mitigate environmental damage	2RP - 238

* Attach Additional Sheets If Necessary

SEB 082 7656006