Form 3160-5 (August 1999)

N.M. DIV-Dist. 2 UNITED STATES 1301 W. Grand Avenue

Oil Cons.

FORM APPROVED OMB No. 1004-0135

•		BUREAU OF LAND MANA	Artesia.	IM 88210	Expires November 30, 2000		
		BUREAU OF LAND MANA			5. Lease Serial No.		
SUNDRY NOTICES AND REPOR Do not use this form for proposals to d abandoned well. Use Form 3160-3 (APD)			RTS ON WELLS drill or to re-enter an		NMLC029387B		
					6. If Indian, Allottee or Tribe Name		
	abandoneu w	en. Ose follli stoos (Aft) ioi sucii proposais	•			
==	SURMIT IN TR	IIPLICATE - Other instru	ictions on reverse	side	7. If Unit or CA/Agreement, Name and/	or No.	
	OODMII IN III		RECEIVED				
ī.	Type of Weil	·			†		
	Oil Well Gas Well &	Other INJ	NOV 1 4 2003		8. Well Name and No.		
2.	Name of Operator		OCD-ARTESIA		SHUGART D #10		
	MOMENTUM OPERATING CO, INC				9. API Well No.		
3a.	. Address		3b. Phone No. (include area code)		30-015-22199		
		Y, TX 76430	(325)762-3331		10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					SHUGART (Y, 7R, Q)		
LOT G SECTION 30 TOWNSHIP 18 S RAN 660 FEET FROM THE NORTH LINE AND 1					11. County or Parish, State		
	EAST LINE.	HE NORTH LINE AND	1030 FEEL FROM	ını	EDDY		
		DDODDIATE DOVICE) TO	NAME NAME	E OF NOTICE DI	EDODE OR OTHER DATE		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION TYPE OF ACTION							
		Acidize	☐ Deepen	Production (Start	Resume)		
X	Notice of Intent	Alter Casing	Fracture Treat	Reclamation	☐ Well Integrity		
	Subsequent Report	Casing Repair	New Construction	Recomplete	Other CONVERT TO	0	
u	2 anzedneni veboti	Change Plans	Plug and Abandon	Temporarily Aba	andon PRODUCER.		
	Final Abandonment Notice	Convert to Injection	☐ Plug Back	Water Disposal			
3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereo							
	If the proposal is to deepen direct	ctionally or recomplete horizontall	ly, give subsurface location	is and measured and tru-	e vertical depths of all pertinent markers and red subsequent reports shall be filed within	d zone:	
	following completion of the invi-	olved operations. If the operation	results in a multiple comp	letion or recompletion i	in a new interval, a Form 3160-4 shall be fil	ed one	
	testing has been completed. Fir determined that the site is ready	nal Abandonment Notices shall be for final inspection.)	e filed only after all require	ements, including recla	mation, have been completed, and the oper	ator ha	
	₹	• •	ODUCER	STATES TO STATE OF STATES			
CONVERT T-A INJECTION WELL TO PRODUCER. 1) PERFORATE QUEEN AND YATES ZONES 2300-3300 FT.							
2) SWAB TEST AND ACIDIZE - FRAC.							
	3) RUN TUBING, RODS, AND PUMP.						
4) INSTALL PUMPING UNIT AND PUT IN PRODUCTION.							
5)TEST WELL INTO TANK BATTERY.							
	,				APPROVED		
1	WORK WILL BEGIN AS	APPINO					
				1	NOV 1 3 2003		
				1	1 100	\	
						1	
			\$	1	LES BABYAK PETROLEUM ENGINEER]	
14.	I hereby certify that the foregoin	g is true and correct	- P				
•	Nama (Printed/Typed)	O	*	L -	2 5 2		

LYNN NEFF TREASURER Date 10/31/03 THIS SPACE FOR FEDERAL OR STATE OFFICE USE 6 Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.