



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

OCT 01 2003

RECEIVED

NOV 17 2003

OCD-ARTESIA

25 September 2003

Pecos River Operating Inc.
400 W. Illinois, Suite 1070
Midland, Texas 79701

Form C-103 Report of Plugging for your Mitchell # 1 D-9-6-26 API 30-005-61443
Cannot be approved until an NMOCDD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Ron Leune
Name

Manager
Title

Yan Babin
Field Rep. II

Submit 3 Copies To Appropriate District
Office
District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised June 10, 2003

WELL API NO.
30-005-61443

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Mitchell

8. Well Number

1

9. OGRID Number

017081

10. Pool name or Wildcat

Pecos Slope Abo

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

Pecos River Operating

3. Address of Operator

400 W. Illinois, Suite 1070, Midland, TX 79701

4. Well Location

Unit Letter D : 660 feet from the North line and 990 feet from the West line

Section 9 Township 6-S Range 26-E NMPM Chaves County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3644' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

8/21/03- POH w/pkr & TIH w/2 3/8" tbg to 4060'.

8/22/03- Spot 30 sxs CI C cmt 4060'-3700'. POOH w/tbg

8/25/03- TIH w/2 3/8" tbg to 4060'. Spot 30 sxs CI C cmt - plug #2. Tag attempt witnessed by OCD.

8/26/03- TIH & tag cmt @ 3765'. TIH w/pkr on 2 3/8" tbg. Perf 4 1/2" csg @ 1622'.

8/27/03- Squeeze perms @ 1622' w/30 sxs CI C. Displace plug to 1500'. WOC. Rls pkr & tag plug @ 1508'. TIH w/tbg. Spot plug #4 @ 900'-700' (30 sxs).

8/28/03- Tag plug @ 765'. Perf 4 1/2" csg @ 100'. Break circ & pmp top plug (60 sxs). Circ cmt to surface. RDMO.

8/29/03- Cut off wellhead install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE William R. Huck TITLE VP - Engr & Operatins DATE 9/18/03

Type or print name William R. Huck E-mail address: billh@pecosproduction.com Telephone No. 432-620-8480

(This space for State use)

APPROVED BY [Signature] TITLE Field Sup DATE 9/20/03

Conditions of approval, if any:

APPROVED NOV 20 2003