Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103		
District I	Energy, Minerals and Natural Resources			Revised June 10, 2003		
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.		
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			30-005-63614	CY	
District III	1220 South St. Francis Dr.			5. Indicate Type		
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505			STATE	FEE 🛛	
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Sama 1 6, 14141 67505			6. State Oil & G	as Lease No.	
87505				NM 118-8		
	CES AND REPORTS ON				or Unit Agreement Name	e
(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLICATION"				MCKAY WINS	ΓΟΝ "C" #1	
PROPOSALS.)	ATION FOR FERMIT (FORM	(C-101) FO	K SUCH			
1. Type of Well: RECEIVED			ECFIVED	8. Well Number		
Oil Well Gas Well Other				#1		
2. Name of Operator		N	IOV 2 4 2003	9. OGRID Num	ber	
MCKAY OIL CORPORATION	OCD-ARTESIA			014424		
3. Address of Operator			<del>D'AN I ESIA</del>	10. Pool name o	r Wildcat	
PO BOX 2014 ROSWELL, NM 88202-2014				WEST PECOS A	ABO SLOPE	
4. Well Location						
Unit Letter_LOT 4:	660feet from the	_North	line and660	feet from the _	Westline	
	- 11 00		2.77	) II (B) (	<b>a</b>	1
Section 3	Township 8S		Range 26E	NMPM	County Chaves	
and the second	11. Elevation (Show who	ether DR,	RKB, RT, GR, etc.,			
12 Charles	<u> </u>	1: 4 - NT	-4	D O41	- Dete	
	ppropriate Box to Inc	ncate in				
NOTICE OF IN				SEQUENT RE		_
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WOR	к 📙	ALTERING CASING [	Ш
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI	LLING OPNS.	PLUG AND [ ABANDONMENT	
PULL OR ALTER CASING ☐ MULTIPLE ☐ CASING TEST A			ND 🖾	ABAINDONNENT		
_	COMPLETION	_	CEMENT JOB	_		
OTHER:			OTHER:		,	
	. 1		<u></u>	1	1 1.	<u> </u>
13. Describe proposed or complete factoring any proposed was						
of starting any proposed wor or recompletion.	K). SEE KULE 1103. FO	or iviuitipi	le Completions: At	iach wellbore diagi	ram of proposed complet	tion
or recompletion.						
10/16/03 3:15 am – Run 25 j	ts 8 5/8" 23# Rd surface	casing @	989.83 set at 990'.	Rig up cementers	& break circulate.	
10/16/03 3:15 am - Run 25 jts 8 5/8" 23# Rd surface casing @ 989.83 set at 990'. Rig up cementers & break circulate.  Pump 500 sacks HC Premium plus cement, circulate 100 sacks to pits. Plug down @ 6:30 am 10/16/03. Wait						
on cement. Take off landing joint, nipple up BOP choke manifold & flow line. Test BOP 1000# 15 minut						
OK.						
8:00 pm - Test pipe rams 1000# - 15 minutes - OK						
10/26/03 4:15 pm – TD 4800	)'					
10/27/02 (.00 am Bis	: 100 is 5 l	/?? T 55 1	5 5#: @ 4 <b>9</b> 21	21 48002		
	asing crew, run 109 jts 5 ½ cementers and break circu				l 150 agaka Promium Dh	
	i @ 11:30 pm 10/27/03.	nate. Tui	np 123 sacks HL Fi	cinium rius. Tota	1 130 Sacks Fielinulli Fil	12
plug down	. (a) 11.50 pm 10/2/105.					
I hereby certify that the information a	bove is true and complete	to the be	st of my knowledge	and belief.		
SIGNATURE Mantito W	nullen fer I	TITLE	Production Analy	stDA	ATE_10/28/03	
Type or print name Nametta White's	/ eton		atta () !1	. 7r-1- 1	Na 605 (00 4707	
Type or print name Nanette Whitting	ion E-mail addr	ress: nan	ette@mckayoil.com	l elephone	No. 505-623-4735	
(This space for State use)						
APPPROVED BY	led for record . Manage	TTI F			DATE 11/24/03	
APPPROVED BY Accepted for record - NIMOCHITLE  Conditions of approval, if any:					_DAID HI-1 103	_
* * /						