Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FEB 18 2009

FORM APPROVED OMB No 1004-0137 Expires March 31, 2007

5 Lease Serial No

NM06407-В

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

2 1611 1 64/4 1 1 1 1 1 1 1 1

6 If Indian, Allottee or Tribe Name

SUBMIT IN TE	7 If Unit or CA/Agreement, Name and/or No			
1 Type of Well				West Henshaw Premier Unit
Oil Well Gas Well	Other			8 Well Name and No
2 Name of Operator				W Henshaw Premier Ut Tr 9 #1J
Nordstrand Engineering In	ic.			9 API Well No
3a Address		3b Phone No (include area code)		30-015-03857
3229 D'Amico St. # 2200		713 520 1555		10 Field and Pool, or Exploratory Area
Houston, TX 77019				
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				West Henshaw Grayburg
3660' FNL & 1650' FEL. S	11 County or Parish, State			
				EDDY COUNTY, NM
12. CHECK AF	PROPRIATE BOX	(ES) TO INDICATE NA	TURE OF NOTICE, REPO	ORT, OR OTHER DATA
TYPE OF SUBMISSION			TYPE OF ACTION	
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Treat	Reclamantion	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	Other
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Abandon	
	Convert to Injection	Plug Back	Water Disposal	
If the proposal is to deepen direc	tionally or recomplete l	nonzontally, give subsurface lo	cations and measured and true	proposed work and approximate duration thereof vertical depths of all pertinent markers and zones subsequent reports shall be filed within 30 days

8 5/8 @ 512 Cemented to surface

5 1/2 @ 2863 Cemented w/ 600 sx cmt

determined that the site is ready for final inspection)

- 1. 01/20/09 Prepare location to move in w/ backhoe. Install anchors. MI rig up rig and equipment.
- 2. 01/21/09 ND well head and NU BOP. work packer free. POH & lay down thg and packer. Close well in.
- 3. 01/22/09 Tally tbg. and RIH w/ CIBP. Set plug @ 2543'. Circulate hole w/ mud laiden fluid (9.5 lb.). Spot 55 sx class C cement on top of CIBP. Stand back 900' tbg. lay down rest. RIH and perf 5 1/2 csg. @ 1175'. RIH w/ packer and set @ 900'. Sqz. 45 sx. class C cement. Close well in for night.

following completion of the involved operations if the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamantion, have been completed, and the operator has

4. 01/23/09 RIH w/ tbg and tag plug @ 1035'. Lay down tbg. Perf. 5 1/2 casing @ 562'. Run packer on 1 jt. Could not pump into perfs. Pressured up to 1400 psi. Pull packer. RIH w/ tbg. open ended to 600'. Circulate class C cement to surface with 60 sx. ND BOP. Cut off well head and install Dry Hole Marker. Rig down Move off.

Accepted for record NMOCD

Approved as to plugging of the well bore. Liability under bond is retained until Surface restoration is completed.

MINOUS		•
14 I hereby certify that the foregoing is true and correct)		
Name (Printed Typed) Mike Huffman	m-411 a	
Mike nullinan Title	Feild Supervisor	
Signature IIII Wall	2-4-09	ADDDOVED.
THIS SPACE FOR FEDERAL O	741160120	
Approved by	Title	Date FFB 1 6 2009
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		·
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person know States any false, fictitious or fraudulent statements or representations as to any matter within its juris	ringly and willfully to make to any depa	rtiment or agency of the United AIVIUS SUPERVISOR-EPS