| | State of New Mex | | MAR 2 0 2009 | Form C-103 |
|--|--|---|---|---|
| <u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 | French Dr., Hobbs, NM 88240 | | WELL API NO. | May 27, 2004 |
| District II 1301 W Grand Ave., Artesia, NM 88210 | | | 30-015-26444 5. Indicate Type of Lease | |
| District III 1000 Rio Brazos Rd, Aztec, NM 87410 | 1220 South St. Francis Dr. Santa Fe, NM 87505 | | STATE STATE F | TEE |
| District IV 1220 S St. Francis Dr., Santa Fe, NM 87505 | | | 6. State Off & Gas Lease I | NO. |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH | | | 7. Lease Name or Unit Agreement Name EASTLAND QUEEN UNIT | |
| PROPOSALS) 1. Type of Well: Oil Well | 1. Type of Well: Oil Well | | | |
| 2. Name of Operator BEACH EXPLORATION, INC. | | | 9. OGRID Number 1903 | |
| 3. Address of Operator 800 NORTH MARIENFELD, SUITE 200, MIDLAND, TX 79701 | | | 10. Pool name or Wildcat TURKEY TRACK; 7RVRS-QU-GB-SA | |
| 4. Well Location | | | | |
| Unit Letter_H; 2,310 feet from theNORTH line and330feet from theEASTline Section 2 Township 19S Range 29E NMPM EDDY County | | | | |
| Section 2 | 11. Elevation (Show whether DR, | | | |
| Pit or Below-grade Tank Application □ or Closure □ | | | | |
| Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water | | | | |
| Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material | | | | |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data | | | | |
| NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: | | | | |
| PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK | | | | NG CASING |
| TEMPORARILY ABANDON PULL OR ALTER CASING | CHANGE PLANS ☐ MULTIPLE COMPL ☐ | COMMENCE DRI CASING/CEMENT | | A LI |
| OTHER: | | OTHER: C | ONVERTED TO INJECTION | ı 🖂 |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date | | | | |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. | | | | |
| | | | | |
| • | | | | |
| Work Completed - EQU # | | | | |
| 08/26/08 Pulled and laid down re | <u>3</u> ods, pump and 2 3/8" tbg. 2770' of tbg. No er to 2775'. Set 5 1/2" CIBP on WL at 1900 | | | |
| 08/26/08 Pulled and laid down r Ran 4 3/4" bit & scrape 08/27/08 Spotted 25sx Class C | - ods, pump and 2 3/8" tbg. 2770' of tbg. No er to 2775'. Set 5 1/2" CIBP on WL at 1900 cmt at 1766'. Hesitation sqz'd 7 Rvrs perfs | '. Tested CIBP to 120 (1626'-1736') but cm | 0 psi t started going away | <u> </u> |
| 08/26/08 Pulled and laid down re Ran 4 3/4" bit & scrape 08/27/08 Spotted 25sx Class C 08/28/08 Tagged sqz cmt at 170 09/03/08 Drld sqz cmt w/4 3/4" bit & scrape 25sx Class C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx Class C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx Class C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx Class C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx Class C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx Class C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx Class C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx Class C 08/28/08 Tagged sqz cmt at 170 09/03/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx Class C 08/28/08 Tagged sqz cmt at 170 09/03/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx Class C 08/28/08 Tagged sqz cmt at 170 09/03/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx Class C 08/28/08 Tagged sqz cmt at 170 09/03/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx Class C 09/03/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx Class C 09/03/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx Class C 09/03/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx C 08/28/08 Tagged sqz cmt w/4 3/4" bit & scrape 25sx C 08/28/08 Tagged sqz cmt w/ | ods, pump and 2 3/8" tbg. 2770' of tbg. No er to 2775'. Set 5 1/2" CIBP on WL at 1900 cmt at 1766'. Hesitation sqz'd 7 Rvrs perfs i2'. Spotted 25sx Class C cmt at 1700'. He bit from 1485' to 1770'. Pressure tested sq | '. Tested CIBP to 120 (1626'-1736') but cm sitation sqz'd 7 Rvrs p z to 505 psi. Drld CIB | 0 psi t started going away erfs (1626'-1736') to 600 psi | |
| 08/26/08 Pulled and laid down re Ran 4 3/4" bit & scrape 08/27/08 Spotted 25sx Class C 08/28/08 Tagged sqz cmt at 170 09/03/08 Drld sqz cmt w/4 3/4" be Pushed CIBP to 2770' | - ods, pump and 2 3/8" tbg. 2770' of tbg. No er to 2775'. Set 5 1/2" CIBP on WL at 1900 cmt at 1766'. Hesitation sqz'd 7 Rvrs perfs ı2'. Spotted 25sx Class C cmt at 1700'. He | '. Tested CIBP to 120 (1626'-1736') but cm sitation sqz'd 7 Rvrs p z to 505 psi. Drld CIB ent) | 0 psi t started going away erfs (1626'-1736') to 600 psi P at 1900'. | |
| 08/26/08 Pulled and laid down re Ran 4 3/4" bit & scrape 08/27/08 Spotted 25sx Class C 08/28/08 Tagged sqz cmt at 170 09/03/08 Drld sqz cmt w/4 3/4" bit Pushed CIBP to 2770' 09/04/08 Set CIBP on WL at 230 Laid down work string. | Jods, pump and 2 3/8" tbg. 2770' of tbg. No or to 2775'. Set 5 1/2" CIBP on WL at 1900 cmt at 1766'. Hesitation sqz'd 7 Rvrs perfs 12'. Spotted 25sx Class C cmt at 1700'. Hesit from 1485' to 1770'. Pressure tested sq (CIBP's at 2350' and 2580' were not prese 30' and dump bailed 15' cmt on top (PBTD SI well. | '. Tested CIBP to 120 (1626'-1736') but cm sitation sqz'd 7 Rvrs p z to 505 psi. Drld CIB ent) | 0 psi t started going away erfs (1626'-1736') to 600 psi P at 1900'. | |
| 08/26/08 Pulled and laid down re Ran 4 3/4" bit & scrape 08/27/08 Spotted 25sx Class C 08/28/08 Tagged sqz cmt at 170 09/03/08 Drld sqz cmt w/4 3/4" bit Pushed CIBP to 2770' 09/04/08 Set CIBP on WL at 230 Laid down work string. 11/18/08 Ran 5 1/2" PC AD-1 To | ods, pump and 2 3/8" tbg. 2770' of tbg. No or to 2775'. Set 5 1/2" CIBP on WL at 1900 cmt at 1766'. Hesitation sqz'd 7 Rvrs perfs 12'. Spotted 25sx Class C cmt at 1700'. Hesit from 1485' to 1770'. Pressure tested sq (CIBP's at 2350' and 2580' were not prese 30' and dump bailed 15' cmt on top (PBTD SI well. S (Odessa) to be lined w/fiberglass. | '. Tested CIBP to 120 (1626'-1736') but cm sitation sqz'd 7 Rvrs p z to 505 psi. Drld CIB ent) 2365'). Pressure test | 10 psi t started going away erfs (1626'-1736') to 600 psi P at 1900'. ed CIBP to 1300 psi ueen perfs (2244'-2294') | |
| 08/26/08 Pulled and laid down re Ran 4 3/4" bit & scrape 08/27/08 Spotted 25sx Class C 08/28/08 Tagged sqz cmt at 170 09/03/08 Drld sqz cmt w/4 3/4" bit Pushed CIBP to 2770' 09/04/08 Set CIBP on WL at 230 Laid down work string. 11/18/08 Ran 5 1/2" PC AD-1 To | Jods, pump and 2 3/8" tbg. 2770' of tbg. No or to 2775'. Set 5 1/2" CIBP on WL at 1900 cmt at 1766'. Hesitation sqz'd 7 Rvrs perfs 12'. Spotted 25sx Class C cmt at 1700'. Hesit from 1485' to 1770'. Pressure tested sq (CIBP's at 2350' and 2580' were not prese 30' and dump bailed 15' cmt on top (PBTD SI well. | '. Tested CIBP to 120 (1626'-1736') but cm sitation sqz'd 7 Rvrs p z to 505 psi. Drld CIB ent) 2365'). Pressure test | 10 psi t started going away erfs (1626'-1736') to 600 psi P at 1900'. ed CIBP to 1300 psi ueen perfs (2244'-2294') | |
| 08/26/08 Pulled and laid down re Ran 4 3/4" bit & scrape 08/27/08 Spotted 25sx Class C 08/28/08 Tagged sqz cmt at 170 09/03/08 Drld sqz cmt w/4 3/4" bit Pushed CIBP to 2770' 09/04/08 Set CIBP on WL at 230 Laid down work string. 11/18/08 Ran 5 1/2" PC AD-1 To | ods, pump and 2 3/8" tbg. 2770' of tbg. No or to 2775'. Set 5 1/2" CIBP on WL at 1900 cmt at 1766'. Hesitation sqz'd 7 Rvrs perfs 12'. Spotted 25sx Class C cmt at 1700'. Hesit from 1485' to 1770'. Pressure tested sq (CIBP's at 2350' and 2580' were not prese 30' and dump bailed 15' cmt on top (PBTD SI well. S (Odessa) to be lined w/fiberglass. | '. Tested CIBP to 120 (1626'-1736') but cm sitation sqz'd 7 Rvrs p z to 505 psi. Drld CIB ent) 2365'). Pressure test | 10 psi t started going away erfs (1626'-1736') to 600 psi P at 1900'. ed CIBP to 1300 psi ueen perfs (2244'-2294') | |
| 08/26/08 Pulled and laid down re Ran 4 3/4" bit & scrape 08/27/08 Spotted 25sx Class C 08/28/08 Tagged sqz cmt at 170 09/03/08 Drld sqz cmt w/4 3/4" bit Pushed CIBP to 2770' 09/04/08 Set CIBP on WL at 23i Laid down work string. 09/18/08 Took 2 3/8" tbg into CI 11/18/08 Ran 5 1/2" PC AD-1 Ti Flushed backside w/38 | ods, pump and 2 3/8" tbg. 2770' of tbg. No or to 2775'. Set 5 1/2" CIBP on WL at 1900 cmt at 1766'. Hesitation sqz'd 7 Rvrs perfs 12'. Spotted 25sx Class C cmt at 1700'. Hesit from 1485' to 1770'. Pressure tested sq (CIBP's at 2350' and 2580' were not prese 30' and dump bailed 15' cmt on top (PBTD SI well. S (Odessa) to be lined w/fiberglass. | '. Tested CIBP to 120 (1626'-1736') but cm sitation sqz'd 7 Rvrs p z to 505 psi. Drld CIB ent) 2365'). Pressure test e tbg Pkr at 2221'. Q 4 bbl of pkr fluid and p | to psi t started going away erfs (1626'-1736') to 600 psi P at 1900'. ed CIBP to 1300 psi ueen perfs (2244'-2294') pressure tested to 500 psi | |
| 08/26/08 Pulled and laid down re Ran 4 3/4" bit & scrape 08/27/08 Spotted 25sx Class C 08/28/08 Tagged sqz cmt at 170 09/03/08 Drld sqz cmt w/4 3/4" bit Pushed CIBP to 2770' 09/04/08 Set CIBP on WL at 23i Laid down work string. 09/18/08 Took 2 3/8" tbg into CI 11/18/08 Ran 5 1/2" PC AD-1 Ti Flushed backside w/38 | ods, pump and 2 3/8" tbg. 2770' of tbg. No or to 2775'. Set 5 1/2" CIBP on WL at 1900 cmt at 1766'. Hesitation sqz'd 7 Rvrs perfs 12'. Spotted 25sx Class C cmt at 1700'. Hesit from 1485' to 1770'. Pressure tested sq (CIBP's at 2350' and 2580' were not prese 30' and dump bailed 15' cmt on top (PBTD SI well. S (Odessa) to be lined w/fiberglass. ension pkr, PC SN, and 70 jts of Glassbores bbl pkr fluid, set pkr, loaded backside w/2 | '. Tested CIBP to 120 (1626'-1736') but cm sitation sqz'd 7 Rvrs p z to 505 psi. Drld CIB ent) 2365'). Pressure test e tbg Pkr at 2221'. Q 4 bbl of pkr fluid and p | to psi t started going away erfs (1626'-1736') to 600 psi P at 1900'. ed CIBP to 1300 psi ueen perfs (2244'-2294') pressure tested to 500 psi | |
| 08/26/08 Pulled and laid down rean 4 3/4" bit & scrape 08/27/08 Spotted 25sx Class C 08/28/08 Tagged sqz cmt at 170 09/03/08 Drld sqz cmt w/4 3/4" bit Pushed CIBP to 2770' 09/04/08 Set CIBP on WL at 23i Laid down work string. 11/18/08 Ran 5 1/2" PC AD-1 To Flushed backside w/38 02/27/09 MIT witnessed by I hereby certify that the information | ods, pump and 2 3/8" tbg. 2770' of tbg. No or to 2775'. Set 5 1/2" CIBP on WL at 1900 cmt at 1766'. Hesitation sqz'd 7 Rvrs perfs 12'. Spotted 25sx Class C cmt at 1700'. Hesit from 1485' to 1770'. Pressure tested sq (CIBP's at 2350' and 2580' were not prese 30' and dump bailed 15' cmt on top (PBTD SI well. S (Odessa) to be lined w/fiberglass. ension pkr, PC SN, and 70 jts of Glassbores bbl pkr fluid, set pkr, loaded backside w/2 | '. Tested CIBP to 120 (1626'-1736') but cm sitation sqz'd 7 Rvrs pz to 505 psi. Drld CIB ent) 2365'). Pressure test etbg Pkr at 2221'. Q4 bbl of pkr fluid and pof the Chart attachest of my knowledg | to psi t started going away erfs (1626'-1736') to 600 psi P at 1900'. ed CIBP to 1300 psi ueen perfs (2244'-2294') pressure tested to 500 psi ed. | hat any pit or below- D-approved plan □. |
| 08/26/08 Pulled and laid down in Ran 4 3/4" bit & scrape 08/27/08 Spotted 25sx Class C 08/28/08 Tagged sqz cmt at 170 09/03/08 Drld sqz cmt w/4 3/4" bit Pushed CIBP to 2770' 09/04/08 Set CIBP on WL at 230 Laid down work string. 11/18/08 Ran 5 1/2" PC AD-1 To Flushed backside w/38 O2/27/09 MIT witnessed by I hereby certify that the information grade tank has been/will be constructed of SIGNATURE | ods, pump and 2 3/8" tbg. 2770' of tbg. No er to 2775'. Set 5 1/2" CIBP on WL at 1900 cmt at 1766'. Hesitation sqz'd 7 Rvrs perfs 12'. Spotted 25sx Class C cmt at 1700'. Hesit from 1485' to 1770'. Pressure tested sq (CIBP's at 2350' and 2580' were not prese 30' and dump bailed 15' cmt on top (PBTD SI well. S (Odessa) to be lined w/fiberglass. ension pkr, PC SN, and 70 jts of Glassbore bbl pkr fluid, set pkr, loaded backside w/2 Richard Inge. Well passed. Copy of above is true and complete to the bear closed according to NMOCD guidelines. | '. Tested CIBP to 120 (1626'-1736') but cm sitation sqz'd 7 Rvrs p z to 505 psi. Drld CIB ent) 2365'). Pressure test e tbg Pkr at 2221'. Q 4 bbl of pkr fluid and p of the Chart attach est of my knowledg], a general permit □ Engineer | t started going away erfs (1626'-1736') to 600 psi P at 1900'. ed CIBP to 1300 psi ueen perfs (2244'-2294') pressure tested to 500 psi ed. e and belief. I further certify tor an (attached) alternative OCE | D-approved plan □. |
| 08/26/08 Pulled and laid down in Ran 4 3/4" bit & scrape 08/27/08 Spotted 25sx Class C 08/28/08 Tagged sqz cmt at 170 09/03/08 Drld sqz cmt w/4 3/4" bit Pushed CIBP to 2770' 09/04/08 Set CIBP on WL at 230 Laid down work string. 11/18/08 Ran 5 1/2" PC AD-1 To Flushed backside w/38 O2/27/09 MIT witnessed by I hereby certify that the information grade tank has been/will be constructed of the structed of the second process of the second | ods, pump and 2 3/8" tbg. 2770' of tbg. No er to 2775'. Set 5 1/2" CIBP on WL at 1900 cmt at 1766'. Hesitation sqz'd 7 Rvrs perfs 12'. Spotted 25sx Class C cmt at 1700'. Hesit from 1485' to 1770'. Pressure tested sq (CIBP's at 2350' and 2580' were not prese 30' and dump bailed 15' cmt on top (PBTD SI well. S (Odessa) to be lined w/fiberglass. ension pkr, PC SN, and 70 jts of Glassbore bbl pkr fluid, set pkr, loaded backside w/2 Richard Inge. Well passed. Copy of a bove is true and complete to the bear closed according to NMOCD guidelines. TITLE E-mail address: bi | '. Tested CIBP to 120 (1626'-1736') but cm sitation sqz'd 7 Rvrs p z to 505 psi. Drld CIB ent) 2365'). Pressure test e tbg Pkr at 2221'. Q 4 bbl of pkr fluid and p of the Chart attach est of my knowledg], a general permit □ Engineer | t started going away erfs (1626'-1736') to 600 psi P at 1900'. ed CIBP to 1300 psi ueen perfs (2244'-2294') pressure tested to 500 psi ed. e and belief. I further certify to an (attached) alternative OCE | D-approved plan □. |
| 08/26/08 Pulled and laid down in Ran 4 3/4" bit & scrape 08/27/08 Spotted 25sx Class C 08/28/08 Tagged sqz cmt at 170 09/03/08 Drld sqz cmt w/4 3/4" bit Pushed CIBP to 2770' 09/04/08 Set CIBP on WL at 23 Laid down work string. 09/18/08 Took 2 3/8" tbg into CL 11/18/08 Ran 5 1/2" PC AD-1 To Flushed backside w/38 02/27/09 MIT witnessed by I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Jack M. Ros | ods, pump and 2 3/8" tbg. 2770' of tbg. No er to 2775'. Set 5 1/2" CIBP on WL at 1900 cmt at 1766'. Hesitation sqz'd 7 Rvrs perfs 12'. Spotted 25sx Class C cmt at 1700'. Hesit from 1485' to 1770'. Pressure tested sq (CIBP's at 2350' and 2580' were not prese 30' and dump bailed 15' cmt on top (PBTD SI well. S (Odessa) to be lined w/fiberglass. ension pkr, PC SN, and 70 jts of Glassbore bbl pkr fluid, set pkr, loaded backside w/2 Richard Inge. Well passed. Copy of above is true and complete to the bear closed according to NMOCD guidelines. | '. Tested CIBP to 120 (1626'-1736') but cm sitation sqz'd 7 Rvrs p z to 505 psi. Drld CIB ent) 2365'). Pressure test e tbg Pkr at 2221'. Q 4 bbl of pkr fluid and p of the Chart attach est of my knowledg], a general permit □ Engineer | t started going away erfs (1626'-1736') to 600 psi P at 1900'. ed CIBP to 1300 psi ueen perfs (2244'-2294') pressure tested to 500 psi ed. e and belief. I further certify to an (attached) alternative OCEDATEMarch 12, 2009 .com Telephone No. (432) | 0-approved plan □. 1 683-6226 |



