DATE ____

SEP 0 3 2003

Submit 3 Copies to Appropriate District Office	State of New Energy, Minerals and Natural	D D days and		Form C-103 Revised 1-1-89
DISTRICT II P.O. Box 1980, Hobbs, NM 88240 DISTRICT II P.O. Drawer DD, Artesia, NM 88210, RECE DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87610	CONSERVAT 2040 Pacheco S Santa Fe, NM RTESIA	ION DIVISION st. 87505	WELL API NO. 30-015-31709 sIndicate Type of Lease «State Oil & Gas Lease	STATE FEE
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1Type of Well:			rLease Name or Unit	Agreement Name
oll WELL XX GAS WELL *Name of Operator *Address of Operator	other ucing Company		«Well No. 2	
P. O. Box	10340, Midland, TX 7	9702-7340	Cedar Canyo	
4Well Location Unit LetterM :660	Feet From The South	Line and990	Feet From The	WestLine
Section 10	Township 24S	Range 29E	NMPM E	ddy county
	••Elevation (Show whether to 2947 '		<u> </u>	
11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON PULL OR ALTER CASING	CHANGE PLANS	COMMENCE DRILLING C		PLUG AND ANBANDONMENT
OTHER:	Γ	OTHER: Plugb		įχ
	ions (Clearly state all pertinent details and			any omposed
## Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 108/05/03 POOH w/ rods, pump & tbg. 108/06/03 Set CIBP @ 7700'. Perf Delaware 6624-31, 6546-53, 6444-51 w/ 1 spf. Test CIBP to 3000#. 108/08/03 Tag CIBP @ 7700'. CIBP @ 7700' leaking. Knock CIBP @ 7700 free & push to 7827. 108/09/03 Set CIBP @ 7680. Test to 3000# ok. Acdz 6444-6631 w/ 1596 gals 7-1/2% acid. 108/12/03 Frac w/ 96,000# 16/30 Ottawa + 48,000# 16/30 SLC. Swab. 108/15/03 Perf Delaware 6266-80 w/ 1 spf. RIH w/ RBP & set @ 6400. Test to 3000# ok. 108/15/03 Acdz 6266-80 w/ 1000 gals 7-1/2% acid. Swab. 108/19/03 Clean sd off RBP @ 6400' & reposition t 6180'. Test to 3000# ok. Perf Delaware 5960-70 w/ 2 spf. 108/20/03 Acdz 5960-70 w/ 1000 gals 7-1/2% acid. 108/22/03 Rel RBP @ 6180 & POOH. 108/24/03 RIH w/ production equipment and return well to production.				
I hereby certify that the information above	e is true and complete to the best of my kno		ion Tosh	00/20/02
SIGNATURE COM	Somber	тпце Sr. Operat		DATE 08/29/03
TYPE OR PRINT NAME Cathy	/ Tomberlin	433	2-685-8100	TELEPHONE NO.

ORIGINAL SIGNED BY TIM W. GUM

__ TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY