## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

MAY 12 2009

OMB

## FOR Expire

	f
M APPROVED	1
NO. 1004-0135	U
es Inly'31 2010	

OCD Artesia	tesia	A	CD	O
-------------	-------	---	----	---

SUNDRY Do not use this abandoned wel	5. Lease Serial No. NMNM102035 6. If Indian, Allottee	NMNM102035  6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIE	7. If Unit or CA/Agre	7. If Unit or CA/Agreement, Name and/or No				
<ol> <li>Type of Well</li> <li>Gas Well</li> <li>Oth</li> </ol>	8. Well Name and No PLU ROSS RANG	8. Well Name and No PLU ROSS RANCH 6 FEDERAL 1H				
<ol> <li>Name of Operator CHESAPEAKE OPERATING,</li> </ol>	9. API Well No. 30-015-36883-0	9. API Well No. 30-015-36883-00-X1				
3a Address OKLAHOMA CITY, OK 73154	1-0496	3b Phone No. (include area code Ph: 405-935-4275	10 Field and Pool, of POKER LAKE WILDCAT			
4 Location of Well (Footage, Sec., T Sec 6 T26S R30E SWSE 350		n)	11 County or Parish, EDDY COUNT			
12. CHECK APPR	ROPRIATE BOX(ES) TO	O INDICATE NATURE OF N	NOTICE, REPORT, OR OTHE	R DATA		
TYPE OF SUBMISSION	TYPE OF ACTION					
<ul><li>☑ Notice of Intent</li><li>☐ Subsequent Report</li><li>☐ Final Abandonment Notice</li></ul>	☐ Alter Casing       ☐ Fracture Treat       ☐ Recommendation         ☐ Casing Repair       ☐ New Construction       ☐ Recommendation         ☐ Change Plans       ☐ Plug and Abandon       ☐ Temporary		☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☐ Temporarily Abandon ☐ Water Disposal	□ Water Shut-Off □ Well Integrity ☑ Other Drilling Operations		
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved	eration (clearly state all pertin ally or recomplete horizontall rk will be performed or provic d operations. If the operation bandonment Notices shall be	ent details, including estimated starti y, give subsurface locations and mea de the Bond No. on file with BLM/Bl results in a multiple completion or re	ng date of any proposed work and app sured and true vertical depths of all per A. Required subsequent reports shall: completion in a new interval, a Form 3 iding reclamation, have been complete	rtinent markers and zones be filed within 30 days 1160-4 shall be filed once		
CHESAPEAKE, RESPECTFU REQUEST BY THE BLM:	ILLY, REQUESTS VERE	BAL APPROVAL FOR THE FO	LLOWING REMEDIAL CEMEN	IT PROCEDURE PE		
CASING: 5 1/2" 20# L-80, 0-1	2,379' ID ? 4.778", Drift	? 4.653", BURST 9,190 PSI	,	-		
PBTD/TD: 12,336'/12,383'						
Perfs: BONE SPRING 8,072-7	12,330'	SEE A	TTACHED FOR			
RECOMMENDED PROCEDU	RE:	CONIT	OITIONS OF APPRO	VAL		
1. MIRU PU. POH W/CAP ST	RING. ND WH/NU BOF	COM	ATTATIO OF PETER			
14. I hereby certify that the foregoing is	s true and correct					

14. Thereby certify	For Ch	IESAPEAKE OPERATIN	IG, INC	BLM Well Information Sy , sent to the Carlsbad MONS on 05/07/2009 (09K		
Name (Printed/T	yped) LINDA GOOD		Title	SR. REGULATORY C	OMPLIANCE SPEC	
Signature	(Electronic Submission)		Date	05/07/2009	)	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved By WE	SLEY INGRAM		TitleF	PETROLEUM ENGINEEI	R	2009 Date 05/07/20
certify that the applic	al, if any, are attached. Approval of this ant holds legal or equitable title to those he applicant to conduct operations there	rights in the subject lease		≎ Carlsbad		
	on 1001 and Title 43 U.S.C. Section 121 titious or fraudulent statements or representations.				te to any department or age	ncy of the United

## Additional data for EC transaction #69813 that would not fit on the form

- 32. Additional remarks, continued
- 2. RELEASE PACKER AND POH W/2 7/8" TBG.
- 3. RU WIRELINE CO. PERFORATE 4 SQUEEZE HOLES AT 6,000', JUST ABOVE TOC. TOC @ 6400' PER SCHLUMBERGER USIT LOG.
- 4. RIH W/PACKER AND RBP ON 2 7/8" TBG. SET RBP AT 6,100'. PULL UP ONE JOINT AND PRESSURE TEST RBP TO 2000 PSI. DROP SAND ON RBP. PULL PACKER UP TO 5,000' AND SET. OPEN CASING VALVE ON 9 5/8" CASING. ESTABLISH INJECTION INTO SQUEEZE PERFS AND OUT 9 5/8" CASING VALVE. POH W/PACKER.
- 5. RIH W/CI CEMENT RETAINER ON TUBING. SET RETAINER AT 5,900'. ESTABLISH INJECTION INTO SQUEEZE PERFS. PUMP CEMENT PER CEMENT RECOMMENDATION TO BRING CEMENT BACK TO 3,000'. STING OUT OF RETAINER, CIRCULATE CLEAN, POH W/TBG. WAIT ON CEMENT 24 HRS.
- 6. RIH W/BIT AND DRILL COLLARS ON 2 7/8" TUBING. DRILL OUT CI CEMENT RETAINER AND CEMENT. PRESSURE TEST SQUEEZE HOLES TO 2,000 PSI. WASH SAND OFF OF RBP. POH W/BIT.
- 7. RIH W/RETRIEVING TOOL ON 2 7/8" TBG. POH W/RBP.
- 8. RIH W/ESP PUMP ON 2 7/8" TBG TO 7,400'.
- 9. RIH W/CAP STRING.
- 10. ND BOP/NU WH. RIH W/CAP STRING INSIDE 2 7/8" TBG TO JUST ABOVE TOP OF PUMP. RIG DOWN.

(CHK PN 624821)

## PLU Ross Ranch 6 Federal 1H 30-015-36883 Chesapeake Operating, Inc. May 7, 2009 Conditions of Approval

Top of cement must be verified by temperature survey or CBL prior to putting the well back on production. Copy of survey or log to be submitted to BLM.

WWI 050709