					į.
Submit 3 Copies To Appropriate District State of New Mexico				Form C-103	
Office <u>District 1</u> Energy, Minerals and Natural Resources				Revised March 25, 1999	
1625 N French Dr., Hobbs, NM 88240 District II				WELL API NO.	
811 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION				30-005-62594 5. Indicate Type	
District III 1220 South St. Francis Dr.			ncis Dr.		X FEE
District IV	Santa Fe	, NM 8	7505	6. State Oil & G	as Lease No.
1220 S. St. Francis Dr , Santa Fe, NM 87505				VA-2071	
Santa Fe, NM 87505 District IV 1220 S. St. Francis Dr, Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUT BASK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM COULT) FOR SUCLE PROPOSALS) 1. Type of Well: Oil Well Gas Well Other X 2. Name of Operator				7. Lease Name or	Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOS	SALS TO DRILL OR TO DEEP	EN OR PI	JUG BACK TO A		
PROPOSALS)	ATION FORTERMIT (FORM)	Segmon	OKSOGETO	Window AWT	State
1. Type of Well:	\(\frac{\sqrt{\gamma}}{2}\)) T	1 1 3 3 1 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
Oil Well Gas Well	Other X	<u> </u>	4/4 2000 6)		
2. Name of Operator	ration $\frac{1}{6}$	OCORE	CEIVED 18	7. Well No.	
Yates Petroleum Corporation 3. Address of Operator 105 S. 4th Street Artesia, NM 88210				#1 8. Pool name or Wildcat	
105 S. 4th Street Artesia, NM 88210				Wildcat Glorieta	
105 5. 4" Sifeer Aries	IG, 141/1 00210	⁶ 2	120	Wildcai Gi	oneid
4. Well Location	······································	1,005	52 42620	<u></u>	<u></u>
Unit Letter <u>E: 1980</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>West</u> line					
Section 10 Township 10S Range 26E NMPM Chaves County 10. Elevation (Show whether DR, RKB, RT, GR, etc.)					
	10. Elevation (Show wi	3839 3839		.)	
11 Check A	ppropriate Box to Ind			Report or Other	Data
NOTICE OF IN		Toute 14		SEQUENT REI	
	T		*		ALTERING
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORI	Κ	CASING
TEMPORARILY ABANDON CHANGE PLANS		COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT X			
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB	√1D	
OTHER:			OTHER:		
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of					
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or					
recompilation. 3/15/02 - MIRU pulling unit.					
3/18/02 – Put 35' cement on top of CIBP at 5900'. Set CIBP at 5510' and cap with 35' cement.					
Perforate 4 squeeze holes at 2400' to squeeze cement behind 4" csg. Set cement retainer at 2350'.					
3/19/02 – Pumped 200 sxs Pec	•			3 bbls.	
3/21/02 – TIH and tagged cer 3/22/02 – Run CBL. TOC 700'.				38" Swah test	
3/27/02 - Received verbal pe					
Artesia OCD. Plugged well as		a.			Tan Banon Will
Set CIBP at 2190', capped wit					
TIH with tbg open ended to 2					casing shoe at 2000'
and the 8-5/8" casing shoe at					
Perforate 4 squeeze holes at a		t down	4" csg and up 5-	-1/2" csg to surta	ice.
Well is plugged and abandor I hereby certify that the information		to to the	hast of my lenguilad	as and halist	
i /	above is true and comple	ic to the	oest of my knowled	ge and benet.	
SIGNATURE Alxin LAL	OC TITLE	<u>Er</u>	ngineering Tech	nician DATE_	April 8, 2002
Type or print name Susan He	reina			Telephone	No. 505-748-1471
(This space for State use)			1:01	Land	MAY 9 2 9009
APPPROVED BY Conditions of approval, if any:		TITLE_		170	DATE CO CULE