

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

JUN - 2 2009
OCD-ARTESIA

FORM APPROVED
OMB No 1004-0137
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
COG Operating

3a. Address
550 W Texas, Ste 1300
Midland, TX 79701

3b. Phone No. (include area code)
(432) 686-3021

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Sec 17 18S 31E
B-1650 East 990 North

5. Lease Serial No
LC 029393C

6 If Indian, Allottee or Tribe Name

7 If Unit of CA/Agreement, Name and/or No

8 Well Name and No.
VS Unit #105

9 API Well No
30-015-05574

10 Field and Pool or Exploratory Area

11. Country or Parish, State
EDDY CO

12 CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☐ Other _____
	☐ Change Plans	☒ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 must be filed once testing has been completed Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection)

1) Set CIBP @ 2,916'. Cap w/ 25sx cmt. Circulate H.M.L.F.

2) Perf @ 1,835'. Sqz 60sx cmt. WOC-Tag.

3) Tbg - 830'. Spot 40sx cmt. WOC-Tag.

4) Perf @ 650'. Sqz 60sx cmt. WOC-Tag.

5) Perf @ 100'. Sqz 30sx cmt to surface.

100' minimum Tag
Perf & Sqz from 830 - 720 Tag
Not Needed
Perf & Sqz both 7" & 8 5/8" circ in/out to Surface

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

* See Attached Reclamation Procedures

14 I hereby certify that the foregoing is true and correct

Name (Printed/Typed)
GARY EGGLESTON

Title P&A SUPERVISOR

Signature

Date 05/20/2009

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Office

APPROVED

MAY 29 2009
Date

JAMES A. AMOS
SUPERVISOR EPS

Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Title 18 U S C Section 1001 and Title 43 U S C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

03/14/2007 17:15 IFAX fax@claytonwilliams.com

→ Howard, Dawn

006/007

04/23/2007 14:41 5053930720

EMRD-OGD

PAGE 06/07

PLUGGING & ABANDONMENT WORKSHEET

(3 STRING CONG)

OPERATOR

LEASENAME

WELL #

SECT

TWN

RNG

FROM

NSL

EWL

TD:

FORMATION @ TD

PBDT:

FORMATION @ PBDT

	SIZE	SET @	TOC	TOC DETERMINED BY
SURFACE				
INTMED 1				
INTMED 2				
PROD				
	SIZE	TOP	BOT	TOC DETERMINED BY
LINER 1				
LINER 2				
	CUT & PULL @		TOP - BOTTOM	
INTMED 1		FEET		
INTMED 2		FEET		
PROD				

• ADDITIONAL PLUGS DISTRICT 1

PLUG	TYPE	SACKS	DEPTH
PLUG 1	OH	25 ETS	9250'
PLUG 2	SHOE	30 ETS	8700-8800'
PLUG 3	CEMENT		500'
PLUG 4	CEP	25 ETS	3900'
PLUG 5	STUB	10 ETS	4400-4700'
PLUG 6	SEPTUM	200 ETS	200'
PLUG 7	SEP	10 ETS	6-10'
PLUG 8			
PLUG 9			
PLUG 10			
PLUG 11			
PLUG 12			
PLUG 13			
PLUG 14			
PLUG 15			
PLUG 16			
PLUG 17			
PLUG 18			
PLUG 19			
PLUG 20			
PLUG 21			
PLUG 22			
PLUG 23			
PLUG 24			
PLUG 25			
PLUG 26			
PLUG 27			
PLUG 28			
PLUG 29			
PLUG 30			
PLUG 31			
PLUG 32			
PLUG 33			
PLUG 34			
PLUG 35			
PLUG 36			
PLUG 37			
PLUG 38			
PLUG 39			
PLUG 40			
PLUG 41			
PLUG 42			
PLUG 43			
PLUG 44			
PLUG 45			
PLUG 46			
PLUG 47			
PLUG 48			
PLUG 49			
PLUG 50			
PLUG 51			
PLUG 52			
PLUG 53			
PLUG 54			
PLUG 55			
PLUG 56			
PLUG 57			
PLUG 58			
PLUG 59			
PLUG 60			
PLUG 61			
PLUG 62			
PLUG 63			
PLUG 64			
PLUG 65			
PLUG 66			
PLUG 67			
PLUG 68			
PLUG 69			
PLUG 70			
PLUG 71			
PLUG 72			
PLUG 73			
PLUG 74			
PLUG 75			
PLUG 76			
PLUG 77			
PLUG 78			
PLUG 79			
PLUG 80			
PLUG 81			
PLUG 82			
PLUG 83			
PLUG 84			
PLUG 85			
PLUG 86			
PLUG 87			
PLUG 88			
PLUG 89			
PLUG 90			
PLUG 91			
PLUG 92			
PLUG 93			
PLUG 94			
PLUG 95			
PLUG 96			
PLUG 97			
PLUG 98			
PLUG 99			
PLUG 100			

PLUG	TYPE	SACKS	DEPTH
PLUG 1	OH	25 ETS	9250'
PLUG 2	SHOE	30 ETS	8700-8800'
PLUG 3	CEMENT		500'
PLUG 4	CEP	25 ETS	3900'
PLUG 5	STUB	10 ETS	4400-4700'
PLUG 6	SEPTUM	200 ETS	200'
PLUG 7	SEP	10 ETS	6-10'
PLUG 8			
PLUG 9			
PLUG 10			
PLUG 11			
PLUG 12			
PLUG 13			
PLUG 14			
PLUG 15			
PLUG 16			
PLUG 17			
PLUG 18			
PLUG 19			
PLUG 20			
PLUG 21			
PLUG 22			
PLUG 23			
PLUG 24			
PLUG 25			
PLUG 26			
PLUG 27			
PLUG 28			
PLUG 29			
PLUG 30			
PLUG 31			
PLUG 32			
PLUG 33			
PLUG 34			
PLUG 35			
PLUG 36			
PLUG 37			
PLUG 38			
PLUG 39			
PLUG 40			
PLUG 41			
PLUG 42			
PLUG 43			
PLUG 44			
PLUG 45			
PLUG 46			
PLUG 47			
PLUG 48			
PLUG 49			
PLUG 50			
PLUG 51			
PLUG 52			
PLUG 53			
PLUG 54			
PLUG 55			
PLUG 56			
PLUG 57			
PLUG 58			
PLUG 59			
PLUG 60			
PLUG 61			
PLUG 62			
PLUG 63			
PLUG 64			
PLUG 65			
PLUG 66			
PLUG 67			
PLUG 68			
PLUG 69			
PLUG 70			
PLUG 71			
PLUG 72			
PLUG 73			
PLUG 74			
PLUG 75			
PLUG 76			
PLUG 77			
PLUG 78			
PLUG 79			
PLUG 80			
PLUG 81			
PLUG 82			
PLUG 83			
PLUG 84			
PLUG 85			
PLUG 86			
PLUG 87			
PLUG 88			
PLUG 89			
PLUG 90			
PLUG 91			
PLUG 92			
PLUG 93			
PLUG 94			
PLUG 95			
PLUG 96			
PLUG 97			
PLUG 98			
PLUG 99			
PLUG 100			

89/8
@ 782
TOC 505XS

711
@ 5016
TOC 1003XS

TD 3183

**BUREAU OF LAND MANAGEMENT
Carlsbad Field Office
620 East Greene Street
Carlsbad, New Mexico 88220
575-234-5972**

**Permanent Abandonment of Federal Wells
Conditions of Approval**

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within ninety (90) days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

2. Notification: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. Blowout Preventers A blowout preventer (BOP), as appropriate, shall be installed prior to commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. Mud Requirement. Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.

5. Cement Requirement Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. Subsequent Plugging Reporting: Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

8. Trash: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos
Supervisory Environmental Protection Specialist
575-234-5909, 575-361-2648 (Cell)

Cody Layton
Natural Resource Specialist
575-234-5959

Terry Gregston
Environmental Protection Specialist
575-234-5958

Trishia Bad Bear
Natural Resource Specialist
575-393-3612

Bobby Ballard
Environmental Protection Specialist
575-234-2230

Todd Suter
Surface Protection Specialist
575-234-5987

Randy Rust
Environmental Protection Specialist
575-234-5943

Doug Hoag
Civil Engineering Technician
575-234-5979

Linda Denniston
Environmental Protection Specialist
575-234-5974

Jennifer Van Curen
Environmental Protection Specialist
575-234-5905

Justin Frye
Environmental Protection Specialist
575-234-5922



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office
620 E. Greene St
Carlsbad, New Mexico 88220-6292
www.blm.gov/nm



In Reply Refer To 1310

Reclamation (Interim/Final) Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its pre-disturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation