



New Mexico Energy, Minerals and Natural Resources Department

Bill Richardson
Governor

Joanna Prukop
Cabinet Secretary

Mark Fesmire
Division Director
Oil Conservation Division



July 10, 2009

Burnett Oil Co., Inc.
Burnett Plaza-Suite 1500
801 Cherry Street-Unit #9
Fort Worth, TX 76102

Mr. Arline,

In response to your letter dated July 07, 2009 the C-104 for the Gissler B #50 (API #30-015-36783) is being held due to an incomplete well file. In reviewing the well file for the above mentioned site it came to my attention that there is no pit permit on file. In order to process the C-104, a C-144 pit permit and closure form must be on file. Once the pit permit and closure are provided, as well as Burnett Oil Co., Inc. meeting compliance criteria, the C-104 will be approved.

The lack of a pit permit is a serious matter. In the future please make sure that all the necessary paperwork is in place before drilling commences.

Your attention in providing the required paperwork is appreciated. Should you have questions, please contact me.

Sincerely,

Jacqui Reeves
NMOCD
District II Geologist

