August 1999)

ıts jurisdiction.

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS


OCD-ARTESIA

FORM APROVED

ANAGEMENT	11 11	20	700 <del>2</del>
DODTS ON WELLS	.11.11	<b>Z S</b>	/UUR

OMB NO. 1004-0135 EXPIRES: NOVEMBER 30, 2000 Lease Serial No.

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals	NMNM 0533177A 6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE				
	7. Unit or CA Agreement Name and No.			
1a. Type of Well 🗸 Oil Well 🗌 Gas Well 📗 Other	8 Well Name and No. Form 3160-5			
2. Name of Operator	Todd 14 Federal 2			
Devon Energy Production Co., LP	9. API Well No.			
3. Address and Telephone No.	30-015-32866			
20 North Broadway, Oklahoma City, OK 73102 405-228-8699 10. Field and Pool, or Exploratory				
4. Location of Well (Report location clearly and in accordance with Federal requirements)*	Ingle Wells; Delaware			
Lot A Sec 14 T23S R31E	12. County or Parish 13. State			
810' FNL & 940' FEL	Eddy NM			
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA  TYPE OS SUBMISSION TYPE OF ACTION				
Acidiza Doopen Droduction (Stat/Decums) DW(star Shut Off				
Notice of Intent  Activize  Activize  Deepen  Production  Reclamate				
☐ Subsequent Report ☐ Casing Repair ☐ New Construction ☐ Recomple	==			
	rily Abandon			
Convert to Injection Plug Back Water Disposal  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal				
the Bond No. on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection)  Devon Energy Production Company, L.P. respectfully requests approval to run a MIT test on the referenced well as follows: MIRU PT and pressure up on casing to 500 psi for 30 mins using chart type pressure recorder. RD PT. CIBP will be set @ 6889' w/ 35' cmt on top. TA'ing this well will bring it into				
compliance with the OCD until further evaluation to convert to a SWD within the next year.				
(See attached wellbore schematic) SEE ATTACHED FOR CONDITIONS OF APPROVAL	APPROVED  JUL 2 7 2009  /s/ JD Whitlock Jr  BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE			
14. Thereby certify that the foregoing is true and correct				
Signed Multy Sorner Title Name Regulatory Analyst	Date <u>7/7/2009</u>			
(This space for Federal or State Office use)				
Approved by Title	Date			
Conditions of approval, if any:				



## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
  - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
  - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
  - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
  - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
  - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3 Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram.
- Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Todd 14 federal #2 Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA/SI for a period of 6 months after successful MIT and subsequent report is submitted. This will be the last and only TA/SI approval. Well must be P&A or producing after 1/27/2010. Submit NOI to convert to SWD.