

Submit 1 Copy To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.	30-015-33739
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Red Lake 28 N State
8. Well Number	1
9. OGRID Number	224400
10. Pool name or Wildcat	Empire

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Edge Petroleum Operating Company, Inc.	
3. Address of Operator 1301 Travis Ste. 2000 Houston, TX 77002	
4. Well Location Unit Letter <u>N</u> : <u>330</u> feet from the <u>South</u> line and <u>2000</u> feet from the <u>West</u> line Section <u>28</u> Township <u>17S</u> Range <u>28E</u> NMPM Eddy County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3848'GL	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

1. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.
- 10-30-09 Tbg & csg left open to flowline, 0 PSI. PU & GIH w/ 2.430 spear, 3 3/4 bumper sub, 3 3/4 jars, 4- 3 1/2 DC's- length of tools 145.81', 12' KB. GIH w/ 186 jts tbg, tag fish @ 6045.34'. Work spear several times, torqued up, POOH w/ tbg & tools, left spear in hole. RIH w/ overshot, latch on to spear, work spear, came loose, POOH w/ tbg & tools, got out of hole w/ both fish. 1-3" x 30' had 2 7/8" collars welded on each end, 4 perf subs on 1 end broke loose, 1 jt of 2 7/8" tbg w/ B.P. on the other welded collar. Slots on 3" cut in all sides (reason pipe collapsed). LD tools, bumper sub, jars & 4- 3 1/2" DC's. SWI SDFN
- 11-02-09 TP-0, CP-50#. GIH w/ 1 mud jt, perf sub, SN, 8 jts tbg, TAC, 181 jts tbg. 12' KB. ND BOP, NU wellhead. Mix 10 gal chemical w/ 45 bbls oil- mix hot. Pump down tbg, drop S/V- load & test to 500#- held. Bleed press off, fished S/V. GIH w/ pump & rods, spaced well out 36", hung well on, has good pump action. Removed check valve flapper on csg flow line, shut flow line valve, well is circ btm up tbg, down csg. SDFN
- 11-03-09 Well was left circ. over night. Shut pump jack down, install flapper in csg check valve, open flow line. Start unit up, press up to 500# in 1 stroke. Well was pumping 100% oil.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Angela Lightner TITLE Angela Lightner DATE 11/4/2009

Type or print name Angela Lightner E-mail address: angela@rkford.com PHONE: 432-682-0440

For State Use Only

APPROVED BY: Jaqueline TITLE Geologist DATE 11/10/2009

Conditions of Approval (if any):