

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised June 10, 2003

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO 30-005-62967
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Yates Petroleum Corporation		6. State Oil & Gas Lease No. V-2925
3. Address of Operator 105 S. 4 <sup>th</sup> Street, Artesia, NM 88210		7. Lease Name or Unit Agreement Name Trailblazer ANL State
4. Well Location  Unit Letter <u>O</u> : 330' feet from the <u>South</u> line and <u>1,650'</u> feet from the <u>East</u> line Section <u>11</u> Township <u>8S</u> Range <u>27E</u> NMPM <u>Chaves</u> County		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 025575
		10. Pool name or Wildcat Southeast Acme San Andres

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Notify the NMOCD 24 hours before starting the work, MIRU a WSU & any safety equipment as needed. Load the casing w/ 30 +/- BBLS of 2% KCL water. NU the BOP on the wellhead.
2. RIH w/ a string of 2 3/8" tubing to 2,131' & circulate the hole w/ 10.0 ppg brine plugging mud w/ 25 lbs of gel/bbl in the mud & pump a 35sacks cement plug across the San Andres perfs. WOC and tag. Pull the tubing up the hole to 508' & pump a 35 sack cement plug across the base of the 8 5/8" casing. Pull the tubing up the hole to 60' & pump a 10 sack cement plug to the surface.
3. Remove all surface equipment & weld dry hole marker per regulations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE: Su Ann Rogers TITLE: Production Clerk DATE: 1/15/04

Type or print name Su Ann Rogers E-mail address: \_\_\_\_\_ Telephone No. 505-748-1471  
(This space for State use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_

Conditions of approval, if any:

**DENIED**

**JAN 19 2004**