

Submit 1 Copy To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.

30-015-33853

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
Bounds 25 Com

8. Well Number

1

9. OGRID Number

147179

10. Pool name or Wildcat

Black River; Morrow, SW (97255)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
Chesapeake Operating, Inc.

3. Address of Operator P.O. Box 18496
Oklahoma City, OK 73154-0496

4. Well Location

Unit Letter D : 990' feet from the North line and 660' feet from the West line
Section 25 Township 24S Range 26E NMPM County Lddy

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3230' GR

RECEIVED
JAN 27 2010
NMOCD ARTESIA

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL. ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Please find our intent to run a MIT on this well in order to temporarily abandon for 5 years or the maximum time allowed. The work procedure is to:

- 1) Notify NMOCD 24 hours in advance prior to performing MIT
- 2) Hold PJSA prior to beginning work each morning and as required for specific operations.
- 3) Load well with packer fluid.
- 4) Pressure up to 500 psi. Record MIT for 30 minutes. If less than 10% pressure change in 30 minutes, MIT is acceptable.
- 5) Bleed pressure off well. ND BOP. NU WH.
- 6) RDMO. Clean location.

Spud Date:

Rig Release Date:

LAST PROD 8/1/08

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Bryan Arrant

TITLE Senior Regulatory Compl. Sp.

DATE 01/26/2010

Type or print name Bryan Arrant

E-mail address: bryan.arrant@chk.com

PHONE: (405)935-3782

For State Use Only

APPROVED BY:

Richard Innes

TITLE

COMPLIANCE OFFICER

DATE

2/2/10

Conditions of Approval (if any):